

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20009626/AGA3Q2

Date: 19/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SJT7342T **Insured Vehicle No :** SDQ1191M

Date of Loss: 04/09/2020 **Nature of Claim:** TP **Claim No:** 1382152131SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT7342T	Engine No:	G4FC9U667123
Make & Model:	HYUNDAI I30 (FD), 1.6 DOHC (A)	Chassis No:	KMHDC51DR9U185330
Reg. Date:	28/10/2009 (Man. Year: 2009)	Odometer:	130314 km
Colour:	Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Roadstone 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,310.80	5,000.24	5,310.56	51.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	2,510.00	1,870.00	42.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,690.80	7,510.24	7,180.56	48.88
Approved Total (Overridden) (\$\$)		6,000.00		
(\$\$)	14,690.80	6,000.00	8,690.80	59.16
+ GST 7.00/7.00% (\$\$)	1,028.36	420.00	608.36	59.16
Nett Amount (\$\$)	15,719.16	6,420.00	9,299.16	59.16
+ Car Rental (5.0 x \$100.00/day) (\$\$)		500.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		6,922.00		
Global Sum Settlement (\$\$)		6,880.00		

INSPECTION

Date of Assignment: 07/09/2020

Date Inspected: 07/09/2020 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT LID	Dented	1,201.60 F	*1,076.00 FL
2	2	*REAR BOOT LID HINGE	Not Necessary	64.20 F	*- FL
3	2	*REAR BOOT LID SHOCK ABSORBER	Not Necessary	165.20 F	*- FL
4	1	*REAR BOOT LID EMBLEM LOGO	Necessary	32.00 F	*32.00 FL
5	1	*REAR BOOT LID HYUNDAI LOGO	Necessary	32.00 F	*32.00 FL
6	1	*REAR BOOT LID 130S LOGO	Necessary	39.40 F	*39.40 FL
7	1	*REAR BOOT LID INNER LOCK	Damaged	145.00 F	*145.00 FL
8	1	*REAR BOOT LID INNER RUBBER	Cut	94.00 F	*94.00 FL
9	1	*REAR BOOT LID INNER TRIM BOARD	Cracked	155.00 F	*155.00 FL
10	1	*REAR BOOT LID WIPER ARM	Not Necessary	115.60 F	*- FL
11	1	*REAR BOOT LID WIPER MOTOR	Not Necessary	190.30 F	*- FL
12	1	*REAR BOOT LID WINDSCREEN	Cut	950.00 F	*950.00 FL
13	2	*REAR BOOT LID WINDSCREEN MOULDING	Necessary	210.00 F	*210.00 FL
14	1	*REAR TAIL LAMP	N/S Cracked / O/S Cut	910.00 F	*468.40 FL
15	4	*REAR TAIL LAMP CLIP	Necessary	32.00 F	*10.00 FL
16	1	*SET REAR TAIL LAMP OUTER CHROME	Necessary	200.00 FS	*100.00 FS
17	1	*REAR TAIL LAMP PANEL	N/S Buckled	272.00 F	*136.00 FL
18	1	*REAR BUMPER	Deformed	462.00 F	*462.00 FL
19	10	*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
20	2	*REAR BUMPER SIDE RETAINER	Necessary	70.00 F	*70.00 FL
21	1	*REAR BUMPER TOWING COVER	Deformed	28.00 F	*28.00 FL
22	1	*REAR BUMPER NUMBER PLATE	Cracked	50.00 F	*50.00 FL
23	1	*REAR BUMPER INNER SPONGE	Cracked	122.00 F	*122.00 FL
24	1	*REAR BUMPER LOWER COVER	Torn	86.50 F	*86.50 FL
25	1	*REAR BUMPER REINFORCEMENT	Cracked	243.80 F	*243.80 FL
26	2	*REAR BUMPER REINFORCEMENT BRACKET	Bent	168.80 F	*168.80 FL
27	5	*REAR BUMPER TOP & LOWER BRACKET	Damaged	179.00 F	*90.00 FL
28	1	*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
29	2	*REAR FENDER INNER TRIM BOARD	Torn	431.60 F	*431.60 FL
30	1	*REAR END PANEL	Dented	449.30 F	*449.30 FL
31	1	*REAR END PANEL TOP GARNISH	Cracked	75.50 F	*75.50 FL
32	1	*REAR SPARE TYRE PANEL	Repair	513.00 F	*- FL
33	1	*REAR SPARE TYRE PANEL TOP COVER	Deformed	220.00 F	*220.00 FL
34	1	*REAR SPARE TYRE PANEL SEALANT	Not Necessary	450.00 F	*- FL
35	1	*REAR WINDSCREEN MOULDING	Repeated	108.00 F	*- FL
36	1	*REAR EXHAUST	Not Necessary	712.00 F	*- FL
37	1	*REAR CENTRE EXHAUST	Not Necessary	688.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,310.80 6,175.30
- List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 1,175.06

Total Parts (\$\$) 10,310.80 5,000.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION	New	280.00	80.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	0.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
5	GUM	New	50.00	50.00
6	TO CHECK WIRING	New	100.00	30.00
7	TUFF KOTE	New	150.00	80.00
8	PANEL BEATING	New	1,600.00	1,100.00
9	SPRAY PAINTING	New	1,600.00	1,000.00
Gross Labour Cost (\$\$)			4,380.00	2,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >