

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20009627/QPA3Q2

**Date:** 25/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800032313-02

**Claimant**  
**Vehicle No :** SHF125Y **Insured Vehicle No :** SCG1199G

Date of Loss: 03/09/2020 Nature of Claim: TP Claim No: 4544125520SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHF125Y</b>		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2F43356
Reg. Date:	26/12/2019 (Man. Year: 2019)	Chassis No:	JTDKB3FU403089407
Colour:	Maroon	Odometer:	65772 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,484.24	991.51	5,492.73	84.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,025.00	450.00	1,575.00	77.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>8,509.24</b>	<b>1,441.51</b>	<b>7,067.73</b>	<b>83.06</b>
<b>+ Loss of Use (2.5 x S\$50.00/day) (\$\$)</b>		125.00		
<b>+ Car Rental (2.5 x S\$119.31/day) (\$\$)</b>		298.28		
<b>+ Doc/Search Fee (\$\$)</b>		7.00		
<b>Nett Liability (\$\$)</b>		<b>1,871.79</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>1,870.00</b>		

### INSPECTION

Date of Assignment: 03/09/2020

Date Inspected: 03/09/2020 Inspected At:

SMRT Automotive Services Pte Ltd  
(Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 2.0 days

**Adjuster:** OI SUN PIN

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*COVER ,RR BUMPER ASSY (DISC 25%)	Crumpled	485.60 F	*364.20 F
2	1	*PAD ,RR BUMPER ,RH & LH ,3 (DISC 25%) (2 PCS)	Necessary	11.00 F	*8.25 F
3	2	*PAD ,RR BUMPER ,RH & LH ,2 (DISC 25%)	Necessary	4.00 F	*3.00 F
4	2	*PAD ,RR BUMPER ,RH & LH ,1 (DISC 25%)	Necessary	4.00 F	*3.00 F
5	1	*PAD ,RR BUMPER ,CTR (DISC 25%) (3 PCS)	Necessary	33.00 F	*24.75 F
6	1	*SEAL ,RR BUMPER ARM ,RH & LH (DISC 25%) (2 PCS)	Necessary	11.30 F	*8.48 F
7	1	*RETAINER ,RR BUMPER RH (DISC 25%)	Broken	132.60 F	*99.45 F
8	1	*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	45.00 F	*33.75 F
9	1	*GUARD ,RR BUMPER ,LOWER (DISC 25%)	Crumpled	374.50 F	*280.88 F
10	1	*COVER ,GUARD RR BUMPER LOWER (DISC 25%)	Missing	22.00 F	*16.50 F
11	1	*REAR BUMPER REINFORCEMENT	Serviceable	332.70 F	*- F
12	1	*EXTENSION SUB-ASSY, RH	Serviceable	120.10 F	*- F
13	1	*EXTENSION SUB-ASSY ,LH	Serviceable	120.10 F	*- F
14	2	*STOPPER ,RR BUMPER ,RH & LH	Serviceable	4.50 F	*- F
15	1	*RETAINER ,RR BUMPER ,LH	Serviceable	132.60 F	*- F
16	1	*SEAL ,RR BUMPER ,RH	Serviceable	118.30 F	*- F
17	1	*SEAL ,RR BUMPER ,LH	Serviceable	118.30 F	*- F
18	1	*REAR BUMPER REFLECTOR ASSY ,REFLEX RH (DISC 25%)	Bracket / Cracked	39.00 F	*29.25 F
19	1	*COVER ,REAR FLOOR UNDER ,RH	Serviceable	175.10 F	*- F
20	1	*COVER ,REAR FLOOR UNDER ,LH	Serviceable	241.90 F	*- F
21	1	*COVER ,REAR FLOOR UNDER CENTER	Serviceable	229.90 F	*- F
22	1	*LENS & BODY REAR COMBINATION LAMP ,RH	Serviceable	339.60 F	*- F
23	1	*COVER ,REAR COMBINATION LAMP RH	Serviceable	69.90 F	*- F
24	1	*LAMP ASSY ,REAR ,RH	Serviceable	293.60 F	*- F
25	1	*END PANEL SUB-ASSY ,BODY LOWER BACK	Serviceable	651.00 F	*- F
26	1	*SEALANT SIKAFLEX	Serviceable	37.00 F	*- F
27	1	*WHEEL DISC	Serviceable	1,879.40 F	*- F
28	1	*TYRE	Serviceable	126.74 F	*- F
29	1	*CAP SUB-ASSY ,WHEEL	Serviceable	211.50 F	*- F
30	2	*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F

F=Franchise part.

**Total Parts (\$\$) 6,484.24 991.51**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING & BODY WORK	New	507.00	200.00
2	SPRAY PAINT	New	918.00	200.00
3	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
5	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	30.00
6	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
8	TO WASH AND VACUUM	New	60.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,025.00</b>	<b>450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >