

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20009628/ATF3E2

Date: 19/03/2021

REFERENCE

Insured/Claimant:	EDY SUSANTO PANGGABEAN	Policy No:	1800062546
Date of Loss:	08/09/2020	Nature of Claim:	OD
		Claim No:	1342674426SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF2517B	Engine No:	CYG023009
Make & Model:	AUDI A6, 1.8 TFSI S-tronic (A)	Chassis No:	WAUZZZ4G6JN034633
Reg. Date:	06/06/2018 (Man. Year: 2017)	Odometer:	30341 km
Colour:	Bronze		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$130,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,151.00	17,873.84	16,277.16	47.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,652.00	3,302.00	2,350.00	41.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,803.00	21,175.84	18,627.16	46.80
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	39,003.00	20,375.84	18,627.16	47.76
+ GST 7.00/7.00% (S\$)	2,730.21	1,426.31	1,303.90	47.76
Nett Amount (S\$)	41,733.21	21,802.15	19,931.06	47.76

INSPECTION

Date of Assignment:	09/09/2020		
Date Inspected:	09/09/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	3,021.00 FS	*2,416.80 FS
2	1		*FRONT BUMPER ATTACHMENT PARTS	Not Necessary	537.00 FS	*- FS
3	1		*FRONT BUMPER TOWING EYE COVER	Deformed	46.00 FS	*- FS
4	2		*FRONT BUMPER SECURING STRIP	Not Necessary	14.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	126.00 FS	*- FS
6	14		*FRONT BUMPER LOCKING CLIP	Not Necessary	52.00 FS	*- FS
7	1		*FRONT BUMPER ADAPTER - RH	Not Necessary	37.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Torn	216.00 FS	*172.80 FS
9	1		*FRONT BUMPER SPOILER	Not Necessary	246.00 FS	*- FS
10	1		*FRONT BUMPER SPOILER	Not Necessary	935.00 FS	*- FS
11	1		*RADIATOR GRILLE	Cracked	1,912.00 FS	*1,529.60 FS
12	1		*RADIATOR GRILLE COVER	Not Necessary	36.00 FS	*- FS
13	2		*RADIATOR GRILLE SENSOR SUPPORT - LH / RH FRONT	Necessary	132.00 FS	*104.32 FS
14	2		*FRONT PARKING AID SENSOR - INNER / OUTER (NPA)	Not Necessary	0.00 FS	*- FS
15	1		*SIGNAL HORN - RH HIGH TONE	Not Necessary	232.00 FS	*- FS
16	1		*SPRING SHACKLE - RH	Not Necessary	47.00 FS	*- FS
17	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Bent	816.00 FS	*652.80 FS
18	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	234.00 FS	*187.20 FS
19	1		*FOAM FILLER PIECE COVER	Not Necessary	121.00 FS	*- FS
20	1		*FRONT BUMPER BRACKET HOLDER - RH	Not Necessary	257.00 FS	*- FS
21	1		*FRONT BUMPER BRACE - RH	Not Necessary	30.00 FS	*- FS
22	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
23	1		*TEMPERATURE SENSOR BRACKET	Not Necessary	23.00 FS	*- FS
24	1		*HEADLIGHT MOUNTING - RH	Cracked	117.00 FS	*93.60 FS
25	1		*LED HEADLIGHT - RH	Cracked	9,337.00 FS	*7,469.60 FS
26	1		*LIFT CYLINDER - RH	Cracked	234.00 FS	*186.80 FS
27	1		*LIFT CYLINDER HOSE	Not Necessary	472.00 FS	*- FS
28	1		*LOCK CARRIER	Not Necessary	1,234.00 FS	*- FS
29	1		*READY MIX COOLANT	Not Necessary	91.00 FS	*- FS
30	1		*RADIATOR AIR GUIDE - RH	Not Necessary	28.00 FS	*- FS
31	1		*RADIATOR AIR GUIDE COVER - UPPER CENTRE	Not Necessary	29.00 FS	*- FS
32	1		*RADIATOR AIR GUIDE SEALING STRIP	Not Necessary	23.00 FS	*- FS
33	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Missing	566.00 FS	*452.40 FS
34	1		*FRONT BUMPER AIR GUIDE GRILLE COVER - RH	Missing	51.00 FS	*40.32 FS
35	1		*FRONT WHEEL SPOILER - RH	Not Necessary	261.00 FS	*- FS
36	1		*HEADLIGHT COVER CAP - RH	Not Necessary	57.00 FS	*- FS
37	1		*DISTANCE REGULATION CONTROL UNIT - RH	Not Necessary	6,609.00 FS	*- FS
38	1		*RADAR SENSOR COVER FRAME - RH	Not Necessary	13.00 FS	*- FS
39	1		*BONNET	Buckled	5,374.00 FS	*4,299.20 FS
40	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
41	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS
42	1		*BONNET STRIKER RHS	Bent	49.00 FS	*39.20 FS
43	1		*BONNET LID LOCK	Bent/Jammed	212.00 FS	*169.20 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 34,151.00 17,873.84

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,800.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,500.00	1,100.00
5	TO CARRY OUT CALIBRATION FOR FRONT SOFTWARE FOR DISTANCE REGULATION AND RADAR SENSOR	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,652.00	3,302.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >