

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFJ 6922B**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DEFORMED	1,953.10	1,380.00
10	REAR BUMPER CLIPS	NECESSARY	50.00	9.60
1	REAR BUMPER SIDE RETAINER - RH	CUT	90.80	90.80
1	REAR SIDE BUMPER - RH	NOT NECESSARY	125.00	-
1	REAR SIDE BUMPER REFLECTOR - RH	NOT NECESSARY	136.00	-
1	REAR BUMPER SPONGE (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER TOWING COVER - RH	NOT NECESSARY	15.00	-
1	REAR BUMPER CENTER GARNISH	NOT NECESSARY	101.00	-
1	REAR END PANEL (NPA)	NOT NECESSARY	-	-
1	REAR END PANEL TOP GARNISH (NPA)	NOT NECESSARY	-	-
1	REAR FENDER LOWER PANEL	TO REPAIR SEE LABOUR	208.00	-
1	REAR FENDER GARNISH - RH	TORN	368.00	149.00
8	REAR FENDER GARNISH CLIP	NECESSARY	40.00	20.00
1	RHR DOOR	TO REPAIR SEE LABOUR	1,207.80	-
1	RHR DOOR RUBBER	NOT NECESSARY	101.70	-
15	RHR DOOR RIVET (NPA)	NOT NECESSARY	-	-
1	RHR DOOR OUTER MOULDING	NOT NECESSARY	75.00	-
1	RHR DOOR TOP CHROME	NOT NECESSARY	95.00	-
1	RHR DOOR SIDE QUARTER GARNISH	TO REPAIR SEE LABOUR	107.00	-
2	REVERSE SENSOR	NOT NECESSARY	30.00	-
2	PARKING SENSOR	NOT NECESSARY	200.00	-
	LESS 25% DISCOUNT		-1,225.85	-412.35
			3,677.55	1,237.05
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	RH REAR RIM (SN)	CUT	1,000.00	800.00
			1,000.00	800.00

Report Ref No. CS/FCI20009632/Gqf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b> TO REPLACE, REFOCUS, RE-WIRE TAILLAMP, BRAKE LIGHTS, BUMPER BEAM & CHECK WIRINGS, RE-SET COMPUTER. TO REMOVE, REFIX PARKING SENSOR AND CAMERA. TO PANEL BEAT, CUT, WELD, REMOVE AND REPLACE THE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER LOWER PANEL, RHR DOOR AND RHR DOOR SIDE QUARTER GARNISH. TO PUTTY AND RE-SPRAY PAINT OF THE AFFECTED AREAS.	NOT NECESSARY	180.00	-
			80.00	40.00
			1,200.00	400.00
			1,800.00	650.00
			3,260.00	1,090.00
<b>GRAND TOTAL</b>			<b>7,937.55</b>	<b>3,127.05</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,500.00</b>

Report Ref No. CS/FCI20009632/Gqf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.