

ASS. REC. BY:

REF:

LPC / 2000 9635 1K933

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____ Complete

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBD 2653H Yr Regn: 08, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Hiace c.c. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 23.2176 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTMH 702 P 8 00145783

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Sumi 195 R15 XJ

R: Petlas

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm.

L/Bal. 6 mm

D.O.A. 5/9/20

Survey held at

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 8/9/2020

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/9 / 11 Pm @ 6:50 7050L Confirmed

Date/Time, File Pass to?

: Prel. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS. SI

Fuel

Others

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL



Not Authorized
U/Snp @ 6150/h
Resurvey After Paint
7 days

Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

ISO TEAM ACCESS PTE LTD
 8 CHANGI NORTH STREET 1
 ISOTEAM BUILDING SINGAPORE 498829

Estimate : ES007027

Attention : THE OWNER
 Contact : 67470220 Fax No. : 67470110

Date : 07/09/2020
 Vehicle Num. : GBD2653H
 Make/Model : TOYOTA HIACE-2014
 Chassis/Eng# : JTFHT02P800145783/1KD2424898
 Accident Date : 05/09/2020
 Claim No. :
 Reference :
 Policy No. :

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS :		
2.	1	TAIL GATE <i>1700</i>		
3.	1	REAR W/SCREEN MOULDING		
4.	1	REAR WIPER BLADE		
5.	1	REAR WIPER ARM		
6.	1	REAR WIPER MOTOR		
7.	1	REAR WINDSCREEN GLASS <i>1115.70</i>		
8.	1	TAIL GATE LOCK		
9.	1	TAIL GATE INNER BOARD		
10.	2	TAIL GATE OUTER GARNISH <i>220</i>		
11.	1	REAR NUMBER PLATE LAMP		
12.	1	TAIL GATE OUTER HANDLE		
13.	1	TOYOTA LOGO		
14.	1	TOYOTA HIACE STICKER		
15.	1	TAIL LAMP R/H		
16.	1	TAIL LAMP LOWER PANEL R/H		
17.	1	REAR FENDER R/H		
18.	1	TAIL LAMP L/H		
19.	1	REAR BUMPER <i>374.45</i>		
20.	6	REAR VIEW MIRROR		
21.	2	REAR BUMPER CLIP		
22.	1	REAR BUMPER BRACKET		
23.	1	REAR END PANEL OUTER		
24.	1	REAR END PANEL TOP PLATE		
25.	1	BOOT WEATHERSTRIP		
26.	1	SPARE TIRE CARRIAGE TOOL COVER		
		SPARE TIRE CARRIAGE <i>172.10</i>		

Phattered
71.50
173.415N
add/CA

BU 2,278.20 ✓
net 138.70 ✓
sn 65.57 X
sn 98.57 X
sn 650.42 X
TM 1,440.00 ✓
TM 286.68 ✓
BU 193.64 ✓
my CMA 386.00 ✓
sn 143.00 X
wap 147.58 ✓
na 68.59 ✓
na 58.31 ✓
CA 311.86 ✓
BU 239.62 ✓
R 1,470.66 X
CA 311.86 ✓
BU 425.30 ✓
mi 362.05 ✓
na 8.00 ✓
CMA 88.36 ✓
BU 176.72 ✓
BU 466.82 ✓
nd 291.65 ✓
solon 346.82 ✓
sn 63.00 X
DIT 280.05 ✓

List TotalS\$: 10,749.67
 25.00% Discount S\$: 2,687.42
 8,062.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

CONTINUE / ...



Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

ISO TEAM ACCESS PTE LTD
 8 CHANGI NORTH STREET 1
 ISOTEAM BUILDING SINGAPORE 498829

Estimate : ES007027

Attention : THE OWNER
 Contact : 67470220 Fax No. : 67470110

Date : 07/09/2020
 Vehicle Num. : GBD2653H
 Make/Model : TOYOTA HIACE-2014
 Chassis/Eng# : JTFHT02P800145783/1KD2424898
 Accident Date : 05/09/2020
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	SPECIAL NETT ITEMS :		
2.	1	REAR W/SCREEN SEALANT	<i>Ma 401n</i>	65.00
3.	1	70 KM/H STICKER	<i>Ma</i>	15.00 ✓
4.	1	REAR NUMBER PLATE	<i>Ma</i>	25.00 ✓
		REVERSE SENSOR	<i>CM 2001n</i>	280.00

Special Nett Total S\$: 385.00

LABOUR :				
	REMOVE & REINSTALL REAR W/SCREEN GLASS		<i>120l</i>	180.00 <i>X NN</i>
	TRANSFER TAILGATE COMPONENT TO NEW GATE		<i>60l</i>	150.00
	RUST PROOFING TREATMENT		<i>60l</i>	100.00
	SPRAY PAINT DAMAGED AREA AFFECTED		<i>750l</i>	1,200.00
	COMPANY LOGO, LETTERING AND TEL NO. STICKER ON TAIL GATE	<i>(Bill)</i>		380.00 <i>180l</i>
	LOGO STICKER / TEL NO ON R/H REAR FENDER		<i>(Bill)</i>	300.00 <i>200l</i>
	TO CUT OFF REAR FENDER R/H, REAR END PANEL OUTER, KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS		<i>900l</i>	1,800.00

Labour Total S\$: 4,110.00

SingDollars : Twelve Thousand Five Hundred Fifty-Seven & Cents Twenty-Five Only

Total S\$: 12,557.25
 =====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

ISO TEAM ACCESS PTE LTD
 8 CHANGI NORTH STREET 1
 ISOTEAM BUILDING SINGAPORE 498829

Attention : THE OWNER
 Contact : 67470220 Fax No. : 67470110

Supplementary Estimate : ES007030

Date : 09/09/2020
 Vehicle Num. : GBD2653H
 Make/Model : TOYOTA HIACE-2014
 Chassis/Eng# : JTFHT02P800145783/1KD2424898
 Accident Date : 05/09/2020
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS :		
2.	1	REAR END CORNER PANEL R/H	<i>B1</i>	452.00 ✓
		REAR EXHAUST SILENCER	<i>R</i>	565.00 X
		List TotalS\$:		1,017.00
		25.00% Discount S\$:		254.25
				762.75
1.	1	SPECIAL NETT ITEMS :		
		REAR FLOOR ALUMINUM PLATE	<i>B1</i>	850.00 ✓
		Special Nett Total S\$:		850.00
		LABOUR :		
		REMOVE & REINSTALL REAR EXHAUST SILENCER BOX	<i>60L</i>	120.00
		Labour Total S\$:		120.00

SingDollars : One Thousand Seven Hundred Thirty-Two & Cents Seventy-Five Only

Total S\$: 1,732.75

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun