

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/LCR18016284/UDA3Q2-1

**Date:** 21/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994772

**Claimant**  
**Vehicle No :** YN1179S **Insured Vehicle No :** SLP6640L

**Date of Loss:** 29/08/2018 **Nature of Claim:** TP **Claim No:** 1506226964SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN1179S		
Make & Model:	ISUZU NHR85AUE4A, 3.0 D (M)	Engine No:	4JJ1827150
Reg. Date:	10/05/2010 (Man. Year: 2009)	Chassis No:	JAANHR85E97100137
Colour:	Dark Blue	Odometer:	234187 km
Engine Capacity:	2999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/75 R16	Rear Tyre Size:	195 R14 (D)
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6/6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6/6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,709.60	1,738.40	1,971.20	53.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,270.00	480.00	27.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,459.60</b>	<b>3,008.40</b>	<b>2,451.20</b>	<b>44.90</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,459.60</b>	<b>2,400.00</b>	<b>3,059.60</b>	<b>56.04</b>
<b>+ Loss of Use (5.0 x S\$120.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,007.45</b>		

### INSPECTION

Date of Assignment: 06/09/2018

Date Inspected: 06/09/2018 Inspected At: Chin Meng Motors (HQ)  
1 Kaki Bukit Ave 6 #01-40/63, Autobay  
@ Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*TAILLAMPS	Cracked	504.00 FL	*504.00 FL
2	2		*TAILLAMP BRACKETS	Not Necessary	372.00 FL	*- FL
3	1		*TAILLAMP WIREMESH	O/S Bent	200.00 FS	*100.00 FS
4	1		*SET REAR REVERSE SENSOR	Cracked	350.00 FS	*200.00 FS
5	1		*REAR REVERSE SENSOR HOLDER BASE	Shorted	200.00 FS	*200.00 FS
6	2		*STOPPERS	Not Necessary	120.00 FS	*- FS
7	1		*REAR NO.PLATE	Not Necessary	35.00 FS	*- FS
8	1		*REAR NO.PLATE BRACKET	Not Necessary	120.00 FS	*- FS
9	1		*REAR BUMPER	Bent	350.00 FS	*350.00 FS
10	2		*REAR BUMPER BRACKETS	Bent	300.00 FS	*300.00 FS
11	1		*REAR BUMPER STICKER -3M REFLECTIVE	Necessary	120.00 FS	*80.00 FS
12	1		*REAR CENTRE STEP BRACKET	Bent	80.00 FS	*80.00 FS
13	1		*REAR LOCK BAR	Repair	280.00 FS	*- FS
14	1		*REAR LOCK BAR BRACKET	Not Necessary	60.00 FS	*- FS
15	1		*REAR END PANEL	Repair	380.00 FS	*- FS
16	1		*REAR COMPARTMENT DOOR STICKER -CERTIS CISCO	Not Necessary	100.00 FS	*- FS
17	1		*REAR COMPARTMENT DOOR STICKER -ANTI-HIJACK	Not Necessary	100.00 FS	*- FS
18	1		*REAR COMPARTMENT DOOR STICKER -AUXILIARY POLICE	Not Necessary	100.00 FS	*- FS
19	1		*REAR R/H COMPARTMENT DOOR STICKER -60KM/H	Not Necessary	10.00 FS	*- FS
20	1		*REAR R/H COMPARTMENT DOOR EMBLEM -TYRON	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,841.00</b>	<b>1,814.00</b>
<b>- List Item Discount on L Items 15.00/15.00% (\$\$)</b>	131.40	75.60
<b>Total Parts (\$\$)</b>	<b>3,709.60</b>	<b>1,738.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO PANEL BEATING ,WELDING ,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE PARTS AS MENTIONED ABOVE ETC	New	800.00	600.00
2	TO RESPRAY AFFECTED PART	New	800.00	600.00
3	TO APPLY UNDERSEAL	New	60.00	0.00
4	TO REMOVE & REFIT REAR REVERSE SENSOR	New	60.00	50.00
5	TO REMOVE & REFIT OF WIRINGS	New	30.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>1,750.00</b>	<b>1,270.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**