

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20009640/KGS3Q2

**Date:** 26/02/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SFP4134R	<b>Insured Vehicle No :</b>	SHA7213G
Date of Loss: 08/09/2020	Nature of Claim: TP	Claim No: MCT20090105

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SFP4134R</b>		
Make & Model:	TOYOTA VOXY, 2.0 ZS CVT (A)	Engine No:	3ZRB611355
Reg. Date:	01/04/2016 (Man. Year: 2015)	Chassis No:	ZRR800131865
Colour:	Metallic Black	Odometer:	82182 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,519.40	4,302.25	2,217.15	34.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	1,560.00	450.00	22.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,529.40</b>	<b>5,862.25</b>	<b>2,667.15</b>	<b>31.27</b>
<b>+ GST 7.00/7.00% (S\$)</b>	597.06	410.36	186.70	31.27
<b>Nett Amount (S\$)</b>	<b>9,126.46</b>	<b>6,272.61</b>	<b>2,853.85</b>	<b>31.27</b>
<b>+ Loss of Use (5.0 x S\$80.00/day) (S\$)</b>		400.00		
	<b>Nett Liability (S\$)</b>	<b>6,672.61</b>		

### INSPECTION

Date of Assignment:	09/09/2020	
Date Inspected:	09/09/2020 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	5.0 days	

**Adjuster:** KENNETH KONG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2020)
<b>Parts:</b>	M1-MPV	TOYOTA VOXY 2.0 ZS CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFP4134R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Mtg Cracked	541.20 F	*541.20 FL
2	1		*REAR BUMPER RH SIDE RETAINER	Serviceable	160.70 F	*- FL
3	5		*REAR BUMPER CLIP	Necessary	22.50 F	*22.50 FL
4	1		*REAR TAILGATE	Bent	1,812.70 F	*1,812.70 FL
5	1		*TAILGATE INNER LOCK	Dented	467.00 F	*467.00 FL
6	1		*TAILGATE INNER RUBBER	Cut	372.30 F	*372.30 FL
7	1		*SET TAILGATE WINDSCREEN GLASS MOULDING	Necessary	70.20 F	*70.20 FL
8	1		*TAILGATE INNER TRIM BOARD	Mtg Cracked	570.30 F	*570.30 FL
9	1		*TAILGATE INNER HANDLE	Dented	46.90 F	*46.90 FL
10	1		*REAR END PANEL	Repair	735.70 F	*- FL
11	1		*REAR END PANEL INNER TOP GARNISH	Dented	152.90 F	*152.90 FL
12	1		*REAR END PANEL ANTENNA	Cracked	136.70 F	*136.70 FL
13	1		*REAR LUGGAGE COMPARTMENT INNER TOP BOARD	Cracked	1,050.30 F	*1,050.30 FL
14	1		*SET REVERSE SENSOR	Necessary	200.00 FS	*200.00 FS
15	1		*REAR BUMPER STEP GARNISH	Necessary	100.00 FS	*100.00 FS
16	1		*REAR END PANEL SEALANT	Necessary	40.00 FS	*30.00 FS
17	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,519.40</b>	<b>5,613.00</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	0.00	1,310.75
<b>Total Parts (\$\$)</b>	<b>6,519.40</b>	<b>4,302.25</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ,TAILLAMPS ,TAILGATE ,SPOILER & ATTACHMENTS ,TO CUT ,WELD & RENEW REAR END PANEL ,KNOCKING & REPAIR REAR LUGGAGE PANEL,FENDERS & REALIGN THE SAME	New	900.00	550.00
3	PUTTY & RESPRAY REAR BUMPER ,TAILGATE,REAR END PANEL ,REAR LUGGAGE PANEL,FENDERS & ALL AFFECTED AREAS	New	800.00	720.00
4	REMOVE & REFIX REVERSE CAMERA ,RESET & REPOSITION	New	50.00	50.00
5	REMOVE & REFIX REAR GARNISH ,CARPET TO FACILITATE REPAIR	New	80.00	60.00
6	RUSTPROOFING	New	60.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,010.00</b>	<b>1,560.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >