



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 392S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	COVER, FR BUMPER (DISC 25%)	CRUMPLED	521.00	390.75
1	SUPPORT, FR BUMPER LH (DISC 25%)	BROKEN	82.30	61.73
1	COVER, FR BUMPER LH (DISC 25%)	DEFORMED	30.20	22.65
10	CLIPS PIECE, FRT & RR BUMPER @\$4.50 (DISC 25%)	NECESSARY	45.00	33.75
1	SUPPORT, FR BUMPER RH	SERVICEABLE	80.10	-
1	COVER, FR BUMPER RH	SERVICEABLE	30.20	-
1	GRILLE, RADIATOR	SERVICEABLE	178.60	-
1	GRILLE SUB-ASSY	SERVICEABLE	422.50	-
1	GRILLE, SUB-ASSY, 2	SERVICEABLE	160.50	-
1	COVER ASSY, ENGINE	SERVICEABLE	241.90	-
2	RETAINER, FR BUMPER, LH & RH	SERVICEABLE	8.80	-
1	PAD, FRONT BUMPER (NO.1)	SERVICEABLE	40.70	-
1	PAD, FRONT BUMPER (NO.2)	SERVICEABLE	36.00	-
1	MOULDING, FRONT BUMPER SIDE, LH	SERVICEABLE	95.60	-
1	ABSORBER, FR BUMPER LOWER	SERVICEABLE	132.70	-
1	ABSORBER, FR BUMPER	SERVICEABLE	80.20	-
1	EXTENSION SUB-ASSY, RH	SERVICEABLE	120.10	-
1	EXTENSION SUB-ASSY, LH	SERVICEABLE	120.10	-
1	REINFORCEMENT FRONT LOWER	SERVICEABLE	246.10	-
1	REINFORCEMENT FRONT UPPER	SERVICEABLE	716.60	-
1	UNIT, HEADAMP, LH	SERVICEABLE	2,637.60	-
1	LAMP ASSY, FOG, LH	SERVICEABLE	237.10	-
1	SET COVER ASSY, ENGINE UNDER CENTER	SERVICEABLE	472.40	-
1	COVER, ENGINE UNDER CENTER	SERVICEABLE	98.00	-
1	UNIT, HEADLAMP, LH (DISC 10%)	CRACKED	2,637.60	2,373.84
			9,471.90	2,882.72
<b><u>LABOUR</u></b>				
	PANEL BEATING & BODY WORK.		338.00	200.00
	SPRAY PAINT.		558.00	200.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-

Report Ref No. NS/INC20009650/Qqf3e2



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	20.00
	TO WASH AND VACUUM.		60.00	-
			1,136.00	420.00
GRAND TOTAL			10,607.90	3,302.72
RECOMMENDED COST OF REPAIRS (CONFIRMED)				3,302.72

Report Ref No. NS/INC20009650/Qqf3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.