

(09/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CC4/Fc120009655/Ves3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMN 4073K

at Workshop m/s

Focus

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

\$80k

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 34808

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMN 4073K

Yr Regn:

*8 119*Type: *M. Car* / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA1

Make:

Toyota sienta Hybrid 1496

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

80839

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

*NHP170 7121443*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: Nil / *S/Rim* / STD A/Rim or

Tyre Size:

F:

195/55 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

C.S.T tires

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

mm

D.O.A.

4/9/20

D.O.I.

9/9/20

Survey held at

Des. of Damages: *Frt* / Rear / O/S / N/S / U/C / Rooftop or*Rt + O/S*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/9/20 4/5 \$5200 confirmed with MR Wong

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

), S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

*dkh: Ashur**not Authorized
dkh**9/9/20**1/5 \$5200
6 days***M/S : First Capital Insurance Ltd****Estimate No : M001700****Date: : 12/09/2020****Veh Reg No SMN4073K****Make/Model : TOYOTA SIENTA****Chassis No : NHP1707121443****Engine No: 1NZ8508039****Reg. Date : 06/08/2019****PAGE:1/2****ATTN : Motor Claim Department****Your Ref No: : SMN4073K****Claim Type : THIRD PARTY****Accident Date : 04/09/2020****Estimate Repair Cost to Vehicle No : SMN4073K**

S/N	Description	Quantity	Unit	Price	Amount
	<u>LIST PRICE</u>			<u>\$\$</u>	<u>\$\$</u>
1	Front Bonnet <i>benf/suc 245.10</i>	1	PCS	856.90	856.90 ✓
2	Front Bonnet Lock <i>suc</i>	1	PCS	96.90	96.90 X
3	Front Bonnet Insulator <i>11</i>	1	PCS	279.60	279.60 X
4	Front Bonnet Insulator Clipse <i>11</i>	5	PCS	12.90	64.50 X
5	Front Bonnet Hinges <i>11</i>	2	PCS	101.90	203.80 X
6	Front Support Panel <i>benf/tm 788.10</i>	1	PCS	1099.50	1099.50 ✓
7	Front HeadLamp - RH <i>320 727.20</i>	1	PCS	3145.90	3145.90 ✓
8	Front Fender - RH <i>2.5</i>	1	PCS	654.60	654.60 ✓
9	Front Fender Dust Cover - RH <i>Top</i>	1	PCS	199.00	199.00 ✓
10	Front Fender Dust Cover Clipse - RH <i>neu 1/1 set</i>	1	PCS	33.00	33.00 ✓
11	Front Fender Emblem - RH <i>neu</i>	1	PCS	49.80	49.80 ✓
12	Front Fender Top Inner Garnish - RH <i>tm/cra</i>	1	PCS	46.90	46.90 ✓
13	Front Washer Tank <i>re</i>	1	PCS	168.90	168.90 ✓
14	Front Bumper <i>2.5 679.10</i>	1	PCS	864.20	864.20 ✓
15	Front Bumper Side Protector - RH <i>2.5</i>	1	PCS	189.60	189.60 ✓
16	Front Bumper Lower Rubber <i>11</i>	1	PCS	298.40	298.40 X
17	Front Bumper Inner Sponge <i>Top</i>	1	PCS	75.90	75.90 ✓
18	Front Bumper Reinforcement <i>benf</i>	1	PCS	381.90	381.90 ✓
19	Front Bumper Reinforcement Bracket - RH <i>benf</i>	1	PCS	151.60	151.60 ✓
20	Front Towing Cover <i>11</i>	1	PCS	36.90	36.90 X
21	Front Grille <i>2.5 605.10</i>	1	PCS	859.60	859.60 ✓
22	Front Grille Mould <i>SCR</i>	1	PCS	188.90	188.90 ✓
23	Front Bumper Top Rubber <i>neu</i>	1	PCS	96.90	96.90 ✓
24	Front Bumper Clipse <i>neu 1 set</i>	1	PCS	12.90 <i>50</i>	103.20 ✓
25	Front Bumper Reinforcement Side Garnish <i>Top</i>	1	PCS	90.40	90.40 ✓
26	Front Engine Dust Cover <i>Top</i>	1	PCS	181.60	181.60 ✓

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50
AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

M/S : First Capital Insurance Ltd

Estimate No : M001700

Date: : 12/09/2020

Veh Reg No SMN4073K

Make/Model : TOYOTA SIENTA

Chassis No : NHP1707121443

Engine No: 1NZ8508039

Reg. Date : 06/08/2019

PAGE:2/2

ATTN : Motor Claim Department

Your Ref No: : SMN4073K

Claim Type : THIRD PARTY

Accident Date : 04/09/2020

Estimate Repair Cost to Vehicle No : SMN4073K

S/N	Description	Quantity	Unit	Price	Amount
	<u>LIST PRICE</u>			<u>S\$</u>	<u>S\$</u>
27	Front Engine Dust Cover Clipse	1	PCS	12.90	12.90
28	Front Crossmember Support Arm - RH	1	PCS	298.40	298.40
29	Front Air Con Condenser Cover - RH	1	PCS	98.40	98.40
30	Front Bumper Top Beam	1	PCS	96.20	96.20
6308.8				TOTAL	10653.00
				DISCOUNT 25%	7989.75
					10963.00
					8222.25

LABOUR CHARGES

	<u>S\$</u>	<u>S\$</u>
31 Towing		50.00
32 Panel Beating		1200.00
33 Check Wiring and Diagnose Test		150.00
34 Alignment	1	50.00
35 To Removed & Replace Support Arm	1	60.00
36 To Spray Paint		900.00
37 To Removed & Refit Air Con Condenser and Charge Gas		160.00
TOTAL		2570.00

OVERALL TOTAL 10792.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR FOCUS AUTO PTE LTD



Aidah Zailani
Claims Executive
HP: 8139 9800

AUTHORISE SIGNATURE

P- 4747.35
L- 1840
6587.35
202
5268