

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III20009657/AGS3Q2

**Date:** 06/01/2021

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005521
<b>Claimant Vehicle No :</b>	SKE8173A	<b>Insured Vehicle No :</b>	GX9049S
Date of Loss:	06/09/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0001751

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE8173A	Engine No:	LDA33008160
Make & Model:	HONDA INSIGHT, 1.3 CVT HYBRID (A)	Chassis No:	JHMZE2850CS203890
Reg. Date:	03/04/2012 (Man. Year: 2012)	Odometer:	214055 km
Colour:	Blue		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,237.84	6,712.40	4,525.44	40.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,560.00	2,040.00	2,520.00	55.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,797.84</b>	<b>8,752.40</b>	<b>7,045.44</b>	<b>44.60</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,000.00</b>		
<b>(S\$)</b>	15,797.84	7,000.00	8,797.84	55.69
<b>+ GST 7.00/7.00% (S\$)</b>	1,105.85	490.00	615.85	55.69
<b>Nett Amount (S\$)</b>	<b>16,903.69</b>	<b>7,490.00</b>	<b>9,413.69</b>	<b>55.69</b>
<b>+ Loss of Use (8.0 x S\$50.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>7,897.45</b>		

### INSPECTION

Date of Assignment:	08/09/2020	
Date Inspected:	08/09/2020	Inspected At:
		Mg Solution Pte Ltd - Kaki Bukit (HQ)
		25 Kaki Bukit Road 4 #04-01
		Singapore 41800
Estimated Period of Repair:	7.0 days	

---

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 12 Oct 2020)
<b>Parts:</b>	144	HONDA INSIGHT 1.3 CVT HYBRID (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKE8173A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,255.20 FL	*1,092.00 FL
2	1		*TAILGATE LOGO	Necessary	80.00 FL	*80.00 FL
3	1		*TAILGATE EMBLEM INSIGHT	Necessary	85.20 FL	*85.20 FL
4	1		*TAILGATE EMBLEM HYBRID	Necessary	85.20 FL	*85.20 FL
5	1		*TAILGATE INNER LOCK	Damaged	230.50 FL	*230.50 FL
6	1		*TAILGATE WEATHER STRIP	Cut	255.40 FL	*255.40 FL
7	1		*TAILGATE INNER TRIM BOARD	Deformed	510.20 FL	*285.00 FL
8	1		*SET TAILGATE NUMBER PLATE LAMP	Not Necessary	155.60 FL	*- FL
9	1		*TAILGATE NUMBER PLATE GARNISH WITH CHROME	Cracked	405.00 FL	*405.00 FL
10	1		*SET TAILGATE WINDSCREEN MOULDING	Necessary	190.00 FL	*190.00 FL
11	1		*TAILGATE WINDSCREEN WITH MOULDING (SMALL)	Shattered	722.50 FL	*722.50 FL
12	1		*TAILGATE BRAKE LIGHT WITH BRACKET	Cracked	455.20 FL	*455.20 FL
13	1		*REAR BUMPER	Deformed	722.30 FL	*722.30 FL
14	1		*REAR BUMPER LOW	Deformed	412.20 FL	*412.20 FL
15	2		*REAR BUMPER SIDE RETAINER	Necessary	124.80 FL	*124.80 FL
16	1		*REAR BUMPER REFLECTOR	N/S Cracked	180.00 FL	*90.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Not Necessary	380.00 FL	*- FL
18	1		*TAILLAMP	N/S Cracked	1,261.00 FL	*630.50 FL
19	1		*TAILLAMP PANEL	N/S Dented	560.00 FL	*280.00 FL
20	1		*REAR FENDER INNER TRIM (TOP) LH	Deformed	630.00 FL	*225.00 FL
21	1		*TAILGATE WINDSCREEN (BIG)	Not Necessary	1,320.70 FL	*- FL
22	1		*REAR FENDER INNER TRIM (LOW)	N/S Deformed	822.40 FL	*411.20 FL
23	1		*REAR END PANEL	Dented	533.50 FL	*533.50 FL
24	1		*REAR END PANEL TOP GARNISH	Deformed	180.00 FL	*180.00 FL
25	1		*REAR FLOOR PANEL	Repair	1,157.90 FL	*- FL
26	1		*REAR FLOOR PANEL TOP GARNISH	Deformed	320.00 FL	*320.00 FL
27	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
28	1		*SET TAILGATE INNER TRIM CLIP	Necessary	20.00 FS	*20.00 FS
29	1		*TAILGATE WINDSCREEN SEALANT (BIG)	Necessary	100.00 FS	*60.00 FS
30	1		*TAILGATE WINDSCREEN SEALANT (SMALL)	Necessary	120.00 FS	*60.00 FS
31	1		*REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
32	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	20.00 FS	*20.00 FS
33	1		*REAR END PANEL INSULATOR SEAL	Necessary	120.00 FS	*60.00 FS
34	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
35	1		*REAR FLOOR PANEL INSULATOR SEAL	Not Necessary	120.00 FS	*- FS
36	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 13,844.80 8,275.50**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>					2,606.96	1,563.10
<b>Total Parts (S\$)</b>					<b>11,237.84</b>	<b>6,712.40</b>

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,800.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	800.00
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	150.00	50.00
4	WIRING CHECK	New	150.00	30.00
5	TUFF COAT	New	250.00	60.00
6	TRANSFER TAILGATE MECHANISM	New	140.00	80.00
7	REMOVE AND REFIX TAILGATE WINDSCREEN (BIG)	New	150.00	120.00
8	REMOVE AND REFIX TAILGATE WINDSCREEN (SMALL)	New	120.00	100.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,560.00</b>	<b>2,040.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >