

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19022122/HYF3E2
Date: 18/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800073282
Claimant Vehicle No : SLJ6457G **Insured Vehicle No :** GBD9043Y
Date of Loss: 11/12/2019 Nature of Claim: TP Claim No: 5731039988SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ6457G**
Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A) Engine No: 1ZRY346826
Reg. Date: 20/12/2016 (Man. Year: 2016) Chassis No: MR053REH104562395
Colour: Blue Odometer: 57144 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm
Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 16/12/2019
Date Inspected: 17/12/2019 Inspected At: Ms Car Auto Pte Ltd (HQ)
8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT
Singapore 415875
Estimated Period of Repair: 5.0 days

Adjuster: LEE HOCK ANN**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	0.00 F	*- F
2	1		*SET REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
5	1		*SET REVERSE SENSOR	Shorted	0.00 F	*- F
6	1		*REAR END PANEL	Repair	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	Crumpled	0.00 F	*- F
8	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
9	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
10	1		*BOOTLID	Repair	0.00 F	*- F
11	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
12	1		*BOOTLID LOCK	Jammed	0.00 F	*- F
13	1		*BOOTLID RUBBER	Crumpled	0.00 F	*- F
14	1		*REAR BUMPER SENSOR	Cracked	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)
0.00
0.00

LKK Auto Consultants Pte Ltd/SLJ6457G/18/02/2020 17:07

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

LKK Auto Consultants Pte Ltd/SLJ6457G/18/02/2020 17:07
--

< END OF ESTIMATES >