

INSPECTION REPORT

MS Car Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875

Assign Date:	13/12/2019	Inspection Date:	13/12/2019	TP Report Date:	12/12/2019
Accident Date:	11/12/2019	TP Policy No:	5112314356	Our Ref:	AVS2019-21952/PN
Place of Inspection:	MS Car Auto Pte Ltd 8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875			Your Ref:	SLJ6457G
				Claimant:	Koh Teng Meng

Description of Vehicle:

Veh. No:	SLJ6457G	Make/Model:	Toyota Corolla Altis 1.6 CVT		
Colour:	Grey	Engine No:	1ZRY346826	Sum Insured (S\$):	Market Value
Engine Capacity:	1,598 cc	Chassis No:	MR053REH104562395	Mkt Value (S\$):	\$61,000.00
Odometer:	57144	Reg. Date:	20/12/2016		

Condition of Vehicle:

General:	Fair	Modification:	No	Steering:	Serviceable
Air-Conditioner:	Yes	Radio/Cassette/CD:	Yes	Wing Mirror:	Yes
Handbrake:	Serviceable	Footbrake:	Serviceable	Paint work:	Fair
Tyre Make:	Michelin				
Front Tyre Size:	215/45R17	Front Left Side:	5mm	Front Right Side:	5mm
Rear Tyre Size:	215/45R17	Rear Left Side:	5mm	Rear Right Side:	5mm

Description of Damage:

The damage was found on the rear portion. The bootlid, rear bumper and reinforcement, end panel, reverse sensor and wire harness, both taillamps, both bootlid lamps were among other parts affected.

Point of Impact:



COMPLETED 21 FEB 2020

Adjuster:

Patrick Ng
Motor Appraiser

Date

Note: This report is confidential and solely for the use of the client. The inspection was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Adjustment of Repair Cost for Vehicle:		SLJ6457G		Our Ref: AVS2019-21952/PN	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
List Items					
1	1	Bootlid X R	Damaged	1,213.00	1,213.00 X
2	1	Bootlid inner trim Xsvc	Deformed	181.00	181.00 X
3	2	Bootlid hinge Xsvc	Bent	134.00	134.00 X
4	1	Bootlid lock Jam	Jammed	159.00	159.00 /
5	1	Bootlid lock striker Xsvc	Bent	65.00	65.00 X
6	1	Bootlid release sensor /CRA	Cracked	294.00	294.00 220
7	1	Bootlid release cable Xsvc	Jammed	53.00	53.00 X
8	1	Bootlid weatherstrip /CR4	Deformed	185.00	185.00 /
9	2	Licence plate lamp Xsvc	Damaged	144.00	144.00 X
10	1	Bootlid outer chrome garnish Xsvc	Damaged	187.00	187.00 X
11	2	Bootlid hinge garnish Xsvc	Not necessary	98.00	--
12	1	Bootlid "TOYOTA" logo /Nec	Necessary	61.00	61.00 /
13	1	Bootlid "COROLLA" emblem /Nec	Necessary	47.00	47.00 /
14	1	Bootlid "ALTIS" emblem /Nec	Necessary	42.00	42.00 /
15	2	Bootlid lamp Xsvc	Damaged	948.00	948.00 X
16	2	Bootlid lamp sponge seal /Nec	Necessary	16.00	16.00 /
17	1	Rear bumper /CR4	Damaged	688.00	688.00 531
18	2	Rear bumper side retainer /BR	Necessary	114.00	114.00 /
19	1	Rear bumper reinforcement /DD	Bent	576.00	576.00 399
20	1	Rear bumper lower cowl Xsvc	Not necessary	188.00	--
21	1	Taillamp LH-CRA RH Xsvc	Damaged	1,378.00	1,378.00 394
22	2	Taillamp sponge seal /Nec	Necessary	16.00	16.00 /
23	2	Taillamp panel Xsvc	Repair	294.00	--
24	2	Taillamp lower bracket /BR	Cracked	66.00	66.00 /
25	1	End panel Xsvc	Repair	532.00	--
26	1	End panel top garnish /CR4	Cracked	164.00	164.00 /
27	2	Rear bumper splash guard Xsvc	Not necessary	174.00	--
28	2	Rear bumper reflector Xsvc	Not necessary	132.00	--
Sub Total:				8,149.00	6,731.00
Discount (less 25%):				0.00	1,682.75
				8,149.00	5,048.25

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

2,414

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Adjustment of Repair Cost for Vehicle:

SLJ6457G

Our Ref: AVS2019-21952/PN

No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
-----	-----	----------------------	-----------	----------------------------	------------------------------

Special Nett Items

1	1	Rear licence plate & frame X SVC	Damaged	55.00	50.00 X
2	1	Parking aid harness X SVC	Cut	321.00	321.00 X
3	1	Reverse sensor / short.	Malfunction	280.00	250.00 200
4	10	Bootlid inner trim clips X SVC	Necessary	45.00	40.00 X
5	10	Rear bumper clips / NEC	Necessary	45.00	40.00 ✓
6	6	Taillamp clips / NEC	Necessary	27.00	20.00 10
7	6	Bootlid lamp clips X SVC	Necessary	27.00	20.00 X
8	1	End panel sealant X SVC	Not necessary	120.00	--
9	6	End panel top garnish clips / NEC	Necessary	27.00	20.00 ✓
10	1	Reverse camera X SVC	Not necessary	450.00	--
11	1	Sundries X SVC	Necessary	50.00	40.00 X
Sub Total:				1,447.00	801.00
Total Parts Price:				9,596.00	5,849.25 270

Labour Cost

1	To dismantle/ renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair/ replacement parts.	1,200.00	1,100.00 400
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	50.00	40.00 ✓
3	To remove, refit bootlid components and replace bootlid, check and re-adjust close gap, alignment and water seepage.	100.00	90.00 X
4	Supply spray paint material and necessary items to respray rear bumper, both rear fenders, end panel and other affected area/ panel.	1,200.00	1,000.00 500
5	To rust proof all affected portions after repair.	100.00	90.00 30
Sub Total:		2,650.00	2,320.00
Grand Total:		12,246.00	8,169.25 970

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Adjustment of Repair Cost for Vehicle:			SLJ6457G	Our Ref: AVS2019-21952/PN	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$

Recommendation and Conclusion:

We have inspected the actual damages found on the vehicle and recommended the replacement of parts and repairs accordingly. The estimate repair cost is S\$12,246.00. The repairer has agreed to undertake the repairs at our adjusted lumpsum amount of S\$6,500.00.

We have not authorised the repair. Under normal circumstances, estimated seven (07) working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.

The inspection was conducted entirely on a "Without Prejudice" basis.

Repair days - 3 days

$$\begin{array}{r}
 2,414 \\
 - 25\% \\
 \hline
 P = 1,810.50 \\
 N = 270 \\
 L = 970 \\
 \hline
 3,050.50 \\
 - 20\% \\
 \hline
 2,440.40
 \end{array}$$

215
\$ 2,450
3 days

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R