Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20009660/ARS3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800051340

Claimant
Vehicle No: SGV7777Y

Insured Vehicle No: SKJ6266C

Date of Loss: 04/09/2020 Nature of Claim: TP Claim No: 3056129432SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGV7777Y

Make & Model: TOYOTA ALPHARD, 2.5 ELEGANCE MR (A) Engine No: 2AR2223857

Reg. Date: 21/11/2019 (Man. Year: 2019) Chassis No: JTNGF3DH908024230

Colour: White Odometer: 6139 km

Engine Capacity: 2494 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18
Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,247.65	1,446.00	1,801.65	55.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	1,130.00	500.00	30.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,877.65	2,576.00	2,301.65	47.19
+ GST 7.00/7.00% (S\$)	341.44	180.32	161.12	47.19
Nett Amount (S\$)	5,219.09	2,756.32	2,462.77	47.19
. O D	N450 00/1 \ \ (OA)	600.00		

+ Car Rental (4.0 x S\$150.00/day) (S\$) 600.00

Nett Liability (S\$) 3,356.32

INSPECTION

Date of Assignment: 08/09/2020

Date Inspected: 08/09/2020 Inspected At: J-mart Motor Pte Ltd (HQ)

Blk 5 Defu Lane 10, #01-578

Singapore 539186

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: Jaslin Kok Chin Yi

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*REAR BUMPER	Deformed	835.00 FL	*835.00 FL		
2	1		*REAR BUMPER RH REFLECTOR	Cut	57.60 FL	*57.60 FL		
3	2		*REAR BUMPER REVERSE SENSOR	Damaged (1 PCS ONLY)	785.60 FL	*260.00 FL		
4	1		*REAR BUMPER TOW HOOK COVER	Missing	56.40 FL	*56.40 FL		
5	6		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL		
6	1		*REAR BUMPER RETAINER	O/S Necessary	270.00 FL	*135.00 FL		
7	1		*RH TAILLAMP	Not Necessary	843.60 FL	*- FL		
8	1		*REAR BUMPER SIDE RH	Deformed	425.00 FL	*325.00 FL		
9	1		*ALPHARD EMBLEM	Necessary	66.00 FL	*66.00 FL		
10	1		*END PANEL	Repair	798.00 FL	*- FL		
11	1		*REAR BUMPER RH BRACKET	Dented	163.00 FL	*163.00 FL		
F=Fra	F=Franchise part. L=ListItemDisc. Sub Total (S\$)					1,928.00		
- List Item Discount on L Items 25.00/25.00% (S\$)				1,082.55	482.00			
				Total Parts (S\$)	3,247.65	1,446.00		
	Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	800.00	700.00
3	WIRING	New	30.00	30.00
		Gross Labour Cost (S\$)	1,630.00	1,130.00
	F	Report was unsubmitted during this print-out.		

< END OF ESTIMATES >