



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 5734G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEADLAMP RH	CUT	713.90	713.90
1	FRONT BUMPER	DEFORMED	435.80	435.80
2	FRONT BUMPER SIDE RETAINER LH/RH @\$58.70	O/S DAMAGED	117.40	58.70
1	FRONT BUMPER FOG LAMP RH	CRACKED	425.90	285.00
1	FRONT BUMPER FOG LAMP GARNISH RH	NOT NECESSARY	95.60	-
1	FRONT FENDER INNER SHIELD RH	NOT NECESSARY	165.70	-
	LESS 25% DISCOUNT		-488.58	-373.35
			1,465.72	1,120.05
<u>SPECIAL NETT ITEMS</u>				
1	FRONT HEADLAMP CLIPS SET RH (SN)	NECESSARY	40.00	20.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	FRONT FENDER INNER SHIELD CLIPS SET RH (SN)	NOT NECESSARY	60.00	-
			180.00	50.00
<u>LABOUR</u>				
	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION.		400.00	300.00
	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA.		400.00	200.00
	TO PERFORM LIGHTING & WIRING CHECK.		80.00	30.00
			880.00	530.00
GRAND TOTAL			2,525.72	1,700.05
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,350.00

Report Ref No. CS/AGI20009661/Ayf3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.