

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:**

CC6/AIG20009663/AGA3Q2

**Date:**

31/12/2021

**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900005213

**Claimant Vehicle No :** SLR5702M**Insured Vehicle No :**

SMH3063C

Date of Loss: 29/08/2020

Nature of Claim:

TP

Claim No:

4957588334SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLR5702M**

Make &amp; Model: SUBARU IMPREZA 4D, 1.6 I-S AWD CVT (A)

Engine No: FB16Y662678

Reg. Date: 19/08/2017 (Man. Year: 2017)

Chassis No: JF1GK3KC5HG003518

Colour: Blue

Odometer: 28525 km

Engine Capacity: 1600 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 205/50 R17    | Rear Tyre Size:  | 205/50 R17    |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 310.50            | 0.00              | 310.50            | 100.00        |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 965.00            | 200.00            | 765.00            | 79.27         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>1,275.50</b>   | <b>200.00</b>     | <b>1,075.50</b>   | <b>84.32</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>89.29</b>      | <b>14.00</b>      | <b>75.29</b>      | <b>84.32</b>  |

|                                    |                 |               |                 |              |
|------------------------------------|-----------------|---------------|-----------------|--------------|
| <b>Nett Amount (S\$)</b>           | <b>1,364.79</b> | <b>214.00</b> | <b>1,150.79</b> | <b>84.32</b> |
| <b>Global Sum Settlement (S\$)</b> |                 | <b>0.00</b>   |                 |              |

INSPECTION

|                             |            |               |   |
|-----------------------------|------------|---------------|---|
| Date of Assignment:         | 08/09/2020 |               |   |
| Date Inspected:             | 08/09/2020 | Inspected At: | 1st Autoworks Pte Ltd (HQ)<br>23 Kaki Bukit Ave 4, #04-01<br>Singapore 415933 |
| Estimated Period of Repair: | 1.0 days   |               |   |

|                  |             |                 |               |
|------------------|-------------|-----------------|---------------|
| <b>Adjuster:</b> | ADRIAN LING | <b>Manager:</b> | Chong Pui Lin |
|------------------|-------------|-----------------|---------------|

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's  | Amount                            |
|-----|-----|----------|-------------|-----------|---|-----------------------------------|
| 1   | 1   |          | *RHF FENDER | Repair    | 345.00 FL   | *- FL                             |
|     |     |          |             |           |   | F=Franchise part. L=ListItemDisc. |
|     |     |          |             |           | Sub Total (\$)                                    | 345.00                            |
|     |     |          |             |           | - List Item Discount on L Items 10.00/10.00% (\$) | 34.50                             |
|     |     |          |             |           | Total Parts (\$)                                  | 310.50                            |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars   | Lab.Type | Repairer's    | Amount        |
|--------------------------------|---|----------|---------------|---------------|
| <b><u>Labour Items</u></b>     |   |          |               |               |
| 1                              | TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS | New      | 200.00        | 0.00          |
| 2                              | CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA  | New      | 200.00        | 200.00        |
| 3                              | TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR        | New      | 60.00         | 0.00          |
| 4                              | TO CONDUCT 4 WHEEL ALIGNMENT  | New      | 120.00        | 0.00          |
| 5                              | TO REMOVE AND REPLACE DAMAGED UNDER CARRIAGE PARTS  | New      | 275.00        | 0.00          |
| 6                              | TO REFOCUS HEADLAMP   | New      | 110.00        | 0.00          |
| <b>Gross Labour Cost (S\$)</b> |   |          | <b>965.00</b> | <b>200.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >