

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20009669/QPA3Q2

Date: 13/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SG5585J

Insured Vehicle No : SKM8500Y

Date of Loss: 29/08/2020

Nature of Claim: TP

Claim No: 1370451357SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SG5585J**

Make & Model: VOLVO B9TL, 9.4 D AUTO TURBO ABS (A)

Engine No: D9195521

Reg. Date: 30/09/2016 (Man. Year: 2016)

Chassis No: YV3S4P922GA179948

Colour: Multi-colour

Odometer: 197659 km

Engine Capacity: 9364 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size:

275/70 R22.5

Front Left Side: Falken 6 mm

Rear Left Side:

Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side:

Falken 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 1,303.11 | 0.00 | 1,303.11 | 100.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,676.00 | 962.00 | 714.00 | 42.60 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (\$\$) | 2,979.11 | 962.00 | 2,017.11 | 67.71 |
| Global Sum Settlement (\$\$) | | 0.00 | | |

INSPECTION

Date of Assignment: 07/09/2020

Date Inspected: 07/09/2020 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 1.0 days

Adjuster: OI SUN PIN

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------|-----------|------------|--------|
| 1 | 1 | | *N/S CORNER BUMPER | Repair | 974.78 F | *- F |
| 2 | 1 | | *N/S CORNER DEFLECTOR | Repair | 328.33 F | *- F |

F=Franchise part.

| | | |
|--------------------------|-----------------|-------------|
| Total Parts (S\$) | 1,303.11 | 0.00 |
|--------------------------|-----------------|-------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|------------------------------------------------------------------------------|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS | New | 1,060.00 | 530.00 |
| 2 | PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS | New | 616.00 | 432.00 |
| Gross Labour Cost (\$\$) | | | 1,676.00 | 962.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >