Page 1 of 3 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20009674/T1TF3E2

Date: 25/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100398826 Claimant Vehicle SBS8950G

Insured Vehicle No: EZ3208C No:

Date of Loss: 03/09/2020 Nature of Claim: TP Claim No: 2917221743SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBS8950G

Make & Model: SCANIA KUB4X2 9.3L A/T ABS TURBO, 9.3 D (A) Engine No: 6600628

Reg. Date: 11/08/2009 (Man. Year: 2009) Chassis No: YS2K4X20001865351

Colour: Multi-colour Odometer: 723193 km

Engine Capacity: 9290 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D) Front Left Side: Rear Left Side: Bridgestone 8/8 mm Bridgestone 8 mm Rear Right Side: Bridgestone 8/8 mm Front Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/09/2020

Sbs Transit Ltd (Bedok) (HQ) Date Inspected: 10/09/2020 Inspected At:

1470 BEDOK NORTH ÁVE 4

Singapore 489946

Estimated Period of Repair: 1.0 days

DENISE TAY KWEE CHENG Adjuster: MOHD TAUFIKH BIN HAMID Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty Part N	o. Particulars	Condition	Repairer's	Amount		
1	1	*REAR RH WHEEL ARCH PANEL	Repair	0.00 F	*- F		
2	1	*REAR RH SIDE PANEL	Repair	0.00 F	*- F		
F=Fra	inchise part.		Total Parts (S\$)	0.00	0.00		
	Report was unsubmitted during this print-out.						

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >