

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20009678/ATF3E2

Date: 04/03/2021

REFERENCE

Insured/Claimant:	NG KOK YEE	Policy No:	1900000759		
Date of Loss:	06/09/2020	Nature of Claim:	OD	Claim No:	0676409367SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH1201J		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZA91797
Reg. Date:	11/01/2019 (Man. Year: 2018)	Chassis No:	WAUZZZGA0KA000753
Colour:	Grey	Odometer:	20241 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$100,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,810.00	6,197.92	9,612.08	60.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,772.00	2,572.00	3,200.00	55.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,582.00	8,769.92	12,812.08	59.36
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	21,182.00	8,369.92	12,812.08	60.49
+ GST 7.00/7.00% (S\$)	1,482.74	585.89	896.85	60.49
Nett Amount (S\$)	22,664.74	8,955.81	13,708.93	60.49

INSPECTION

Date of Assignment:	10/09/2020		
Date Inspected:	09/09/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,854.00 FS	*1,482.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	343.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	195.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	167.00 FS	*133.60 FS
5	1		*FRONT BUMPER END CAP - RH	Not Necessary	34.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	296.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	154.00 FS	*- FS
8	1		*WHEEL SPOILER - RH	Not Necessary	34.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,395.00 FS	*1,116.00 FS
10	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	123.00 FS	*- FS
11	1		*FRONT BUMPER CARRIER	Bent	679.00 FS	*543.20 FS
12	1		*FRONT BUMPER COVER	Not Necessary	99.00 FS	*- FS
13	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
14	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
15	1		*BONNET	Dented	2,757.00 FS	*2,205.60 FS
16	1		*BONNET ATTACHMENT PARTS	Not Necessary	163.00 FS	*- FS
17	2		*BONNET LID HINGE - LH/RH	Not Necessary	122.00 FS	*- FS
18	2		*BONNET STRIKER - LH/RH	Not Necessary	218.00 FS	*- FS
19	1		*BONNET SOUND ABSORBER	Not Necessary	217.00 FS	*- FS
20	2		*BONNET LID LOCK	Not Necessary	423.00 FS	*- FS
21	1		*BONNET BOWEN CABLE - CENTRE	Not Necessary	57.00 FS	*- FS
22	1		*BONNET RELEASE ELEMENT	Not Necessary	57.00 FS	*- FS
23	1		*BONNET RELEASE LEVER	Not Necessary	13.00 FS	*- FS
24	1		*HEADLIGHT MOUNTING -RH	Not Necessary	117.00 FS	*- FS
25	1		*LED HEADLIGHT - RH	Not Necessary	4,859.00 FS	*- FS
26	1		*RADIATOR AIR GUIDE - RH	Not Necessary	30.00 FS	*- FS
27	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Deformed	22.00 FS	*17.04 FS
28	1		*EXTERNAL TEMPERATURE SENSOR	Not Necessary	56.00 FS	*- FS
29	2		*FRONT WHEEL COVER - LH/RH	Necessary	636.00 FS	*508.80 FS
30	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
31	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
32	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	77.00 FS	*61.20 FS
33	1		*BONNET IMPACT PROTECTION - CENTRE/LH/RH (3PCS)	Necessary	90.00 FS	*70.48 FS
34	1		*LIFT CYLINDER- RH	Not Necessary	141.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 15,810.00 6,197.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	280.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER, BONNET AND HINGES	New	2,500.00	1,100.00
5	TO CARRY OUT DISGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,772.00	2,572.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >