

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20009679/UVF3Q2

**Date:** 29/09/2020

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00033232001

**Claimant  
Vehicle No :** SLK3848B

**Insured  
Vehicle No :** GBC4428J

Date of Loss: 05/09/2020

Nature of  
Claim: TP

Claim  
No: SNM20D203295/C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK3848B**

Make & Model: MITSUBISHI LANCER EX, 1.5 (A)

Engine No: 4A92CL8386

Reg. Date: 16/01/2017 (Man. Year: 2016)

Chassis No: JMYSRCY1AGU006081

Colour: Blue

Odometer: 60257 km

Engine Capacity: 1590 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60R16

Rear Tyre Size: 205/60R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,545.00	2,166.00	379.00	14.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,950.00	3,090.00	1,860.00	37.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>7,495.00</b>	<b>5,256.00</b>	<b>2,239.00</b>	<b>29.87</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	524.65	367.92	156.73	29.87
<b>Nett Amount (\$\$)</b>	<b>8,019.65</b>	<b>5,623.92</b>	<b>2,395.73</b>	<b>29.87</b>

### INSPECTION

Date of Assignment: 14/09/2020

Date Inspected: 11/09/2020 Inspected At:

Cycle & Carriage Fulco Motor Dealer  
Pte Ltd (HQ)  
330 Ubi Road 3  
Singapore 408650

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 Sep 2020)
<b>Parts:</b>	143	MITSUBISHI LANCER EX 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLK3848B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE,RR BUMPER	Distorted/Torn	861.00 FS	*861.00 FS
2	10		*CLIP,BUMPER	Necessary	40.00 FS	*40.00 FS
3	1		*COVER,REAR BUMPER	Repair	37.00 FS	*- FS
4	1		*RH BRKT,R/BMPR FACE	Necessary	17.00 FS	*17.00 FS
5	1		*LH BRKT,R/BMPR FACE	Necessary	17.00 FS	*17.00 FS
6	1		*REINFORCEMENT,RR BUM	Bent	233.00 FS	*233.00 FS
7	1		*UPR REINFORCEMENT,RR	Bent	91.00 FS	*91.00 FS
8	2		*BRACKET,LICENSE PLAT	Not Necessary	26.00 FS	*- FS
9	1		*BUZZER,KEYLESS OPERA	Serviceable	172.00 FS	*- FS
10	1		*LH REFLECTOR	Not Necessary	37.00 FS	*- FS
11	1		*RH REFLECTOR	Not Necessary	37.00 FS	*- FS
12	2		*LAMP ASSY,LICENSE PL	Not Necessary	70.00 FS	*- FS
13	1		*MARK,THREE-DIA	Necessary	69.00 FS	*69.00 FS
14	1		*MARK,LANCER	Necessary	58.00 FS	*58.00 FS
15	1		*C&C LOGO	Necessary	50.00 FS	*50.00 FS
16	1		*MIVEC EMBLEM	Necessary	50.00 FS	*50.00 FS
17	1		*REAR NUMBER PLATE WITH CASING	Bent	50.00 FS	*50.00 FS
18	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*280.00 FS
19	1		*REAR REVERSE CAMERA	Cracked	350.00 FS	*350.00 FS
<b>Total Parts (S\$)</b>					<b>2,545.00</b>	<b>2,166.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	DIAGNOSTIC/SCANNING	New	250.00	250.00
2	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS	New	100.00	80.00
3	TO REMOVE AND RE-INSTALL REAR TRIMMING AND CAPERTING TO GAVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	600.00	300.00
4	TO REPLACE REAR BUMPER,REAR REINFORCEMENT,ETC-TO REPAIR REAR END PANEL.STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	1,800.00	1,200.00
5	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	New	2,100.00	1,260.00
6	TO APPLY SEALANT KIT ON NEW PANEL	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,950.00</b>	<b>3,090.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >