

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20009682/KSF3E2
Date: 28/09/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSNW00052952001	
Claimant Vehicle No : GBH6955P	Insured Vehicle No : GBB6840T	
Date of Loss: 03/09/2020	Nature of Claim: TP	Claim No: SNM20D203223/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBH6955P		
Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No: 1KD2811704	
Reg. Date: 06/09/2018 (Man. Year: 2018)	Chassis No: JTFAT35Y70K211011	
Colour: White	Odometer: 96210 km	
Engine Capacity: 2982 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8	Rear Tyre Size: 155 R15X8 (D)	
Front Left Side: Yokohama 9 mm	Rear Left Side: Yokohama 9/9 mm	
Front Right Side: Yokohama 9 mm	Rear Right Side: Yokohama 9/9 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,345.00	1,345.00	0.00	0.00
Miscellaneous Items	20.00	20.00	0.00	0.00
Labour	1,430.00	1,140.00	290.00	20.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,795.00	2,505.00	290.00	10.38
+ GST 7.00/7.00% (S\$)	195.65	175.35	20.30	10.38
Nett Amount (S\$)	2,990.65	2,680.35	310.30	10.38

INSPECTION

Date of Assignment: 10/09/2020	Present Location: Cheng Hoe Motor Pte Ltd (Yishun)	
Date Inspected: 16/09/2020	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)	
	Blk 1019 #01-374/382, Yishun Industrial Park A	
	Singapore 768761	
Estimated Period of Repair: 4.0 days		

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 28 Sep 2020)

Parts: N/A TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBH6955P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT BUMPER	Bent	260.00 F	*260.00 F
2	1		*1 PC RH HEADLAMP	Cracked	320.00 F	*320.00 F
3	1		*1 PC FRT RH CORNAL PANEL	Cracked	90.00 F	*90.00 F
4	1		*1 PC FRT RH DOOR	Bent	550.00 F	*550.00 F
5	1		*1 PC FRT RH SIDE MIRROR	Dented / Cut	95.00 F	*95.00 F
<u>Supplementary #1</u>						
6	1		*1 PC FRT RH CORNER PANEL BRACKET	Bent	30.00 F	*30.00 F
Total Parts (S\$)					1,345.00	1,345.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC FRT RH DOOR COY STICKER (NECESSARY)	20.00	20.00
Sub Total (\$\$)			20.00	20.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,CORNAL PANEL,KNOCK & REPAIR FRT RH W/SCREEN PILLAR & REALIGN THE SAME	New	600.00	500.00
2	PUTTY & RESPRAY FRT RH DOOR,FRT BUMPER,CORNAL PANEL,FRT RH W/SCREEN PILLAR	New	650.00	520.00
3	REMOVE & REFIX FRT RH DOOR GLASS,CHECK CENTRAL LOCKING & POWER MIRROR	New	60.00	60.00
4	TO REWRITE ADVERTISEMENT	New	120.00	60.00
Gross Labour Cost (\$\$)			1,430.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >