



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 2704X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BOOTLID	DENTED	875.00	875.00
1	BOOTLID SPOILER	BROKEN	630.00	400.00
1	BOOTLID LOGO	NECESSARY	46.00	46.00
1	BOOTLID EMBLEM - MAZDA	NECESSARY	35.00	35.00
1	BOOTLID EMBLEM - 3	NECESSARY	35.00	35.00
1	BOOTLID STICKER - SP	MISSING	40.00	40.00
1	BOOTLID LAMP LH	NOT NECESSARY	356.00	-
1	BOOTLID LAMP RH	NOT NECESSARY	356.00	-
1	BOOTLID LOCK	BENT	196.00	196.00
1	BOOTLID RUBBER	NOT NECESSARY	95.00	-
2	TAILLAMP LOWER BRACKET LH & RH @\$63.00	NOT NECESSARY	126.00	-
1	REAR BUMPER	DENTED	879.00	799.60
1	SET REAR NUMBER PLATE LAMP	NOT NECESSARY	183.00	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	65.00	-
1	SET REAR BUMPER SKIRT (MISSING)	NOT CONSISTENT WITH THE IMPACT	860.00	-
1	REAR BUMPER SIDE RETAINER LH	BROKEN	36.00	36.00
1	REAR BUMPER SIDE RETAINER RH	BROKEN	36.00	36.00
2	REAR BUMPER LOWER BRACKET @\$42.00	NOT NECESSARY	84.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	475.00	-
10	REAR BUMPER CLIPS @\$4.80	NECESSARY	48.00	30.00
1	END PANEL TOP GARNISH	NOT NECESSARY	125.00	-
1	END PANEL	TO REPAIR SEE LABOUR	350.00	-
LESS 20% DISCOUNT			-1,186.20	-505.72
			4,744.80	2,022.88
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REVERSE SENSOR (SN)	BROKEN	280.00	200.00
1	REAR NUMBER PLATE (SN)	BROKEN	40.00	40.00
			320.00	240.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO INSPECT REAR LIGHTING MECHANISM & CHECK WIRING.		60.00	30.00
	TO INSTALL REVERSE SENSOR & DIAGNOSE FUNCTION.		80.00	30.00
	TO CUT OFF END PANEL. TO REMOVE & REPLACE DAMAGED ITEMS. REALIGN CONNECTION. INCLUSIVE OF THE REPAIR OF END PANEL.		800.00	600.00
	TO APPLY BODY JOINT SEALANT.		60.00	30.00
	TO RUST PROOF ON REPAIRED AREAS.	NOT NECESSARY	60.00	-
	TO SPRAY PAINT ON REPAIRED AREAS.		800.00	700.00
			1,860.00	1,390.00
<b>GRAND TOTAL</b>			<b>6,924.80</b>	<b>3,652.88</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,900.00</b>

Report Ref No. CS/SMO20009684/EKyf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.