

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20009691/T1BA3Q2**Date:** 11/03/2021REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900103885
Claimant
Vehicle No : SH8961G **Insured Vehicle No :** SML6434A
Date of Loss: 09/09/2020 Nature of Claim: TP Claim No: 5786097763SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SH8961G**
Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4FDGU713007
Reg. Date: 13/12/2017 (Man. Year: 2016) Chassis No: KMHLB41UMHU098595
Colour: Blue Odometer: 394211 km
Engine Capacity: 1685 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	1,134.80	952.40	182.40	16.07	
Miscellaneous Items	0.00	0.00	0.00		
Labour	680.00	510.00	170.00	25.00	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	1,814.80	1,462.40	352.40	19.42	
Approved Total (Overridden) (S\$)		1,150.00			
	(S\$)	1,814.80	1,150.00	664.80	36.63
+ GST 7.00/7.00% (S\$)		127.04	80.50	46.54	36.63
Nett Amount (S\$)	1,941.84	1,230.50	711.34	36.63	
+ Car Rental (2.0 x S\$80.45/day) (S\$)		160.90			
+ Doc/Search Fee (S\$)		2.00			
Nett Liability (S\$)		1,393.40			

INSPECTION

Date of Assignment: 10/09/2020
Date Inspected: 10/09/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969
Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*COVER ASSY -RR BUMPE	Deformed	1,106.00 FL	*1,106.00 FL	
2	1		*COVER -RR BUMPER LWR	Repair	228.00 FL	*- FL	
3	10		*HYUNDAI BUMPER COVER CLIP	Necessary	22.00 FL	*22.00 FL	
4	1		*PROTECTOR MAT	Necessary	50.00 FS	*50.00 FS	
					Sub Total (\$)	1,406.00	1,178.00
					- List Item Discount on L Items 20.00/20.00% (\$)	271.20	225.60
					Total Parts (\$)	1,134.80	952.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	300.00	280.00
2	SPRAYPAINT CHARGE	New	300.00	200.00
3	REMOVE /REFIX REVERSE SENSOR	New	80.00	30.00
			Gross Labour Cost (\$\$)	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >