

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009696/KES3Q2

Date: 22/03/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800025728
Claimant Vehicle No :	FBQ9953C	Insured Vehicle No :	SLZ899U
Date of Loss:	17/08/2020	Nature of Claim:	TP
		Claim No:	8009671908SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ9953C	Engine No:	G3K9E0029067
Make & Model:	YAMAHA MT-15, 155cc	Chassis No:	MH3RG5610KK004228
Reg. Date:	22/01/2020 (Man. Year: 2019)	Odometer:	0 km
Colour:	Black/Grey		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	110/70R17	Rear Tyre Size:	150/60R17
Front Left Side:	Bridgestone 3 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,896.72	3,901.29	3,995.43	50.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	320.00	760.00	70.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>8,976.72</b>	<b>4,221.29</b>	<b>4,755.43</b>	<b>52.98</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,150.00</b>		
<b>Nett Amount (\$\$)</b>	<b>8,976.72</b>	<b>3,150.00</b>	<b>5,826.72</b>	<b>64.91</b>
<b>+ Loss of Use (4.0 x S\$20.00/day) (\$\$)</b>		80.00		
	<b>Nett Liability (\$\$)</b>	<b>3,230.00</b>		

### INSPECTION

Date of Assignment:	10/09/2020	Lee Luew Sing Motor (HQ)
Date Inspected:	11/09/2020 Inspected At:	No. 10 Ang Mo Kio Industrial Park 2A, #03-10 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

3/22/2021

## Adjuster Report

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FRONT FAIRING	Dented / Cut	1,219.00 FL	*1,219.00 FL
2	2		*FRONT FAIRING BRACKET (LH/RH)	Repair	318.00 FL	*- FL
3	1		*FRONT WHEEL MUDGUARD	Cut	297.20 FL	*297.20 FL
4	1		*FRONT SIGNAL LAMP LH	Broken	72.00 FL	*72.00 FL
5	1		*SET FRONT LOWER FAIRING	Repair	498.00 FL	*- FL
6	2		*FRONT FORK BRACKET	Not Necessary	90.00 FL	*- FL
7	1		*SET RIDER SEAT LOWER GARNISH	Serviceable	359.00 FL	*- FL
8	1		*FUEL TANK ASSEMBLY	Serviceable	898.00 FL	*- FL
9	1		*FOOT GEAR LEVER	Bent	312.00 FL	*312.00 FL
10	1		*CLUTCH LEVER	Dented	112.00 FL	*112.00 FL
11	1		*ENGINE LOWER COVER	Serviceable	298.00 FL	*- FL
12	1		*ENGINE SIDE COVER LH	Cut	329.00 FL	*329.00 FL
13	1		*PILLION FOOT REST BRACKET LH	Bent	98.20 FL	*98.20 FL
14	1		*HANDLE LH	Bent	298.50 FL	*298.50 FL
15	1		*HANDLE BALANCER LH	Dented	81.00 FL	*81.00 FL
16	1		*HANDLE SHAFT LH	Serviceable	298.00 FL	*- FL
17	1		*BATTERY	Serviceable	128.00 FL	*- FL
18	1		*LEG REST LH	Dented	98.20 FL	*98.20 FL
19	1		*BRAKE FOOT LEVER	Serviceable	68.50 FL	*- FL
20	1		*PARKING STAND	Distorted	287.00 FL	*287.00 FL
21	1		*REAR VIEW MIRROR LH	Cut	247.00 FL	*247.00 FL
22	1		*REAR WHEEL CHAIN COVER GARNISH LH	Serviceable	156.20 FL	*- FL
23	1		*SET EXHAUST SILENCER	Repair	1,211.00 FL	*- FL
24	2		*REAR SIGNAL LAMP	Cut	136.00 FL	*136.00 FL
25	1		*SET REAR SIGNAL GARNISH	Dented / Cut	259.00 FL	*259.00 FL
26	1		*REAR WHEEL NUT LH	Dented	22.00 FL	*22.00 FL
27	1		*SET REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS
28	1		*HEADLAMP FAIRING STICKER	Necessary	20.00 FS	*20.00 FS
29	1		*FAIRING STICKER	Necessary	120.00 FS	*120.00 FS
30	1		*RIDER SEAT LOWER GARNISH STICKER	Necessary	65.00 FS	*65.00 FS
31	1		*FUEL TANK STICKER	Necessary	150.00 FS	*150.00 FS
32	1		*ENGINE LOWER FAIRING STICKER	Not Necessary	65.00 FS	*- FS
33	1		*REAR FAIRING STICKER	Necessary	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,715.80</b>	<b>4,288.10</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	819.08	386.81
<b>Total Parts (\$\$)</b>	<b>7,896.72</b>	<b>3,901.29</b>

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE AND REFIT ABOVE ITEMS	New	500.00	200.00
2	REMOVE ,REFIT AND RE-ALIGN FORK	New	200.00	120.00
3	SPRAY PAINT	New	380.00	0.00
Gross Labour Cost (\$\$)			1,080.00	320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >