

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20009703/UES3Q2

Date: 17/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070054762

Claimant
Vehicle No : SJP8604C **Insured Vehicle No :** SMT1062E

Date of Loss: 09/09/2020 Nature of Claim: TP Claim No: 2917574316SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP8604C	Engine No:	G4EE9301729
Make & Model:	HYUNDAI GETZ, 1.4 5DR (A)	Chassis No:	KMHBU51DR9U908060
Reg. Date:	15/04/2009 (Man. Year: 2009)	Odometer:	141056 km
Colour:	Black		
Engine Capacity:	1399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R14	Rear Tyre Size:	185/60 R14
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,520.80	2,032.64	2,488.16	55.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,590.00	1,290.00	1,300.00	50.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,110.80	3,322.64	3,788.16	53.27
Approved Total (Overridden) (\$\$)		2,650.00		
(\$\$)	7,110.80	2,650.00	4,460.80	62.73
+ GST 7.00/7.00% (\$\$)	497.76	185.50	312.26	62.73
Nett Amount (\$\$)	7,608.56	2,835.50	4,773.06	62.73
+ Loss of Use (6.0 x S\$60.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		3,197.50		

INSPECTION

Date of Assignment: 10/09/2020

Date Inspected: 10/09/2020 Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	311.90 FL	*- FL
2	10		*FRONT BUMPER CLIP	Not Necessary	45.00 FL	*- FL
3	1		*O/S FRONT BUMPER SIDE RETAINER	Not Necessary	45.00 FL	*- FL
4	1		*O/S FRONT FENDER	Badly Dented	372.00 FL	*372.00 FL
5	1		*O/S FRONT FENDER INNER COWLING	Torn	253.00 FL	*181.20 FL
6	6		*O/S FRONT FENDER INNER COWLING CLIP	Necessary	27.00 FL	*27.00 FL
7	1		*O/S FRONT FENDER MUDFLAP	Deformed / Warped	65.00 FL	*65.00 FL
8	1		*O/S FRONT DOOR	Dented / Bent	843.00 FL	*843.00 FL
9	1		*O/S FRONT DOOR PAD	Grazed	85.00 FL	*85.00 FL
10	1		*O/S SIDE MIRROR ASSY	Not Necessary	480.00 FL	*- FL
11	1		*O/S HEADLAMP (Scratched)	Not Consistent With The Impact	380.00 FL	*- FL
12	1		*O/S FRONT WHEEL BEARING	Necessary	89.00 FL	*89.00 FL
13	1		*O/S FRONT LOWER ARM	Bent	223.60 FL	*223.60 FL
14	1		*O/S FRONT STEERING RACK TIE ROCK	Not Necessary	185.00 FL	*- FL
15	1		*STEERING RACK AND PINION ASSY	Not Necessary	1,529.00 FL	*- FL
16	1		*O/S FRONT KNUCKLE ARM	Bent	280.00 FL	*280.00 FL
17	1		*O/S FRONT SPORT RIM	Dented / Bent	350.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **5,563.50** **2,465.80**
- List Item Discount on L Items 20.00/20.00% (\$\$) 1,042.70 433.16

Total Parts (\$\$) **4,520.80** **2,032.64**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TRANSFER OF TYRE ,RIM AND ON WHEEL BALANCING	New	80.00	0.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	120.00	100.00
3	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	80.00	50.00
4	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF THE NECESSARY PARTS ,TO PERFORM FINAL CHECKING AND TESTING	New	200.00	120.00
5	TO PERFORM WATER SEEPAGE TEST ,WINDNOISE AND TEST-DRIVE	New	80.00	0.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
7	TO PROVIDE ADMINSTRATIVE WORKS ,APPLICATION AND RESEAL OFF-PEAK CAR LICENCE PLATE	New	50.00	0.00
8	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,000.00	400.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	900.00	600.00
Gross Labour Cost (\$\$)			2,590.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >