

Vehicle No.: SJJ9278K

Expire No.: R18A11033P22

Chassis No.: JHMFD16306S210526

D.O.A: 9/9/20

TP 111

Veron.

ITEM LIST

1PCS: FRONT BUMPER	Distorted	\$950	638
1PCS: FRONT BUMPER SIDE RETAINER	Rit Dmg	\$75	23.
1PCS: FRONT BUMPER FOG LAMP	Cracked	\$225	✓
1PCS: FRONT BUMPER BEAM	Not in	\$75	X
1PCS: FRONT BUMPER FOG LAMP COVER	Not in	\$45	X
1PCS: FRONT BUMPER LOWER SKIRT	Cracked	\$335	✓
1PCS: FRONT BUMPER REINFORCEMENT	Dented	\$275	✓
1PCS: FRONT BUMPER HEADLAMP(HID)(RH)	Cracked	\$750	✓
1PCS: FRONT BUMPER HEADLAMP CLIP	Not in	\$45	X
1PCS: FRONT BUMPER FENDER (RH)	Distorted	\$375	✓
1PCS: FRONT BUMPER FENDER INNER SHIELD (RH)	Torn	\$185	✓
8PCS: FRONT BUMPER FENDER INNER SHIELD CLIP	Not in	\$36	✓
1PCS: FRONT BUMPER FENDER INNER PANEL(RH)	Distorted	\$450	✓
1PCS: FRONT BUMPER WIPER WASHER TANK	Not in	\$95	X
1PCS: FRONT BUMPER BONNET	Repair	REPAIR	X
1PCS: FRONT BUMPER FRONT DOOR(RH)	Repair	REPAIR	X
TOTAL PARTS COST		\$3916	
LESS 20%		(783.20)	
TOTAL COST		\$3132.80	

3292

len 20%: 2633.60

LABOUR

TO SUPPLY LABOUR TO REPAIR AND REPLACE ABOVE MENTIONED PARTS	\$800	600.
TO SUPPLY LABOUR AND PAINT TO SPRAY ACCIDENT AFFECTED AREA	\$1200	600.
TO SUPPLY LABOUR TO REWIRE ABOVE MENTIONED PARTS	\$90	30
TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	\$120	60

TO SUPPLY LABOUR TO STRAIGHTEN CHASSIS FRONT

\$400 x

TOTAL LABOUR

\$2610

1280

TOTAL PARTS AND LABOUR

\$5742.80

LESS 20%

(\$1148.56)

TOTAL FINAL LUMP SUM

\$4500

total: 3823.60

L/S: 3.1K ✓

05 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: