

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20009718/AQF3E2

Date: 21/01/2021

REFERENCE

Insured/Claimant:	LEE WAI MENG(LI WEIMING)	Policy No:	2070006071	
Date of Loss:	02/09/2020	Nature of Claim:	OD	Claim No: 4808449471SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ8296D	Engine No:	CVK087120
Make & Model:	AUDI A4, 2.0 MU TFSI (8E) (A)	Chassis No:	WAUZZZF46KA112470
Reg. Date:	21/01/2020 (Man. Year: 2019)	Odometer:	7923 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$130,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,311.00	5,933.28	4,377.72	42.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,732.00	3,732.00	3,000.00	44.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,043.00	9,665.28	7,377.72	43.29
- Excess (S\$)	3,000.00	3,000.00	0.00	0.00
(S\$)	14,043.00	6,665.28	7,377.72	52.54
+ GST 7.00/7.00% (S\$)	983.01	466.57	516.44	52.54
Nett Amount (S\$)	15,026.01	7,131.85	7,894.16	52.54

INSPECTION

Date of Assignment:	11/09/2020		
Date Inspected:	11/09/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,698.00 FS	*2,158.40 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	454.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	220.00 FS	*176.00 FS
4	1		*REAR BUMPER SPOILER	Deformed	246.00 FS	*196.40 FS
5	1		*REAR BUMPER TRIM	Cracked	289.00 FS	*230.80 FS
6	2		*REAR BUMPER BRACKET - LH/RH	Not Necessary	230.00 FS	*- FS
7	2		*REAR LGHT REFLECTOR-LH/RH	Not Necessary	82.00 FS	*- FS
8	1		*REAR BUMPER CARRIER	Dented	1,002.00 FS	*801.60 FS
9	2		*REAR BUMPER CARRIER SEAL	Necessary	28.00 FS	*22.08 FS
10	2		*REAR BUMPER GUIDE SECTION - LH /RH	Not Necessary	44.00 FS	*- FS
11	2		*REAR BUMPER HOLDING STRAP LH/ RH	Not Necessary	164.00 FS	*- FS
12	2		*REAR PARKING AID SENSOR -INNER/ OUTER (NPA)	Not Necessary	0.00 FS	*- FS
13	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
14	1		*BOOT LID CONTROL UNIT	Not Necessary	399.00 FS	*- FS
15	1		*REAR LID	Dented	2,623.00 FS	*2,098.40 FS
16	2		*REAR LID HINGE - LH / RH	Not Necessary	452.00 FS	*- FS
17	1		*REAR LID LOCK	Not Necessary	227.00 FS	*- FS
18	1		*REAR LID ATTACHEMENT PARTS	Not Necessary	144.00 FS	*- FS
19	1		*REAR LID LOCK STRIKER	Not Necessary	33.00 FS	*- FS
20	1		*REAR LID FLAP GASKET	Not Necessary	203.00 FS	*- FS
21	1		*PACKING ADHESIVE	Necessary	18.00 FS	*14.40 FS
22	1		*AUDI EMBLEM	Necessary	122.00 FS	*97.60 FS
23	1		*A4 INSCRIPTION	Necessary	95.00 FS	*75.36 FS
24	1		*REAR CROSS PANEL TRIM	Not Necessary	164.00 FS	*- FS
25	1		*REAR NUMBER PLATE	Cut	60.00 FS	*60.00 FS
26	1		*SUNDRIES	Necessary	300.00 FS	*2.24 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 10,311.00 5,933.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESSFOR	New	280.00	280.00
3	TO DISMANTLE AND RENEW REAR BUMPER, REAR BUMPER SPOILER AND REAR LID. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	2,100.00	1,000.00
4	TO RESPRAY REAR BUMPER, REAR LID AND HINGES.	New	2,200.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
6	TO REPAIR REAR END PANELLING.	New	700.00	250.00
7	TO RESPRAY REAR END PANELLING.	New	900.00	550.00
Gross Labour Cost (\$\$)			6,732.00	3,732.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >