

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20009723/AQD3E2

Date: 07/05/2021

REFERENCE

Insured/Claimant: CHUA SWEE BOON (CAI RUIWEN) Policy No: 1700063199-02
Date of Loss: 07/09/2020 Nature of Claim: OD Claim No: 5033249469SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGH7637S**
Make & Model: AUDI A4, 1.4 (A) Engine No: CVN041412
Reg. Date: 11/10/2017 (Man. Year: 2017) Chassis No: WAUZZZF4XHA182059
Colour: Black Odometer: 34530 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$100,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,838.00	3,808.32	11,029.68	74.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,872.00	1,492.00	2,380.00	61.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,710.00	5,300.32	13,409.68	71.67
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	18,110.00	4,700.32	13,409.68	74.05
+ GST 7.00/7.00% (S\$)	1,267.70	329.02	938.68	74.05
Nett Amount (S\$)	19,377.70	5,029.34	14,348.36	74.05

INSPECTION

Date of Assignment: 11/09/2020
Date Inspected: 11/09/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,111.00 FS	*1,688.80 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	282.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	70.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	194.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Torn	208.00 FS	*166.00 FS
6	1		*RADIATOR AIR GUIDE - LH	Not Necessary	62.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cut	1,799.00 FS	*1,439.20 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	361.00 FS	*288.80 FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	795.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	123.00 FS	*98.40 FS
11	1		*FOAM FILLER PIECE COVER	Not Necessary	126.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	36.00 FS	*- FS
13	1		*LOCK CARRIER BRACKET	Not Necessary	136.00 FS	*- FS
14	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	56.00 FS	*- FS
15	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
16	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
17	1		*WHEEL SPOILER - LH	Torn	73.00 FS	*57.76 FS
18	1		*WHEEL SPOILER TRIM - LH	Not Necessary	35.00 FS	*- FS
19	1		*LED HEADLIGHT - LH	Not Necessary	7,693.00 FS	*- FS
20	1		*LIFT CYLINDER - LH	Not Necessary	208.00 FS	*- FS
21	1		*BONNET IMPACT PROTECTION - CENTRE	Not Necessary	27.00 FS	*- FS
22	1		*BONNET IMPACT PROTECTION - LH	Not Necessary	28.00 FS	*- FS
23	1		*BONNET IMPACT PROTECTION - RH	Not Necessary	27.00 FS	*- FS
24	1		*RADIATOR AIR GUIDE - LH	Not Necessary	28.00 FS	*- FS
25	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	16.00 FS	*- FS
26	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
27	1		*SUNDRIES	Necessary	250.00 FS	*9.36 FS
28	1		*RADIATOR AIR GUIDE - LH	Not Necessary	12.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 14,838.00 3,808.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			3,872.00	1,492.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >