

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EGI20009728/KTD3Q2

**Date:** 29/10/2020

### REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant**

**Vehicle No :** SHD5661T

**Insured Vehicle No :**

SKA5696Z

Date of Loss: 10/09/2020

Nature of Claim:

TP

Claim No: N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD5661T**

Make & Model: TOYOTA VIOS, 1.5 S (A)

Engine No: 2ZR2B51923

Reg. Date: 26/10/2018 (Man. Year: 2018)

Chassis No: JTDKB3FU403074051

Colour: Metallic Pearl White/Red

Odometer: 294992 km

Engine Capacity: 1798 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Sailun 9 mm

Rear Left Side:

Sailun 9 mm

Front Right Side: Sailun 9 mm

Rear Right Side:

Sailun 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,125.55	869.17	4,256.38	83.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	540.00	3,010.00	84.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>8,675.55</b>	<b>1,409.17</b>	<b>7,266.38</b>	<b>83.76</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	607.29	98.64	508.65	83.76
<b>Nett Amount (\$\$)</b>	<b>9,282.84</b>	<b>1,507.81</b>	<b>7,775.03</b>	<b>83.76</b>

### INSPECTION

Date of Assignment: 11/09/2020

Date Inspected: 11/09/2020

Inspected At:

Transcab (HQ)

NO 2 AMK STREET 63

Singapore 569111

Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$1,409.18

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Oct 2020)
<b>Parts:</b>	143	TOYOTA VIOS 1.5 S (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD5661T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Buckled	442.60 FL	*442.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Serviceable	332.70 FL	*- FL
3	1		*COVER ,REAR BUMPER ,LOWER	Serviceable	15.40 FL	*- FL
4	1		*GUARD ,REAR BUMPER ,CENTER	Dented / Cut	576.30 FL	*576.30 FL
5	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	117.70 FL	*- FL
6	1		*FILLER ,REAR BUMPER EXTENSION ,RH	Serviceable	123.70 FL	*- FL
7	1		*PANEL SUB-ASSY ,QUARTER RH	Repair	871.50 FL	*- FL
8	1		*LINER ,REAR WHEEL HOUSE ,RH	Serviceable	139.80 FL	*- FL
9	1		*SEAL ,REAR BUMPER SIDE ,RH	Serviceable	88.50 FL	*- FL
10	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
11	1		*SET REAR BUMPER CLIP	Necessary	75.00 FS	*75.00 FS
12	1		*REAR BUMPER PROTECTOR	Necessary	180.00 FS	*30.00 FS
13	1		*REAR WHEEL RIM	Serviceable	1,879.40 FS	*- FS
14	1		*REAR BUMPER RETAINER CLIP	Not Necessary	65.00 FS	*- FS
15	1		*REAR LICENCE PLATE WITH HOLDER	Serviceable	130.00 FS	*- FS
16	1		*REAR FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,802.60</b>	<b>1,123.90</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	677.05	254.73
<b>Total Parts (\$)</b>	<b>5,125.55</b>	<b>869.17</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,200.00	200.00
2	TO REMOVE AND REFIT OF REAR BUMPER FITTINGS,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	280.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
5	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
7	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,550.00</b>	<b>540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >