

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20009731/ATF3E2
Date: 14/01/2021

REFERENCE

Insured/Claimant: LIM ENG KIAT Policy No: 1900066968
Date of Loss: 26/08/2020 Nature of Claim: OD Claim No: 5875178196SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFZ8300Z**
Make & Model: AUDI Q5, 2.0 TFSI Quattro (A) Engine No: DAX049909
Reg. Date: 25/03/2019 (Man. Year: 2018) Chassis No: WAUZZZF5K2018545
Colour: Black Odometer: 21245 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$170,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,128.00	10,035.36	7,092.64	41.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,472.00	3,172.00	4,300.00	57.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,600.00	13,207.36	11,392.64	46.31
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	23,600.00	12,207.36	11,392.64	48.27
+ GST 7.00/7.00% (S\$)	1,652.00	854.52	797.48	48.27
Nett Amount (S\$)	25,252.00	13,061.88	12,190.12	48.27

INSPECTION

Date of Assignment: 11/09/2020
Date Inspected: 11/09/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,595.00 FS	*2,075.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	267.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	111.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	142.00 FS	*- FS
5	1		*FRONT SPOILER	Repair	754.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	171.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	574.00 FS	*458.80 FS
8	1		*FRONT BUMPER END CAP - LH	Not Necessary	91.00 FS	*- FS
9	1		*FRONT BUMPER SECURING STRIP - LH	Not Necessary	37.00 FS	*- FS
10	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	38.00 FS	*- FS
11	1		*FRONT FENDER - LH	Repair	1,411.00 FS	*- FS
12	1		*FRONT FENDER ATTACHMENTS PARTS	Not Necessary	66.00 FS	*- FS
13	1		*FRONT FENDER BRACKET - LH	Not Necessary	17.00 FS	*- FS
14	1		*FRONT FENDER BRACE - LH	Not Necessary	222.00 FS	*- FS
15	1		*WHEEL HOUSING LINER - LH	Not Necessary	275.00 FS	*- FS
16	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	38.00 FS	*- FS
17	1		*WHEEL SPOILER - LH	Cut	159.00 FS	*126.80 FS
18	1		*HEADLIGHT MOUNTING - LH	Not Necessary	117.00 FS	*- FS
19	1		*LED HEADLIGHT - LH	Not Necessary	7,931.00 FS	*6,344.80 FS
20	1		*LIFT CYLINDER - LH	Not Necessary	138.00 FS	*- FS
21	1		*FRONT WHEEL COVER - LH / RH	N/S Cut, O/S Necessary	1,250.00 FS	*1,000.00 FS
22	1		*SUNDRIES	Necessary	250.00 FS	*29.36 FS
23	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	474.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 17,128.00 10,035.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNES FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	2,400.00	500.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER AND BOTH WHEEL ARCH TRIMS	New	4,000.00	1,750.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			7,472.00	3,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >