

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20009737/UGS3Q2

**Date:** 05/05/2021

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
<b>Claimant Vehicle No :</b>	SJP6834T	<b>Insured Vehicle No :</b>	GBH8184J
Date of Loss:	05/09/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0001748

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP6834T		
Make & Model:	HYUNDAI AVANTE, 1.6 HD (A)	Engine No:	G4FC9U623809
Reg. Date:	31/03/2009 (Man. Year: 2009)	Chassis No:	KMH DU41BR9U719786
Colour:	White	Odometer:	432311 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,286.00	1,731.60	4,554.40	72.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	1,400.00	2,300.00	62.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,986.00</b>	<b>3,131.60</b>	<b>6,854.40</b>	<b>68.64</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,986.00</b>	<b>2,500.00</b>	<b>7,486.00</b>	<b>74.96</b>
<b>+ Car Rental (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>Nett Liability (S\$)</b>		<b>3,000.00</b>		

### INSPECTION

Date of Assignment:	11/09/2020	
Date Inspected:	11/09/2020 Inspected At:	Eco Automobile Claims & Repair Pte Ltd - Bartley Biz Center (HQ) 15 KAKI BUKIT ROAD 4, #01-53 BARTLEY BIZ CENTER Singapore 417808
Estimated Period of Repair:	4.0 days	

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Sep 2020)
<b>Parts:</b>	143	HYUNDAI AVANTE 1.6 HD (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJP6834T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	762.00 FL	*- FL
2	1		*REAR BUMPER RHS RETAINER	Not Necessary	98.00 FL	*- FL
3	1		*RHS FRONT FENDER	Dented / Bent	782.00 FL	*466.50 FL
4	1		*RHS FRONT FENDER INNER SHIELD	Not Necessary	182.00 FL	*- FL
5	1		*RHS FRONT DOOR	Dented / Bent	698.00 FL	*698.00 FL
6	1		*RHS FRONT DOOR BLACK TAPE	Necessary	65.00 FL	*65.00 FL
7	1		*RHS FRONT DOOR MOULDING	Not Necessary	110.00 FL	*- FL
8	1		*RHS FRONT DOOR WINDOW REGULATOR	Not Necessary	340.00 FL	*- FL
9	1		*RHS REAR DOOR WINDOW REGULATOR	Not Necessary	340.00 FL	*- FL
10	1		*RHS REAR DOOR BLACK TAPE	Necessary	65.00 FL	*65.00 FL
11	1		*RHS REAR DOOR MOULDING	Not Necessary	110.00 FL	*- FL
12	2		*RHS REAR DOOR HINGES	Not Necessary	176.00 FL	*- FL
13	1		*RHS REAR DOOR	Dented / Bent	870.00 FL	*870.00 FL
14	1		*RHS REAR FENDER	Repair	980.00 FL	*- FL
15	1		*RHS REAR FENDER INNER SHIELD	Not Necessary	182.00 FL	*- FL
16	1		*RHS REAR SHOCK ABSORBER	Not Necessary	560.00 FL	*- FL
17	1		*SET RHS REAR FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
18	1		*SET REAR BUMPER CLIPS	Not Necessary	60.00 FS	*- FS
19	1		*REAR WINDSCREEN MOULDING	Not Necessary	180.00 FS	*- FS
20	1		*REAR WINDSCREEN SEAL	Not Necessary	80.00 FS	*- FS
21	1		*RHS REAR RIM	Repair	850.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,550.00</b>	<b>2,164.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,264.00	432.90
<b>Total Parts (\$\$)</b>	<b>6,286.00</b>	<b>1,731.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS	New	1,400.00	400.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS	New	1,400.00	800.00
3	TO REMOVE ,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER ELECTRICAL FUNCTION	New	150.00	20.00
4	TO REMOVE AND REFIX FRONT AND REAR DOOR COMPONENT	New	240.00	100.00
5	TO REMOVE AND REPLACE RIM	New	100.00	0.00
6	TO REMOVE AND REFIX REAR WINDSCREEN	New	150.00	0.00
7	TO REMOVE AND REPLACE REAR RHS UNDERCARRIAGE	New	140.00	0.00
8	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	120.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,700.00</b>	<b>1,400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >