

(08/11/13) wef
ASS. REC. BY: Marcus

REF: CC4/11/20009737/UGS3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SJP 68347
at Workshop m/s Eco
of _____
Insured: GBH 81847
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____


(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 435
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____



Vehicle: IN / OUT

Veh No: SJP68347 Yr Regn: 31/3/09
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or 41
Make: Hyundai Avante c.c 1591
Colour: White A/C: Insured / Std / NI / NA
Sp. Reading: 432311 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: KMHDU41BR9U719786
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/65R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Finanza
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 5/9/20 D.O.I. 11/9/20
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
0/5 Body
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

col 30-3-2029 21A21819
wks have video.

21/9/20 1/5 2500 confirmed work Repaired

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$) ☐ S + RS, SI
☐ : Interview (\$) Photos
☐ : Tech. Invs (\$) Others
☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

ECO Automobile Claims & Repair Pte Ltd
 15 Kaki Bukit Road 4 #01-53
 Bartley Biz Centre S417808
 T: 6384 7515
 E: ecoautoclaims@gmail.com
 Co. Reg No. 201632730M

*N. + Authored
 dan
 2/5 2500/
 11/9/20
 4 days.*

M. Cecilie



Vehicle No. JIP6834T DOA 05/09/20 (Hyundai Avante)

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR
	<u>PARTS (LIST ITEMS)</u>			
1	Rear bumper		<i>12</i> 762.00	<i>X</i>
1	Rear bumper RHS retainer		<i>11</i> 98.00	<i>X</i>
1	RHS front fender <i>466.50</i>		<i>20/200</i> 782.00	<i>X</i>
1	RHS front fender inner shield		<i>11</i> 182.00	<i>X</i>
1	RHS front door		<i>20/200</i> 698.00	<i>X</i>
1	RHS front door black tape		<i>11</i> 65.00	<i>X</i>
1	RHS front door moulding		<i>11</i> 110.00	<i>X</i>
1	RHS front door window regulator		<i>11</i> 340.00	<i>X</i>
1	RHS rear door window regulator		<i>11</i> 340.00	<i>X</i>
1	RHS rear door black tape		<i>11</i> 65.00	<i>X</i>
1	RHS rear door moulding		<i>11</i> 110.00	<i>X</i>
2	RHS rear door hinges @\$88		<i>11</i> 176.00	<i>X</i>
1	RHS rear door		<i>20/200</i> 870.00	<i>X</i>
1	RHS rear fender		<i>11</i> 980.00	<i>X</i>
1	RHS rear fender inner shield		<i>11</i> 182.00	<i>X</i>
1	RHS rear shock absorber		<i>11</i> 560.00	<i>X</i>
			6320.00	
		less 20%	1264.00	20%
			5056.00	
	SPECIAL NETT ITEM			
1set	RHS rear fender inner shield clips		<i>11</i> 60.00	<i>X</i>
1set	Rear bumper clips		<i>11</i> 60.00	<i>X</i>
1	Rear windscreen moulding		<i>11</i> 180.00	<i>X</i>
1	Rear windscreen seal		<i>11</i> 80.00	<i>X</i>
1	RHS rear rim		<i>11</i> 850.00	<i>X</i>
	Total Parts		6286.00	

ECO Automobile Claims & Repair Pte Ltd
 15 Kaki Bukit Road 4 #01-53
 Bartley Biz Centre S417808
 T: 6384 7515
 E: ecoautoclaims@gmail.com
 Co. Reg No. 201632730M



Vehicle No. SJP6834T DOA 05/09/20 (Hyundai Avante)

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR
	LABOUR		
1	To remove the affected parts & fittings to commence repairs, replace damaged parts	1400.00	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	1400.00	800
3	To remove, refix wiring system at accident damaged areas and check for proper electrical function	150.00	20
4	To remove and refix front and rear door component	240.00	100
5	To remove and replace rear rim	100.00	11 X
6	To remove and refix rear windscreen	150.00	11 X
7	To remove and replace rear RHS undercarriage	140.00	11 X
8	To perform anti-rust treatment on affected areas	120.00	80
Labour Total :		3700.00	
TOTAL (PARTS & LABOUR):		9986.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P- 2164.50
 200
 P- 1731.60
 L- 1400.00
 3131.60
 200
 2505.