3/18/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG20009738/QPA3Q2

Date:

18/03/2021

REFERENCE

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800062546

Claimant Vehicle No :

SHC4655Z

Insured Vehicle No:

SKF2517B

Date of Loss:

08/09/2020

Nature of Claim:

TP

Claim No: 1342674426SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHC4655Z

Make & Model:

TOYOTA PRIUS TAXI, 1.8 (A) 19/09/2014 (Man. Year: 2014)

Engine No: Chassis No: Odometer: 2ZR6157814

402609 km

JTDKN36U605750656

Reg. Date: 19/09/20 Colour: Maroon

Engine Capacity:

1798 cc N/A

Market Value/New Car Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes I

Footbrake (Serviceable): Yes

Handbrake (Serviceable):

Yes Engine Modification:

No

Pre-accident Condition:

195/65 R15

CONDITION OF TYRES

Front Tyre Size:
Front Left Side:
Front Right Side:

195/65 R15 Firenza 6 mm Firenza 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side:

Firenza 6 mm Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		13,803.87	3,446.49	10,357.38	75.03
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,478.00	1,400.00	3,078.00	68.74
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	18,281.87	4,846.49	13,435.38	73.49
	Approved Total (Overridden) (S\$)		4,200.00		
	Nett Amount (S\$)	18,281.87	4,200.00	14,081.87	77.03
	+ Loss of Use (5.0 x S	\$50.00/day) (S\$)	250.00		
	+ Car Rental (5.0 x S\$1	I09.14/day) (S\$)	545.70		
	+ Doc/s	Search Fee (S\$)	7.00		
	N	ett Liability (S\$)	5,002.70		
	Global Sum Settlement (S\$)		5,000.00		

INSPECTION

Date Inspected:

Date of Assignment:

08/09/2020

08/09/2020 Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair:

4.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printrpt&caseid=956930&extid=344135&CFID=82863847&C... 1/4

OI SUN PIN CHEW HSIAO TONG Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*MOULDING BODY ,LH (DISC 25%)	Crumpled	673.60 F	*505.20 F
2	1	*SILL MEMBER PLATE RR/LH (DISC 25%)	Crumpled	57.50 F	*43.13 F
3	1	*DOOR RR/LH (DISC 25%)	Crumpled	954.50 F	*715.88 F
4	1	*FENDER RR/LH (DISC 25%)	Crumpled	766.80 F	*575.10 F
5	1	*QUARTER GLASS RR/LH (DISC 25%)	Necessary	168.10 F	*126.08 F
6	1	*DOOR WEATHER STRIP RR/LH (DISC 25%)	Crumpled	171.20 F	*128.40 F
7	1	*DOOR REAR LH TRIM BOARD (DISC 25%)	Cracked	590.10 F	*442.58 F
8	1	*DOOR LOCK RR/LH (DISC 25%)	Cracked	709.30 F	*531.98 F
9	1	*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F
10	1	*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
11	1	*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
12	1	*SEALANT W/SCREEN (SN)	Necessary	37.00 F	*37.00 F
13	1	*TYRE (SN)	Cut	126.74 F	*126.74 F
14	1	*SOLAR FILM (SN)	Necessary	125.00 F	*125.00 F
15	1	*SILL MEMBER OUTER LH	Serviceable	519.80 F	*- F
16	1	*HINGE LOWER LHR ,DOOR	Serviceable	72.20 F	*- F
17	1	*HINGE UPPER LHR ,DOOR	Serviceable	81.70 F	*- F
18	1	*CHECK ASSY ,RR DOOR	Serviceable	150.30 F	*- F
19	1	*DOOR BELT RR /LH	Serviceable	69.20 F	*- F
20	1	*DOOR LOCK RR/LH	Serviceable	709.30 F	*- F
21	1	*DOOR LOCK STRIKER	Serviceable	40.50 F	*- F
22	1	*DOOR REAR LH TRIM BOARD	Serviceable	590.10 F	*- F
23	1	*DOOR WEATHERSTRIP RR/LH	Serviceable	171.20 F	*- F
24	1	*WEATHERSTRIP ,REAR DOOR OPENING TRIM LH	Serviceable	249.80 F	*- F
25	1	*FENDER LINER RR/LH	Serviceable	141.30 F	*- F
26	1	*TYRE	Serviceable	126.74 F	*- F
27	1	*WHEEL HUB REAR	Serviceable	489.40 F	*- F
28	1	*REAR CROSS MEMBER	Serviceable	2,621.50 F	*- F
29	1	*SHOCK ABSORBER REAR	Serviceable	112.30 F	*- F
30	1	*BUSH ,RR CROSS MEMBER	Serviceable	148.50 F	*- F
31	1	*PANEL QUARTER WHEEL HOUSE OUTER LH	Serviceable	326.70 F	*- F
32	1	*PIPE SUB ASSY ,FUEL NECK	Serviceable	230.80 F	*- F
33	1	*TUBE FUEL TANK	Serviceable	36.10 F	*- F
34	1	*SCUFF PLATE ,RR DOOR LH	Serviceable	153.20 F	*- F
35	1	*SCUFF STEP PLATE LH RR DR	Serviceable	107.49 F	*- F
36	1	*BUMPER REAR	Serviceable	458.60 F	*- F
37	1	*BUMPER SEAL ,RR LH	Serviceable	88.90 F	*- F
38	1	*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F
39	1	*PIXEL STICKER	Serviceable	60.00 F	*- F
40	1	*WHEEL ,DISC	Repair	1,484.20 F	*- F
F=Fr	anchise part.		_		
			Total Parts (S\$)	13,803.87	3,446.49

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING & BODY WORK	New	1,014.00	600.00
2	SPRAY PAINT	New	1,854.00	550.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	30.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
6	TO REMOVE/REFIT SEAT	New	120.00	0.00
7	TO REMOVE & REFIT FUEL TANK	New	120.00	0.00
8	TO TRANSFER DOOR MECHANISM	New	120.00	60.00
9	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	0.00
10	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	20.00
11	TO REMOVE AND REFIX UNDERCARRIAGE	New	250.00	0.00
12	TO REPLACE SUNDRY PARTS	New	100.00	0.00
13	TO WASH AND VACUUM	New	60.00	0.00
14	TO REMOVE & REFIT REAR QUARTER GLASS LH	New	120.00	60.00
15	TO REMOVE & REFIT REAR QUARTER GLASS LH	New	180.00	0.00
	Gross I	4,478.00	1,400.00	

Report was unsubmitted during this print-out.

< END OF ESTIMATES >