Correspondence Address: 1 Simei St.3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0100120

Date of Report

: 21/02/2020

To: M/s. Chang Zheng Auto Agency

C/o. 19 Kim Chuan Terrace Singapore 537041

Date of Assignment Report requested by : 07/01/2020

: M/s. Chang Zheng Auto Ager

Date of Accident

: 04/01/2020

Date of Inspection Claim No.

: 07/01/2020

Third Party Claim

Policy No.

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.

: SJW4189Z

: Toyota Corolla Altis

: 17/03/2009

Engine Capacity (cc) : 1598cc

Mileage (km) Chassis / Frame No. : MR053ZEE106141348

: 243904km

: Met. Blue

Engine No.

: 3ZZ4869511

TYRE CONDITION

Date of Registration

Make & Model

Colour

Front LH

: 7 mm

: 7 mm

Front RH

: 7 mm : CST Tires

Make

: CST Tires

Make Rear RH

: 7 mm

Rear LH Make

: CST Tires

Make

: CST Tires

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork

: Good

Paintwork

: Good

Handbrake

: Serviceable

: Serviceable

Footbrake

Steering

: Serviceable

Apparent Engine Modification

: Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location

M/s. Wee Hoe Auto Service

19, Kim Chuan Terrace, Singapore 537041

ASSESSMENT

Repairer's Estimate

Recommended Reserve

13,967.38 : \$

Revised Amount

: \$ 12,350.20

Less Excess

: \$: \$

9,880.00 (Lump Sum)

Estimated Normal Period of Repairs

: 10 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited. Page 1 of 4

Correspondence Address: 1 Simei St.3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No: SJW4189Z

Report No.: PAS/TP/0100120

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Wee Hoe Auto Service, 19, Kim Chuan Terrace, Singapore 537041.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the front portion.

DAMAGES

The bonnet, front bumper, front support panel, front chassis members, front fenders, RHF apron panel, RHF wheel house, radiator assy, a/c condenser, headlamps, front grilles, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$12,350.20.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$9,880.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How

Automobile Appraiser

MSAAA

Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers Correspondence Address: 1 Simel St 3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com Business Reg. 201404434D

Vehicle No: SJW4189Z

Report No.: PAS/TP/0100120

APPRAISEMENT SCHEDULE

S/No. Qty		Parts Descriptions	Condition		Repairer's Estimate (S\$)			Our Assessment (S\$)	
1.	1 pc	Bonnet / c RY	Dented			¢	952.20	¢.	853.20 57
2		Bonnet seal / Nec	Torn/Necessary			-\$ \$	853.20	\$	
3		Bonnet insulator × Svc	Refit				59.60	\$	59.60
4		Bonnet insulator clip X \$VC	Necessary	\$	2.50	\$ \$	266.40	\$	17.50
5		Bonnet hinge R/L	Bent	\$	59.70		17.50	\$	17.50
6		Frt support panel / 0b	Dented	Φ	39.70	\$ \$	119.40	\$	119.40 X
7	_	Frt support brace panel BT	Dented/Bent			\$	715.30	\$	715.30608
8		Bonnet lock Jam	Dented/Jammed		543.9	\$	114.30	\$	114.30
		Headlamp R/L LH/CRA	Cracked/Broken	\$	709-10		129.30	\$	129.30
10		Frt bumper / bp	Dented Dented	Φ	700.40	\$	1,416.80	\$	1,416.80 543
11		Frt grille CQ4	Dented/Cracked			\$	458.40	\$	458.40
12		Frt grille emblem /Nec				\$	301.90	\$	301.90269
13	-	Frt bumper lower grille / 1/14	Necessary			\$	71.00	\$	71.00
.4		Frt bumper clip / Ne C	Cracked	dr.	2.50	\$	147.10	\$	147.10
5		Frt bumper retainer R/L/BR	Necessary Cracked/Necessary	\$	3.50	\$	21.00	\$	21.00
.6		Frt bumper reinforcement	Cracked/Necessary	\$	54.60	\$	109.20	\$	109.20
.7	_	Frt bumper arm R/L XSVC	Dented	ф	10.60	\$	341.10	\$	341.10
.8		Frt bumper top seal XIVC	Dented	\$	18.60	\$	37.20	\$	37.20 ×
9			Torn/Necessary			\$	51.90	\$	51.90
9		Frt fog lamp R/L KSVC Frt fog lamp cover R/L XSVC	Refit	\$	238.40	\$	476.80	\$	-
			Refit	\$	61.50	\$	123.00	\$	
		Frt fender R/L R4/00	Dented/Distorted	\$	6 16.9 0	\$	1,233.80	\$	1,233.80410
		Frt fender cowling R/L Rh/cRu	Torn/Deformed	\$	169.20	\$	338.40	\$	338.40 69.
		Frt fender cowling clip R/L RH/N		\$	3.20	\$	38.40	\$	38.40 9.2
		Frt fender emblem (VVTi) R/L Nec		\$	41.70	\$	83.40	\$	83.40 41.70
5		Frt apron panel RH X R	Dented/Distorted			\$	491.20	\$	491.20 ×
6	-	Radiator / cRu	Dented			\$	1,965.80	\$	1,965.80/,80
7		Radiator top bracket / BR	Dented/Broken			\$	96.30	\$	96.30
8		Radiator cooling fan blade	Dented/Cracked			\$	147.20	\$	147.20
9		Radiator cooling fan motor	Dented/Damaged			\$	537.90	\$	537.90 入 _
0	1 pc	Radiator cooling fan cowling (Ru	Dented/Broken			\$	83.40	\$	83.40
1		Radiator reserve tank	Refit			\$	155.60	\$	-
2	1 pc	A/c condenser / CR u	Dented			\$	1,473.60	\$	1,473.60 1.2 4
3	1 pc	A/c suction pipe x svc	Refit			\$	132.90	\$	/
4	1 pc	A/c discharge pipe	Refit			\$	248.30	\$	-
5		A/c liquid pipe × svc	Dented/Bent			\$	236.60	\$	236.60
6		Horn XSVC	Dented/Damaged			\$	63.40	\$	63.40
7		Washer tank XSVC	Refit			\$	119.90	\$	
8		Frt wheel house RH 💢 🏌	Dented/Repair					r labour no.	5, 6 & 7)
9	1 pc	Frt chassis member R/L × R	Dented/Repair					r labour no.	
0	1 pc	Frt door RH × R	Dented/Repair					fer labour 1	no. 6 & 7)
						\$	13,276.50	\$	7, 5
				Less I	Discount: 25%	\$	3,319.13	25% \$	2,938.40
			List	Parts Su	ıb-Total:	\$	9,957.38	\$	8,815.20
		Frt no.plate (w/bracket) / BR	Dented/Cracked		S/N	\$	50.00	\$	50.00
2		Radiator coolant / Nec	Necessary		S/N	\$	60.00	\$	60.00
,	1 pc	Frt apron panel sealant RHXVC	Necessary		S/N	\$	50.00	\$	40.00
								•	8,965.20



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers Correspondence Address: 1 Simei St.3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email: pasves@hotmail.com

Business Reg. 201404434D

Vehi	cle No : SJW4189Z		Report No	. : PAS/T	P/0100120
S/No	. Labour Descriptions	Repairer's Estimate (S\$)		Our Assessment (S\$)	
1	Towing.	\$	100.00	\$	85.00 50
2	To check electrical system, repair wire harness and focus headlamp.	\$	60.00	\$	50.0030
3	To remove, replace and reinstall a/c condenser & a/c pipings. (Include vacuum & recharge a/c gas)	\$	120.00	\$	120.00 80
4	To remove, replace and reinstall radiator & cooling system. (Include pressure test cooling system)	\$	100.00	\$	80.00 50
5	To conduct chassis alignments.	\$	320.00	\$	300.00
6	To straighten, repair, realign on affected area and replace damaged parts.	\$	1,500.00	\$	1,320.00 1,000
7	To spray painting, blending on affected and adjacent area.	\$	1,600.00	\$	1,320.00),000 1,400.00),100
8	To spray anti-rust coating on new and affected panels.	\$	50.00	\$	30.00
	Labour Total:	\$	3,850.00	\$	3,385.00
	Total (Parts & Labour):	\$	13,967.38	\$ 1	2,350.20

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 9,880.00

Under normal circumstances, the repairs should be completed within a reasonable period

of 10 Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

64 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Repuir	day	6 days	7,500.40 - 259. P= 5,625.68 N= 110 1= 2,340 - 8,075.68 - 209. - 6,460.54	45 \$6,450 6days
--------	-----	--------	---	------------------------

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.