

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20009745/T1VD3E2

Date: 22/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2100414050
<b>Claimant Vehicle No :</b> FBL8139U	<b>Insured Vehicle No :</b> SKT1891C
Date of Loss: 01/07/2020	Nature of Claim: TP Claim No: 0516104995SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBL8139U</b>	Engine No:	HIDDEN
Make & Model:	YAMAHA XABRE, 150cc TFX150	Chassis No:	HIDDEN
Reg. Date:	(Man. Year: )	Odometer:	0 km
Colour:	Red/Black		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	140/70 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	11/09/2020	Inspected At:	M1 Motoring (HQ)
Date Inspected:	11/09/2020		411 Changi Road
			Singapore 419860
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CLUTCH LEVER	Bent	0.00 F	*- F
2	1		*LH HANDLEBAR BALANCER	Missing	0.00 F	*- F
3	1		*LH WING MIRROR	Cut	0.00 F	*- F
4	1		*HANDLEBAR	Bent	0.00 F	*- F
5	1		*LH HANDLEBAR SWITCH	Distorted	0.00 F	*- F
6	1		*FRT LH FOOTREST	Dented	0.00 F	*- F
7	1		*REAR LH FOOTREST	Dented	0.00 F	*- F
8	1		*REAR SIDE LH FENDER	Cut	0.00 F	*- F
9	1		*REAR LH SIGNAL LIGHT	Cut	0.00 F	*- F
10	1		*REAR EXHAUST HEAT SHIELD	Cut	0.00 F	*- F
11	1		*REAR EXHAUST ASSY	* Check	0.00 F	*- F
					<b>Total Parts (\$\$)</b>	<b>0.00 0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**