

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20009760/UBA3Q2
Date: 07/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLA8808L	Insured Vehicle No :	SH6533Y
Date of Loss:	29/08/2020	Nature of Claim:	TP
		Claim No:	MCT20080464

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA8808L	Engine No:	PE21004281
Make & Model:	MAZDA 6, 2.0 SEDAN EXECUTIVE EU6 (A)	Chassis No:	JM6GL1071J0133072
Reg. Date:	31/01/2018 (Man. Year: 2017)	Odometer:	52190 km
Colour:	Red		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,607.50	1,989.20	1,618.30	44.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,025.00	2,390.00	3,635.00	60.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,632.50	4,379.20	5,253.30	54.54
+ GST 7.00/7.00% (\$\$)	674.28	306.54	367.74	54.54
Nett Amount (\$\$)	10,306.78	4,685.74	5,621.04	54.54
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (\$\$)		321.00		
Nett Liability (\$\$)		5,006.74		

INSPECTION

Date of Assignment:	11/09/2020	
Date Inspected:	11/09/2020	Inspected At:
		Trans Eurokars Pte Ltd (Ubi)
		5 Ubi Close
		Singapore 408605
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

4/7/2021

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Mar 2021)

Parts: 143 MAZDA 6 2.0 SEDAN EXECUTIVE EU6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLA8808L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,266.60 F	*1,266.60 F
2	1		*BRACKET CENTER	Not Necessary	5.40 F	*- F
3	4		*GROMMET ,REAR BUMPER	Necessary	10.80 F	*10.80 F
4	6		*FASTENER ,REAR BUMPER	Necessary	18.00 F	*18.00 F
5	2		*GROMMET ,REAR BUMPER	Necessary	6.00 F	*6.00 F
6	4		*CLIP ,REAR BUMPER	Necessary	14.80 F	*14.80 F
7	4		*TAPE PROTECTOR ,REAR BUMPER	Necessary	34.40 F	*34.40 F
8	1		*RETAINER CENTER LHS ,SENSOR	Not Necessary	18.20 F	*- F
9	1		*SENSOR CENTER LHS ,ULTRASONIC	Not Necessary	180.90 F	*- F
10	1		*BOOTLID	Not Necessary	1,115.00 F	*- F
11	2		*GROMMET ,BOOTLID	Not Necessary	6.60 F	*- F
12	1		*GASKET LHS ,TAILLAMP	Necessary	27.70 F	*27.70 F
13	1		*GASKET RHS ,TAILLAMP	Necessary	27.70 F	*27.70 F
14	1		*GASKET LHS ,BOOTLID	Not Necessary	49.20 F	*- F
15	1		*GASKET RHS ,BOOTLID	Not Necessary	49.20 F	*- F
16	1		*ANTENNA	Not Necessary	111.10 F	*- F
17	1		*CLIP ,ANTENNA	Not Necessary	2.70 F	*- F
18	1		*REAR REINFORCEMENT	Dented	538.30 F	*538.30 F
19	1		*TOWING COVER LHS	Missing	24.90 F	*24.90 F
20	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **3,607.50** **1,989.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER ,REAR REINFORCEMENT AND BOOT LID ,REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	2,310.00	660.00
2	TO RESPRAY REAR BUMPER ,REAR REINFORCEMENT AND BOOT LID	New	2,205.00	1,260.00
3	TO TRANSFER REVERSE SENSORS	New	330.00	200.00
4	TO TRANSFER REVERSE CAMERA	New	330.00	0.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
6	TO CARRY -OUT BODY CAVITY PRESERVATION	New	250.00	0.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	150.00
Gross Labour Cost (\$\$)			6,025.00	2,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >