

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20009762/R1PA3Q2

**Date:** 30/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700050069

**Claimant**  
**Vehicle No :** SMP99C **Insured Vehicle No :** SFD3A

Date of Loss: 06/09/2020 Nature of Claim: TP Claim No: 8911495960SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP99C		
Make & Model:	FERRARI PORTOFINO, 3.9 (M)	Engine No:	462825
Reg. Date:	04/02/2020 (Man. Year: 2019)	Chassis No:	ZFF89FPC000250153
Colour:	Yellow	Odometer:	3730 km
Engine Capacity:	3855 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	245/35 ZR20	Rear Tyre Size:	245/35 ZR20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,685.99	26,811.84	-125.85	-0.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,190.00	15,800.00	4,390.00	21.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>46,875.99</b>	<b>42,611.84</b>	<b>4,264.15</b>	<b>9.10</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>3,281.32</b>	<b>2,982.83</b>	<b>298.49</b>	<b>9.10</b>
<b>Nett Amount (S\$)</b>	<b>50,157.31</b>	<b>45,594.67</b>	<b>4,562.64</b>	<b>9.10</b>
<b>+ Loss of Use (6.0 x S\$200.00/day) (S\$)</b>		<b>1,200.00</b>		
		<b>Nett Liability (S\$)</b>	<b>46,794.67</b>	

### INSPECTION

Date of Assignment: 11/09/2020

Date Inspected: 15/09/2020

Inspected At:

ITAL Auto Pte Ltd (HQ)  
30 Leng Kee Road  
Singapore 159100

Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD RASUL

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ENGINE INTAKE DUCT	Cracked	600.65 FS	*600.65 FS
2	1		*COMPL. FRONT BUMPER	Cracked	22,825.17 FS	*22,825.17 FS
3	1		*PRANCING HORSE BADGE MOUNT	Necessary	16.84 FS	*16.84 FS
4	1		*LH CENTRE SENSOR MOUNT	Deformed	48.05 FS	*48.05 FS
5	1		*BUMPER GRILLE	Cracked	2,548.53 FS	*2,548.53 FS
6	4		*NUT	Necessary	2.74 FS	*10.96 FS
7	1		*FRONT ORNAMENT	Necessary	471.11 FS	*471.11 FS
8	4		*SCREW	Necessary	38.44 FS	*153.76 FS
9	2		*NUT	Necessary	2.31 FS	*4.62 FS
10	1		*CAVALLINO RAMPANTE BADGE	Necessary	132.15 FS	*132.15 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **26,685.99**      **26,811.84**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REPLACE FRONT BUMPER, BUMPER GRILLE AIR DUCTS, REMOVING & RESECURING FRONT AIR DUCTS, HEADLIGHTS AND RADIATOR AND FRONT PARTS FOR ALIGNMENT	New	13,440.00	9,600.00
2	SPRAY PAINTING FRONT BUMPER	New	3,750.00	3,500.00
3	DIAGNOSTIC TEST, FRONT BUMPER STICKER	New	3,000.00	2,700.00
<b>Gross Labour Cost (\$\$)</b>			<b>20,190.00</b>	<b>15,800.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**