

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20009777/AVF3E2

Date: 09/06/2021

REFERENCE

Insured/Claimant:	PREMIUM AUTOMOBILES PTE LTD	Policy No:	0999993763	
Date of Loss:	06/09/2020	Nature of Claim:	OD	Claim No: 9964711524SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN9189C	Engine No:	CHH310224
Make & Model:	AUDI TT, 2.0 COUPE (A)	Chassis No:	TRUZZZFV9K1009836
Reg. Date:	30/08/2019 (Man. Year: 2019)	Odometer:	17640 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$190,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,727.44	25,004.24	13,723.20	35.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,572.00	8,472.00	4,100.00	32.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	51,299.44	33,476.24	17,823.20	34.74
- Excess (S\$)	3,000.00	3,000.00	0.00	0.00
(S\$)	48,299.44	30,476.24	17,823.20	36.90
+ GST 7.00/7.00% (S\$)	3,380.96	2,133.34	1,247.62	36.90
Nett Amount (S\$)	51,680.40	32,609.58	19,070.82	36.90

INSPECTION

Date of Assignment:	14/09/2020		
Date Inspected:	11/09/2020	Inspected At:	24 BENOI SECTOR Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	14.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	3,032.00 FS	*2,425.60 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	480.00 FS	*- FS
3	1	*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	110.00 FS	*- FS
4	1	*WHEEL HOUSING LINER SECURING STRIP - LH	Not Necessary	43.00 FS	*- FS
5	1	*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	268.00 FS	*- FS
6	1	*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	248.00 FS	*198.00 FS
7	1	*WHEEL HOUSING LINER ADAPTER - LH	Not Necessary	70.00 FS	*- FS
8	1	*FRONT BUMPER GUIDE SECTION - LH	Damaged	38.00 FS	*30.16 FS
9	1	*FRONT PARKING AID SENSOR - OUTER (NPA)	Not Necessary	0.00 FS	*- FS
10	1	*FRONT FENDER - LH	Dented	1,174.00 FS	*939.20 FS
11	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	40.00 FS	*- FS
12	1	*FRONT FENDER BRACE - LH	Bent	117.00 FS	*93.60 FS
13	1	*FRONT FENDER BRACKET - UPPER CENTRE	Bent	43.00 FS	*34.08 FS
14	1	*FRONT FENDER BRACKET - LH LOWER	Not Necessary	46.00 FS	*- FS
15	1	*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	53.00 FS	*- FS
16	1	*FRONT FENDER BRACKET - LH UPPER	Bent	52.00 FS	*41.36 FS
17	1	*WHEEL HOUSING LINER SEAL - LH	Not Necessary	37.00 FS	*- FS
18	1	*WHEEL HOUSING LINER - LH	Deformed	255.00 FS	*204.00 FS
19	1	*WHEEL HOUSING LINER - LH (SPOILER)	Cracked	116.00 FS	*92.80 FS
20	1	*BONNET	Dented	4,292.00 FS	*3,433.60 FS
21	1	*BONNET ATTACHMENT PARTS	Not Necessary	101.00 FS	*- FS
22	2	*BONNET LID HINGE - LH / RH	Not Necessary	678.00 FS	*- FS
23	2	*BONNET IMPACT PROTECTION - LH / RH	Necessary	100.00 FS	*79.84 FS
24	1	*BONNET EDGE PROTECTION	Necessary	30.00 FS	*23.76 FS
25	1	*BONNET SEAL - LH	Not Necessary	45.00 FS	*- FS
26	1	*FRONT FENDER SEAL - LH	Not Necessary	61.00 FS	*- FS
27	1	*WHEEL HOUSING LINER ADAPTER - LH	Not Necessary	63.00 FS	*- FS
28	2	*BONNET STRIKER - LH / RH	Not Necessary	204.00 FS	*- FS
29	2	*BONNET LID LOCK	Not Necessary	388.00 FS	*- FS
30	1	*BONNET SOUND ABSORBER	Not Necessary	314.00 FS	*- FS
31	1	*PLENUM CHAMBER COVER	Not Necessary	197.00 FS	*- FS
32	1	*LED HEADLIGHT - LH	Cut	7,836.00 FS	*6,268.80 FS
33	1	*LIFT CYLINDER - LH	Not Necessary	157.00 FS	*- FS
34	1	*WASH WATER RESERVOIR	Not Necessary	218.00 FS	*- FS
35	1	*FRONT ALUMINIUM RIM - LH	Cut	1,012.00 FS	*809.60 FS
36	1	*WISHBONE	Bent	825.00 FS	*659.60 FS
37	1	*STABILIZER BAR	Not Necessary	384.00 FS	*- FS
38	1	*WHEEL BEARING HOUSING - LH	Damaged	957.00 FS	*765.20 FS
39	1	*WHEEL BEARING	Damaged	462.00 FS	*369.20 FS
40	1	*BALL JOINT - LH	Bent	179.00 FS	*143.20 FS
41	1	*RETAINING PLAT - LH	Not Necessary	31.00 FS	*- FS
42	1	*COUPLING ROD	Not Necessary	93.00 FS	*- FS
43	1	*GAS SHOCK ABSORBER	Bent	347.00 FS	*277.60 FS
44	1	*DRIVE SHAFT - LH	Not Necessary	2,267.00 FS	*- FS
45	1	*TRACK ROD	Not Necessary	98.00 FS	*- FS
46	1	*TIE ROD END - LH	Not Necessary	148.00 FS	*- FS
47	1	*FRONT SUBFRAME	Bent	972.00 FS	*777.20 FS
48	1	*SUB FRAME BUSHES	Damaged	165.00 FS	*132.00 FS
49	2	*SEATBELT	N/S Activated / O/S Cut	2,182.00 FS	*1,745.60 FS
50	2	*SPACER SLEEVE	Not Necessary	44.00 FS	*- FS
51	4	*SEAT BELT LOOP - AROUND FITTINGS - LH / RH	N/S Cracked	260.00 FS	*103.52 FS
52	2	*SEAT BELT GUIDE TRIM PLATE - LH / RH	Not Necessary	68.00 FS	*- FS
53	1	*AIRBAG CRASH SENSOR	Activated	139.44 FS	*139.44 FS

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
54	1	*AIRBAG CONTROL UNIT	Activated	1,711.00 FS	*1,368.80 FS
55	1	*CENTRAL PROTECTION	Not Necessary	527.00 FS	*- FS
56	1	*FRONT TYRE - LH	Cut	320.00 FS	*320.00 FS
57	2	*C-PILLAR TRIM - LH / RH	Cracked	438.00 FS	*351.60 FS
58	1	*SUNDRIES	Necessary	300.00 FS	*84.40 FS
59	1	*C-PILLAR INNER TRIM BOARD LHS (Supplementary)	Cut	830.00 FS	*663.60 FS
60	1	*C-PILLAR INNER TRIM BOARD RHS (Supplementary)	Cut	830.00 FS	*663.60 FS
61	1	*REAR SEATBELT RHS (Supplementary)	Activated	1,091.00 FS	*872.80 FS
62	1	*REAR SEATBELT LHS (Supplementary)	Activated	1,091.00 FS	*872.80 FS
63	1	*TRIM PLATE ON C-PILLAR INNER TRIM BOARD LHS (Supplementary)	Cut	25.00 FS	*19.68 FS
64	1	*TRIM PLATE ON C-PILLAR INNER TRIM BOARD RHS (Supplementary)	Not Necessary	25.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 38,727.44 25,004.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	280.00	280.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY	New	350.00	0.00
4	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	1,800.00	1,800.00
5	TO DISMANTLE AND REINSTALL CENTRE CONSOLE. RENEW AIRBAG CONTROL UNIT AND BOTH FRONT SEATBELT	New	1,800.00	1,800.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,500.00
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, HINGES AND LHS FRONT DOOR	New	4,000.00	1,650.00
8	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT	New	520.00	520.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
10	TO REMOVE AND RENEW BOTH UPPER C-PILLAR TRIM AND BOTH C-PILLAR INNER TRIM BOARDS TO FACILITATE RENEWAL OF BOTH REAR SEATBELT ASSY. (Supplementary)	New	480.00	480.00
Gross Labour Cost (S\$)			12,572.00	8,472.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >