



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FZ 9051K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	HONDA HEAD COWL	TO REPAIR SEE LABOUR	130.00	-
1	HONDA HEADLIGHT	CRACKED / SCRATCHED	95.00	95.00
1	HONDA HEADLIGHT STAY (BRACKET)	TO REPAIR SEE LABOUR	80.00	-
1	HONDA TRIPLE CLAMP (TOP)	DISTORTED	280.00	280.00
1	HONDA TRIPLE CLAMP (BOTTOM)	DISTORTED	380.00	380.00
1	HONDA STEERING CONE BEARING	NECESSARY	140.00	140.00
1	HONDA STEERING CONE BEARING SEAL COVER	NECESSARY	35.00	35.00
1	HONDA SPEED SENSOR	FAULTY / DISTORTED	95.00	95.00
1	HONDA SPEED CABLE	DISTORTED / BROKEN	65.00	65.00
1	HONDA FRONT BRAKE CALIPER	NOT NECESSARY	230.00	-
1	HONDA FRONT BRAKE DISC	NOT NECESSARY	220.00	-
1	HONDA FRONT WHEEL SHAFT	DISTORTED	110.00	110.00
2	HONDA FRONT WHEEL BEARING	RATTLE	70.00	70.00
2	HONDA FRONT WHEEL SEAL	NECESSARY	30.00	30.00
2	HONDA FRONT SUSPENSION	DISTORTED	1,600.00	1,600.00
2	HONDA FRONT FORK PROTECTOR FAIRING	GRAZED	120.00	120.00
1	SET HONDA BODY PANEL	GRAZED	380.00	380.00
1	HONDA CHAIN GUARD	TO REPAIR SEE LABOUR	60.00	-
1	HONDA CLUTCH CABLE	NOT NECESSARY	50.00	-
1	HONDA THROTTLE CABLE	NOT NECESSARY	120.00	-
1	SET HONDA RIDER FOOTREST	GRAZED / DENTED	90.00	90.00
1	HONDA REAR BRAKE PEDAL	GRAZED / BENT	80.00	80.00
1	HONDA GEAR SHIFTER	GRAZED	80.00	80.00
1	HONDA ENGINE COVER (LEFT)	NOT NECESSARY	240.00	-
1	HONDA ENGINE COVER (RIGHT)	GRAZED	240.00	240.00
2	HONDA ENGINE COVER GASKET	NOT NECESSARY	40.00	-
1	SET GPR REAR SIGNAL	BROKEN	65.00	65.00

Report Ref No. CS3/FCI19006151/Dtf3s2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET GRP FRONT SIGNAL	SCRATCHED / DISTORTED	65.00	65.00
1	RIZOMA CNC MIRROR	GRAZED / BROKEN	180.00	180.00
1	GPR CNC HANDLEBAR CLAMP	NECESSARY	120.00	120.00
1	ZETA CNC CLUTCH LEVER	NOT NECESSARY	70.00	-
1	RENTHAL FAT HANDLEBAR	DISTORTED	220.00	220.00
1	RENTHAL HANDLEBAR GUARD	BENT / GRAZED	190.00	190.00
1	BREMBO BRAKE MASTER CYLINDER RCS19	NOT NECESSARY	550.00	-
1	METER POLISHING	NOT NECESSARY	120.00	-
1	SET PLAYLIFE GRIP	NECESSARY	35.00	35.00
1	DELTA EXHAUST SYSTEM	GRAZED	980.00	980.00
1	HONDA BRAKE LEVER	GRAZED	70.00	70.00
	LESS 10% DISCOUNT		-	-581.50
			7,725.00	5,233.50
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	NECESSARY	15.00	15.00
1	REAR NUMBER PLATE (SN)	DENTED / BENT	20.00	20.00
1	FRONT RIM REFURBISH (SN)	WARPED / WOBBLE	150.00	80.00
1	FRONT RIM SPOKE BALANCING (SN)	NECESSARY	50.00	20.00
1	LIQUIMOLY FRONT BRAKE FLUID (SN)	SERVICEABLE	15.00	-
1	KAPPA BOX BRACKET (SN)	NOT NECESSARY	110.00	-
1	KAPPA BOX (SN)	NOT NECESSARY	150.00	-
1	KAPPA BOX RACK (SN)	NOT NECESSARY	85.00	-
1	SEAT WRAP (SN)	NOT NECESSARY	65.00	-
			660.00	135.00
	<b><u>LABOUR</u></b>			
	TO REMOVE & REPLACE FRONT RIM, FRONT WHEEL BEARING, AXLE SHAFT, TRIPPLE CLAMPS, FRONT FORK, STEERING CONE, FRONT BRAKE DISC.		300.00	100.00
	TO REMOVE & REPLACE ABOVE BODY DAMAGED PARTS, CHECK WIRING & LIGHTING SYSTEM. INCLUSIVE OF THE REPAIR OF HONDA HEAD COWL, HONDA HEADLIGHT STAY (BRACKET) AND HONDA CHAIN GUARD.		500.00	300.00
	FUEL TANK WELDING / KNOCKING / SPRAY.		350.00	120.00

Report Ref No. CS3/FCI19006151/Dtf3s2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT CHASSIS ALIGNMENT.		350.00	120.00
	TOWING - WORKSHOP TO ACCIDENT REPORTING CENTER.	NOT NECESSARY	60.00	-
	TOWING - ACCIDENT REPORTING CENTER TO WORKSHOP.	NOT NECESSARY	60.00	-
			1,620.00	640.00
<b>GRAND TOTAL</b>			<b>10,005.00</b>	<b>6,008.50</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,800.00</b>

Report Ref No. CS3/FCI19006151/Dtf3s2-1

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.