Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20009790/QBA3Q2

Date: 19/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100337549

Claimant Vehicle No: Insured Vehicle No: GBC8339G

Date of Loss: 09/09/2020 Nature of Claim: TP Claim No: 5335932460SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB5931A

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2F15920

Reg. Date: 12/12/2019 (Man. Year: 2019) Chassis No: JTDKB3FU603088856

Colour: Maroon Odometer: 102933 km

Engine Capacity: 1798 cc Market Value/New Car

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Sailun 6 mm Rear Left Side: Sailun 6 mm
Front Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|-----------------------|----------------------|------------|------------|--------|
| Parts | | 14,663.80 | 1,171.44 | 13,492.36 | 92.01 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 3,781.00 | 910.00 | 2,871.00 | 75.93 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Nett Amount (S\$) | 18,444.80 | 2,081.44 | 16,363.36 | 88.72 |
| | + Loss of Use (5.0 x | S\$50.00/day) (S\$) | 250.00 | | |
| | + Car Rental (5.0 x S | \$116.63/day) (S\$) | 583.15 | | |
| | + Doo | c/Search Fee (S\$) | 7.00 | | |
| | | Nett Liability (S\$) | 2,921.59 | | |

INSPECTION

Date of Assignment: 11/09/2020

Date Inspected: 11/09/2020 Inspected At: SMRT Automotive Services Pte Ltd

Global Sum Settlement (S\$)

(Woodlands)

2.920.00

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN Manager: CHUA ZHEN LI

Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|----------|-----|-------------|--|-------------|------------|--------------|
| 1 | 1 | | *COVER ,RR BUMPER ASSY (DISC 25%) | Cracked | 485.60 F | *364.20 F |
| 2 | 2 | | *PAD ,RR BUMPER ,RH & LH 1 (DISC 25%) | Necessary | 8.00 F | *6.00 F |
| 3 | 2 | | *PAD ,RR BUMPER ,RH & LH 2 (DISC 25%) | Necessary | 8.00 F | *6.00 F |
| 4 | 2 | | *PAD ,RR BUMPER ,RH & LH 3 (DISC 25%) | Necessary | 22.00 F | *16.50 F |
| 5 | 1 | | *SEAL ,RR BUMPER ARM,RH & LH (DISC 25%) (2 PCS) | Necessary | 22.60 F | *16.95 F |
| 6 | 1 | | *GUARD ,RR BUMPER LOWER (DISC 25%) | Scratched | 374.50 F | *280.88 F |
| 7 | 1 | | *COVER GUARD RR BUMPER LOWER (DISC 25%) | Scratched | 22.00 F | *16.50 F |
| 8 | 3 | | *PAD ,RR BUMPER ,CTR (DISC 25%) | Necessary | 33.00 F | *24.75 F |
| 9 | 1 | | *EMBLEM SUB-ASSY REAR (DISC 25%) | Necessary | 47.90 F | *35.93 F |
| 10 | 1 | | *NAME PLATE (HYBRID) LUGGAGE COMPARTMENT (DISC 25%) | Necessary | 54.60 F | *40.95 F |
| 11 | 1 | | *NAME PLATE (PRIUS) LUGGAGE COMPARTMENT (DISC 25%) | Necessary | 54.60 F | *40.95 F |
| 12 | 1 | | *COVER ,REAR FLOOR UNDER CENTER (DISC 25%) | Deformed | 229.90 F | *172.43 F |
| 13 | 2 | | *PIXEL STICKER (SN) | Necessary | 120.00 F | *120.00 F |
| 14 | 1 | | *SMRT LOGO (SN) | Necessary | 7.80 F | *7.80 F |
| 15 | 1 | | *STICKER DECAL 6555 8888 (SN) | Necessary | 21.60 F | *21.60 F |
| 16 | 1 | | *RETAINER ,RR BUMPER LH | Serviceable | | *- F |
| 17 | 1 | | *RETAINER ,RR BUMPER RH | Serviceable | 132.60 F | *- F |
| 18 | 2 | | *RETAINER OUT SIDE RH & LH | Serviceable | 3.90 F | *- F |
| 19 | 1 | | *REAR BUMPER REFLECTOR ASSY ,REAR RH | Serviceable | 39.00 F | *- F |
| 20 | 1 | | *REAR BUMPER REFLECTOR ASSY ,REAR LH | Serviceable | | *- F |
| 21 | 1 | | *REAR BUMPER REINFORCEMENT | Serviceable | | *- F |
| 22 | 1 | | *END PANEL SUB-ASSY ,BODY LOWER BACK | Serviceable | | *- F |
| 23 | 1 | | *END PANEL COVER DECK TRIM REAR | Serviceable | | *- F |
| 24 | 1 | | *END PANEL COVER DECK TRIM SERVICE HOLE | Serviceable | | *-F |
| 25 | 1 | | *SEALANT SIKAFLEX | Serviceable | | *- F |
| 26 | 1 | | *SPARE TYRE PANEL ,PAN REAR FLOOR | Serviceable | | *-F |
| 27 | 1 | | *BOARD REAR FLOOR NO.1 | Serviceable | | *- F |
| 28 | 1 | | *BOX DECK FLOOR LH | Serviceable | | *- F |
| 29 | 1 | | *BOX DECK FLOOR RH | Serviceable | | *- F |
| 30 | 1 | | *COVER REAR FLOOR UNDER ,RH | Serviceable | | *- F |
| 31 | 1 | | *COVER REAR FLOOR UNDER ,LH | Serviceable | | *- F |
| 32 | 1 | | *COVER ,REAR FLOOR UNDER CENTER | Serviceable | | *-F |
| 33 | 1 | | *ANTENNA ELECTRICAL KEY | Serviceable | | *-F |
| 34 | 1 | | *STICKER AUTO TAILGATE PLEASE DO NOT PULL | Serviceable | | *- F |
| 35 | 1 | | *TAIL GATE PANEL SUBASSY ,BACK DOOR | Serviceable | | *- F |
| 36 | 1 | | *AUTO TAILGATE SYSTEM | Serviceable | • | *- F |
| 37 | 1 | | *TAILGATE WEATHERSTRIP BACK DOOR | Serviceable | | *- F |
| 38 | 1 | | *TAILGATE WEATHERSTRIP BACK DOOK *TAILGATE BACK DOOR HINGE ASSY ,LH | Serviceable | | *-F |
| 39 | 1 | | *TAILGATE BACK DOOR HINGE ASSY ,RH | Serviceable | | *-F |
| 40 | 1 | | *TAIL GATE LOCK ASSY BACK DOOR | Serviceable | | *-F |
| 41 | 1 | | *TAIL GATE LOCK COVER BACK DOOR | Serviceable | | *-F |
| 42 | 1 | | *LAMP SET ,STOP CENTER | Serviceable | | *-F |
| 43 | 1 | | *REVERSE SENSOR ,REAR BUMPER | Serviceable | | *-F |
| 43 44 | 1 | | *NUMBER PLATE | Serviceable | | *-F |
| 45 | 1 | | *NUMBER PLATE FRAME | Serviceable | | *-F |
| 46 | 1 | | *WIRE LUGGAGE ROOM | Serviceable | | -г *-F |
| | | | | | | *-F |
| 47 48 | 1 | | *REVERSE CAMERA (FOR TAILGATE) *I AMD ASSY DEAD DH | Serviceable | | "- F *- F |
| 48 | 1 | | *LAMP ASSY ,REAR RH | Serviceable | | - |
| 49 | 1 | | *LAMP ASSY ,REAR LH | Serviceable | 293.60 F | *- F |
| | | | Report was unsubmitted during this print-out. | | | |

Adjuster Report Page 4 of 5

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---------|-------------|--|-------------------|------------|----------|
| 50 | 1 | | *MEMBER SUB-ASSY ,RAIL ROOT SIDE REAR RH | Serviceable | 288.50 F | *- F |
| 51 | 1 | | *TAIL GATE BACK DOOR OUTSIDE GARNISH SUB | Repair | 913.60 F | *- F |
| 52 | 1 | | *SPOILER SUB-ASSY ,REAR | Repair | 1,575.40 F | *- F |
| 53 | 1 | | *MEMBER SUB ASSY ,RAIL ROOT SIDE REAR LH | Repair | 288.50 F | *- F |
| F=Fra | ınchise | part. | | ' | | |
| | | | | Total Parts (S\$) | 14,663.80 | 1,171.44 |
| | | | | ' | | |

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|---|----------------|------------|--------|
| Lab | our Items | | | |
| 1 | PANEL BEATING & BODY WORK | New | 845.00 | 400.00 |
| 2 | SPRAY PAINT | New | 2,016.00 | 460.00 |
| 3 | TO CHECK WIRING AND SYSTEM FUNCTION | New | 80.00 | 20.00 |
| 4 | TO TEST AND REFIX REVERSE SENSOR SYSTEM | New | 120.00 | 30.00 |
| 5 | TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR | New | 120.00 | 0.00 |
| 6 | TO INSPECT RR LIGHTING ,MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE | New | 120.00 | 0.00 |
| 7 | TO REMOVE AND REFIT WIRE HARDESS | New | 200.00 | 0.00 |
| 8 | TO REMOVE AND REFIX AUTO TAILGATE SYSTEM | New | 120.00 | 0.00 |
| 9 | TO REPLACE SUNDRY PARTS | New | 100.00 | 0.00 |
| 10 | TO WASH AND VACUUM | New | 60.00 | 0.00 |
| | Gross Labo | our Cost (S\$) | 3,781.00 | 910.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >