

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 1564U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED / TORN	1,429.35	1,429.35
1	REAR BUMPER LOWER SKIRTING	DEFORMED / TWISTED	341.20	341.20
1	REAR BUMPER BEAM	BENT	417.35	417.35
1	REAR BUMPER RIVET	NECESSARY	60.00	60.00
1	REAR BUMPER INNER RETAINER	CRACKED	148.00	148.00
2	REAR BUMPER SIDE HOLDERS @\$65.00	CRACKED / NECESSARY	130.00	130.00
2	REAR BUMPER PDC SENSORS @\$232.50	SHORTED	465.00	465.00
2	REAR BUMPER PDC SENSOR SEALS @\$6.29	NECESSARY	12.58	12.58
2	TAILLAMPS @\$625.00	NOT NECESSARY	1,250.00	-
1	REAR END PANEL	DENTED	967.45	967.45
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	199.20	-
1	BOOTLID WEATHERSTRIP	TWISTED	185.40	185.40
1	REAR END PANEL SEALER	NECESSARY	50.00	50.00
	LESS 10% DISCOUNT		-	-420.63
			5,655.53	3,785.70
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	30.00
	TO DISMANTLE & REPLACING PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO SPRAY RUST PROOFING.		80.00	30.00
	TO RESET & REPROGRAMME SYSTEM.		120.00	50.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.		1,080.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,200.00	800.00
			-	-
			-	-
			2,730.00	1,840.00
	GRAND TOTAL		8,385.53	5,625.70

Report Ref No. CS/TP20009796/Uyf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/TP20009796/Uyf3e2

CHUA KANG SENG
Licensed Appraiser