



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892		Cust No/Name	KCV13801/Mr Tan Peng Seng (chen Bingchen		
		Reg No/Reg Date	SKS1039C / 25/03/201		
		Date In/Mileage	/ 114063		
		Chassis No	JMYXTGF3WFZ001657		
		Engine No	4B12PG7136		
		Make/Model	MIT/OUTLANDER 2.4 CVT AWD (F27)		
		Colour/Trim	U01 / BK		

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	14/09/2020/ 11:26	QUD	247 / DonBong	57305
Description of Goods / Services					
E PNT80000		RENEW ACCIDENT DAMAGED PARTS ON FRONT BUMPER FACE, RH FRONT FENDER, RH MOULDING GARNISH, REPAIR REAR BUMPER FACE			1125 1350.00
E PNT80000		REMOVE AND INSTALL FRONT PARKING ASSIST			60.00
E PNT98000		PAINT WORK SPRAY FRONT BUMPER, RH FRONT FENDER, BOTH RH DOOR, REAR BUMPER FACE AND AFFECTED PORTION			1050 2100.00
M SUNDRY		APPLY BODY SEALANT			ANX 80.00
A 54900099		CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM			30.00
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST			120.00
A 300000001		RENEW UNDERCARRIAGE DAMAGES			450 675.00
A WHEELALIGNMENTBP		To Conduct Computerize Full Wheel Alignment			120.00
M SUNDRY		LABOUR RENEW RH FRONT AND RH REAR SPORT RIM INCLUDING BALANCING			60.00
M SUNDRY		SUPPLY RH FRONT AND RH REAR TIRE			800 800.00
M SUNDRY		SUNDRIES			90 50.00
M HEADLAMP ASSY,RH		9.7500			1426.04
M TANK,WINDSHIELD WASHER		7.7500			67.76
M MOTOR,HEADLAMP WASHER		7.7500			272.58
M GROMMET,WINDSHIELD WASHER		7.7500			3.85
M COVER,ENG ROOM UNDER,RR RH		7.7500			24.64
M COVER,ENG ROOM UNDER,RR LH		7.7500			24.64
M COVER,ENG ROOM UNDER,FR		7.7500			267.96

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windshield in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windshield.

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

CARRIAGE



ESTIMATE

No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte. Ltd.		Cust No/Name	KCV13801/Mr Tan Peng Seng (chen Bingchen)		
MOTOR CLAIM DEPT		Reg No/Reg Date	SKS1039C / 25/03/201		
78 SHENTON WAY #08-16		Date In/Mileage	/ 114063		
AIG BUILDING		Chassis No	JMYXTGF3WFZ001657		
SINGAPORE 079120		Engine No	4B12PG7136		
Contact No 6419 1892		Make/Model	MIT/OUTLANDER 2.4 CVT AWD (F27)		
		Colour/Trim	U01 / BK		

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	14/09/2020/ 11:26	QUD	247 / DonBong	57305
Description of Goods / Services					
			Qty	Unit Price	Disc% Amount
M COVER, ENG ROOM UNDER, FR	7.5VLC		1.00	149.00	23.00 114.73
M BRACKET, FR BUMPER SIDE, LH	7.5VLC		1.00	24.00	23.00 18.48
M BRACKET, FR BUMPER SIDE, RH	7.5VLC		1.00	24.00	23.00 18.48
M FACE, FR BUMPER	7.5VLC		1.00	1036.00	23.00 797.72
M COVER, FR FOG LAMP	7.5VLC		1.00	20.00	23.00 15.40
M GARNISH, FR BUMPER, RH	7.5VLC		1.00	32.00	23.00 24.64
M GARNISH, FR FOG LAMP, RH	7.5VLC		1.00	50.00	23.00 38.50
M REINFORCEMENT, FR BUMPER	7.5VLC		1.00	503.00	23.00 387.31
M MOULDING, FR BUMPER, RH	7.5VLC		1.00	116.00	23.00 89.32
M MOULDING, RR WHEEL ARCH, RH	7.5VLC		1.00	199.00	23.00 153.23
M MOULDING, RR BUMPER, RH	7.5VLC		1.00	106.00	23.00 81.62
M FENDER, FR RH	7.5VLC		1.00	688.00	23.00 529.76
M AIR DAM, SIDE, RH	7.5VLC		1.00	541.00	23.00 416.57
M HUB ASSY, FR WHEEL	7.5VLC		1.00	235.00	23.00 180.95
M SNAP RING, FR WHEEL HUB	7.5VLC		1.00	25.00	23.00 19.25
M BEARING, FR WHEEL HUB	7.5VLC		1.00	151.00	23.00 116.27
M KNUCKLE, RH	7.5VLC		1.00	356.00	23.00 274.12
M ARM ASSY, FR SUSP, LWR RH	7.5VLC		1.00	337.00	23.00 259.49
M CROSSMEMBER, FR AXLE, NO.1	7.5VLC		1.00	1114.00	23.00 857.78
M STRUT, FR SUSP, RH	7.5VLC		1.00	484.00	23.00 372.68
M PAD, FR SUSP SPRING, UPR	7.5VLC		1.00	71.00	23.00 54.67
M DAMPER, FR SUSP STRUT	7.5VLC		1.00	35.00	23.00 26.95
M INSULATOR, FR SUSP STRUT	7.5VLC		1.00	136.00	23.00 104.72
M LINK, FR SUSP STABILIZER	7.5VLC		1.00	137.00	23.00 105.49
M GEAR & LINK ASSY, STEERING	7.5VLC		1.00	1211.00	23.00 932.47
M END ASSY, TIE ROD	7.5VLC		2.00	62.00	23.00 417.95.48
M RH REAR HUB ASSY, RR WHEEL	7.5VLC		1.00	416.00	23.00 320.32
M RH FRONT WHEEL, DISC	7.5VLC		1.00	1102.00	23.00 848.54
M RH REAR WHEEL, DISC	7.5VLC		1.00	1102.00	23.00 848.54

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Pamela - 40 90010088

SURVEYOR SIGNATURE: (Signature)

DATE: 14/09/2020 0160

Confirm & accepted by

REMARKS:

6 days

Repair before paint

EXCESS: TPA / Repairer

7% GST on

15635.95

Nett

1094.52

Total Payable

16,730.47

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.