

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20009809/R1BA3Q2

Date: 20/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100091950

Claimant
Vehicle No : SME7751P **Insured Vehicle No :** SJH8157T

Date of Loss: 13/09/2020 Nature of Claim: TP Claim No: 5408123452SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME7751P		
Make & Model:	VOLKSWAGEN PASSAT, 1.8 B8 TFSI AT SR 17W 3G24JZ HUD (A)	Engine No:	CJS296730
Reg. Date:	16/10/2018 (Man. Year: 2018)	Chassis No:	WVWZZZ3CZKE012351
Colour:	Blue	Odometer:	36764 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,023.94	3,077.23	2,946.71	48.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,800.00	4,980.00	4,820.00	49.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,823.94	8,057.23	7,766.71	49.08
+ GST 7.00/7.00% (S\$)	1,107.68	564.01	543.67	49.08
Nett Amount (S\$)	16,931.62	8,621.24	8,310.38	49.08
+ Car Rental (7.0 x S\$120.00/day + 7.00% GST) (S\$)		898.80		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,522.04		

INSPECTION

Date of Assignment: 15/09/2020

Date Inspected: 15/09/2020 Inspected At: Volkswagen Group Singapore Pte Ltd
247 ALEXANDRA ROAD
Singapore 159934

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR (LHF DOOR)	Repair	2,548.05 FS	*- FS
2	1		*DOOR SEAL OUTER BLACK	Not Necessary	170.70 FS	*- FS
3	1		*SOUND ABSORBER LAMINATED	Not Necessary	41.40 FS	*- FS
4	1		*DOOR (LHR DOOR)	Bent	2,604.58 FS	*2,604.58 FS
5	1		*SOUND ABSORBER LAMINATED	Necessary	41.40 FS	*41.40 FS
6	1		*DOOR SEAL OUTER BLACK	Necessary	176.60 FS	*176.60 FS
7	1		*COVER STRIP (LHR FENDER CHROME MOULDING)	Scratched	55.74 FS	*55.74 FS
8	1		*COVER FOR DOOR PRIMED (LHF DOOR MOULDING)	Not Necessary	67.60 FS	*- FS
9	1		*DECORATIVE MOULDING CHROM (LHF DOOR CHROME MOULDING)	Not Necessary	118.96 FS	*- FS
10	1		*COVER FOR DOOR PRIMED (LHR DOOR MOULDING)	Cracked	79.95 FS	*79.95 FS
11	1		*DECORATIVE MOULDING CHROM (LHR DOOR CHROME MOULDING)	Scratched	118.96 FS	*118.96 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **6,023.94** **3,077.23**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	0.00
3	TRANSFER DOOR MECHANISM PARTS	New	1,680.00	420.00
4	LABOUR	New	3,360.00	1,680.00
5	SPRAY PAINTING	New	4,000.00	2,400.00
Gross Labour Cost (\$\$)			9,800.00	4,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >