

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009812/KBS3Q2
Date: 05/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993856
Claimant Vehicle No :	SLV2410D	Insured Vehicle No :	SFE6157U
Date of Loss:	12/09/2020	Nature of Claim:	TP
		Claim No:	2845042762SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV2410D		
Make & Model:	HONDA VEZEL, 1.5 X SENSING (A)	Engine No:	LEB5965223
Reg. Date:	26/12/2017 (Man. Year: 2017)	Chassis No:	RU31265203
Colour:	Metallic Green	Odometer:	229731 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,450.88	7,873.48	2,577.40	24.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,110.00	2,560.00	550.00	17.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,560.88	10,433.48	3,127.40	23.06
Approved Total (Overridden) (S\$)		8,350.00		

(S\$)	13,560.88	8,350.00	5,210.88	38.43
+ GST 7.00/7.00% (S\$)	949.26	584.50	364.76	38.43
Nett Amount (S\$)	14,510.14	8,934.50	5,575.64	38.43
+ Loss of Use (9.0 x S\$80.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		9,662.50		
Global Sum Settlement (S\$)		9,600.00		

INSPECTION

Date of Assignment: 14/09/2020

Date Inspected: 14/09/2020

Estimated Period of Repair: 5.0 days

Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	801.70 FL	*801.70 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	360.80 FL	*360.80 FL
3	1		*FRONT BUMPER LH FOG LAMP	Missing	327.70 FL	*327.70 FL
4	1		*FRONT BUMPER LH FOG LAMP GARNISH	Dented	40.50 FL	*40.50 FL
5	1		*FRONT BUMPER LH FOG LAMP BRACKET	Repair	17.10 FL	*- FL
6	1		*FRONT BUMPER CENTRE LOWER GRILLE	Serviceable	77.50 FL	*- FL
7	2		*FRONT BUMPER SIDE RETAINERS	N/s Cracked/O/s Distorted	29.40 FL	*29.40 FL
8	1		*FRONT BUMPER LOWER SKIRT RUBBER	Serviceable	381.00 FL	*- FL
9	6		*FRONT BUMPER CLIPS	Necessary	23.40 FL	*23.40 FL
10	1		*FRONT BUMPER DAY LIGHT	Missing	234.10 FL	*234.10 FL
11	1		*FRONT LH FENDER	Bent	558.70 FL	*558.70 FL
12	1		*FRONT LH FENDER EMBLEM HYBRID	Necessary	76.60 FL	*76.60 FL
13	1		*FRONT LH FENDER INNER SHIELD	Cracked	130.60 FL	*130.60 FL
14	6		*FRONT LH FENDER INNER SHIELD CLIPS	Necessary	23.40 FL	*23.40 FL
15	1		*FRONT LH FENDER INNER PANEL	Bent	409.70 FL	*409.70 FL
16	1		*FRONT LH FENDER WHEEL ARP GARNISH	Missing	199.20 FL	*199.20 FL
17	1		*BONNET	Bent	892.30 FL	*892.30 FL
18	1		*BONNET INNER RUBBER	Cut	24.50 FL	*24.50 FL
19	1		*BONNET LH HINGE	Repair	48.50 FL	*- FL
20	1		*BONNET INNER SPONGE	Serviceable	122.30 FL	*- FL
21	6		*BONNET INNER SPONGE CLIPS	Not Necessary	23.40 FL	*- FL
22	1		*FRONT RH FENDER EMBLEM HYBRID	Necessary	75.00 FL	*75.00 FL
23	1		*FRONT GRILLE BASE	Scratched	351.80 FL	*351.80 FL
24	1		*FRONT GRILLE OUTER GARNISH	Scratched	401.20 FL	*401.20 FL
25	1		*FRONT GRILLE LOGO	Necessary	27.40 FL	*27.40 FL
26	1		*FRONT GRILLE CHROME MOULDING	Serviceable	95.00 FL	*- FL
27	6		*FRONT GRILLE CLIPS	Necessary	23.40 FL	*23.40 FL
28	1		*LH HEADLAMP	Broken	1,923.50 FL	*1,820.20 FL
29	1		*LH HEADLAMP LOWER GARNISH	Cracked	35.00 FL	*35.00 FL
30	1		*FRT SUPPORT PANEL	Bent	576.20 FL	*576.20 FL
31	1		*RADIATOR	Serviceable	1,376.50 FL	*- FL
32	1		*AIR FILTER HOUSING LOWER	Serviceable	175.00 FL	*- FL
33	1		*AIR FILTER RESONATOR	Cracked	90.10 FL	*90.10 FL
34	1		*FRONT WIPER GARNISH	Serviceable	240.00 FL	*- FL
35	1		*FRONT RH FENDER WHEEL ARP GARNISH	Distorted	195.00 FL	*195.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT LH SHOCK ABSORBER	Serviceable	430.10 FL	*- FL
37	1		*HEADLAMP RH	Mtg Cracked	1,923.50 FL	*1,820.20 FL
38	1		*HEADLAMP RH LOWER GARNISH	Cracked	35.00 FL	*35.00 FL
39	1		*FRONT LH TYRE (90%)	Cut	230.00 FS	*207.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,006.10	9,790.10
- List Item Discount on L Items 20.00/20.00% (\$)	2,555.22	1,916.62
Total Parts (\$)	10,450.88	7,873.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	New	100.00	100.00
2	REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,FRT FENDER,BONNET & ATTACHMENT,RADIATOR & MOTOR,CUT,WELD & RENEW FRT SUPPORT PANEL,FRT LH FENDER INNER PANEL & REALIGN THE SAME	New	1,200.00	1,000.00
3	REMOVE & REFIX FRT LH SHOCK ABSORBER	New	100.00	0.00
4	REMOVE & REFIX ENGINE,ECU,ENGINE MOUNTINGS,ETC AND RESET SYSTEM	New	350.00	200.00
5	PUTTY & RESPRAY ON FRT LH DOOR,FRT BUMPER,BONNET,SUPPORT PANEL,FRT LH WHEEL HOUSING	New	1,100.00	1,000.00
6	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
7	RUSTPROOFING	New	80.00	80.00
8	TO REMOVE & REFIT MAIN FUSE BOX ASSY,REPAIR FUSE BOX HOUSING AND CHECK WIRING	New	120.00	120.00
Gross Labour Cost (\$\$)			3,110.00	2,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >