

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009820/ARS3Q2

Date: 18/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993863

Claimant
Vehicle No : SLT6737X **Insured Vehicle No :** SMT5952K

Date of Loss: 13/09/2020 Nature of Claim: TP Claim No: 3104756396SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT6737X		
Make & Model:	TOYOTA SIENTA, 1.5 X CVT (A)	Engine No:	1NZR519116
Reg. Date:	07/11/2017 (Man. Year: 2017)	Chassis No:	NHP1707089615
Colour:	Blue	Odometer:	160292 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,616.25	7,061.80	16,554.45	70.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,500.00	2,400.00	6,100.00	71.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,116.25	9,461.80	22,654.45	70.54
Approved Total (Overridden) (S\$)		7,400.00		
(S\$)	32,116.25	7,400.00	24,716.25	76.96
+ GST 7.00/7.00% (S\$)	2,248.14	518.00	1,730.14	76.96
Nett Amount (S\$)	34,364.39	7,918.00	26,446.39	76.96
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		8,434.45		

INSPECTION

Date of Assignment: 14/09/2020

Date Inspected: 16/09/2020 Inspected At:

Vision Autowork Pte Ltd (HQ)
8 KAKI BUKIT AVE 4,, #08-09
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	96.20 FL	*- FL
2	1		*HEADLAMP RH	Not Necessary	996.20 FL	*- FL
3	1		*FRONT FENDER RH	Dented	579.20 FL	*579.20 FL
4	1		*FRONT FENDER EMBLEM HYBRID	Necessary	42.10 FL	*42.10 FL
5	1		*FRONT FENDER COWRING RH	Deformed	172.25 FL	*172.25 FL
6	1		*FRONT FENDER INNER GARNISH RH	Not Necessary	82.70 FL	*- FL
7	1		*FRONT ABS SENSOR	Not Necessary	397.60 FL	*- FL
8	1		*FRONT KNUCKLE ARM RH	Damaged	598.40 FL	*598.40 FL
9	1		*FRONT KNUCKLE BEARING RH	Damaged	191.90 FL	*191.90 FL
10	1		*FRONT WHEEL HUP CAP RH	Cracked	159.23 FS	*100.00 FS
11	1		*FRONT SHOCK ABSORBER RH	Bent	574.10 FL	*574.10 FL
12	1		*FRONT LOWER ARM RH	Bent	1,154.20 FL	*497.00 FL
13	1		*FRONT STEERING RACK AND PINION	Not Necessary	1,955.40 FL	*- FL
14	1		*FRONT DRIVESHAFT RH	Not Necessary	1,420.60 FL	*- FL
15	1		*FRONT WINDSCREEN TOP MOULDING	Not Necessary	125.30 FL	*- FL
16	1		*FRONT DOOR RH	Distorted	1,384.20 FL	*1,136.00 FL
17	1		*FRONT DOOR OUTER MOULDING RH	Not Necessary	198.60 FL	*- FL
18	2		*FRONT DOOR HINGE RH	Not Necessary	171.40 FL	*- FL
19	1		*FRONT DOOR CHECKER RH	Not Necessary	190.10 FL	*- FL
20	1		*FRONT DOOR WEATHERSTRIP RH	Cut	223.40 FL	*223.40 FL
21	1		*FRONT DOOR FRAME WEATHERSTRIP RH	Not Necessary	278.20 FL	*- FL
22	1		*FRONT DOOR GLASS CHANNEL RH	Not Necessary	185.20 FL	*- FL
23	1		*FRONT DOOR INNER LOCK RH	Damaged	544.70 FL	*544.70 FL
24	1		*FRONT DOOR LOCK CATCH RH	Not Necessary	35.90 FL	*- FL
25	1		*FRONT DOOR INNER SPONGE RH	Not Necessary	182.40 FL	*- FL
26	1		*FRONT DOOR INNER TRIM BOARD RH	Cracked	678.40 FL	*678.40 FL
27	1		*FRONT DOOR REGULATOR RH	Damaged	233.70 FL	*233.70 FL
28	1		*FRONT DOOR POWER WINDOW MOTOR RH	Not Necessary	779.60 FL	*- FL
29	1		*FRONT DOOR SPEAKER RH	Not Necessary	213.10 FL	*- FL
30	1		*FRONT DOOR PILLAR RH (OUTER)	Repair	697.90 FL	*- FL
31	1		*FRONT DOOR STEP PANEL INNER GARNISH (OUTER)	Not Necessary	188.45 FL	*- FL
32	1		*ROCKER PANEL RH	Repair	495.60 FL	*- FL
33	1		*CENTER PILLAR RH (OUTER)	Repair	382.70 FL	*- FL
34	3		*CENTER PILLAR STICKER	Necessary	96.60 FL	*96.60 FL
35	1		*SLIDING DOOR RH	Distorted	1,294.90 FL	*1,294.90 FL
36	1		*SLIDING DOOR REFLECTOR STICKER RH	Necessary	29.78 FS	*5.00 FS
37	1		*SLIDING DOOR LOWER GUARD RH	Missing	147.80 FL	*147.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*SLIDING DOOR STEP PANEL GARNISH RH	Cracked	138.60 FL	*138.60 FL
39	1		*SLIDING DOOR STOPPER (BACK)	Not Necessary	32.60 FL	*- FL
40	2		*SLIDING DOOR ALIGN STOPPER (FRONT)	Not Necessary	51.60 FL	*- FL
41	1		*SLIDING DOOR LOWER ROLLER RH (3 PCS)	Bent	999.60 FL	*333.20 FL
42	1		*SLIDING DOOR LOWER RAILWAY PANEL RH	Repair	642.10 FL	*- FL
43	1		*SLIDING DOOR OUTER STRIP RH	Not Necessary	128.70 FL	*- FL
44	1		*SLIDING DOOR INNER LOCK RH (FRONT)	Damaged	238.90 FL	*238.90 FL
45	1		*SLIDING DOOR INNER LOCK RH (BACK)	Not Necessary	1,092.80 FL	*- FL
46	1		*SLIDING DOOR FRAME WEATHERSTRIP RH	Not Necessary	409.60 FL	*- FL
47	1		*SLIDING DOOR INNER TRM RH	Cracked	800.20 FL	*800.20 FL
48	1		*REAR FENDER LOWER GUARD RH	Cut	128.70 FL	*128.70 FL
49	1		*REAR ABS SENSOR RH	Not Necessary	397.10 FL	*- FL
50	1		*REAR AXLE	Not Necessary	3,574.20 FL	*- FL
51	1		*REAR WHEEL HUP CAP RH	Not Necessary	193.70 FL	*- FL
52	1		*REAR WHEEL HUP WITH BEARING RH	Not Necessary	863.20 FL	*- FL
53	1		*REAR SHOCK ABSORBER RH	Not Necessary	436.70 FL	*- FL
54	1		*SET FRONT BUMPER CLIP	Not Necessary	50.00 FS	*- FS
55	1		*SET FRONT FENDER COWLING CLIP	Necessary	80.00 FS	*30.00 FS
56	1		*SET FRONT FENDER INNER GARNISH CLIP RH	Not Necessary	60.00 FS	*- FS
57	1		*FRONT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
58	1		*FRONT WINDSCREEN INNER SHIELD	Not Necessary	60.00 FS	*- FS
59	1		*FRONT DOOR SEALANT RH	Not Necessary	150.00 FS	*- FS
60	1		*SET FRONT DOOR INNER TRIM BOARD CLIP RH	Necessary	50.00 FS	*30.00 FS
61	1		*SET DASHBOARD (UPPER) CLIP	Not Necessary	80.00 FS	*- FS
62	1		*FRONT PILLAR SEALANT	Not Necessary	150.00 FS	*- FS
63	1		*ROCKER PANEL SEALANT RH	Not Necessary	150.00 FS	*- FS
64	1		*FRONT WHEEL RIM RH	Cut	250.00 FS	*180.00 FS
65	1		*FRONT WHEEL TYRE RH	Not Necessary	480.00 FS	*- FS
66	1		*SLIDING DOOR SEALANT RH	Not Necessary	150.00 FS	*- FS
67	1		*SET SLIDING DOOR INNER TRIM CLIP RH	Necessary	60.00 FS	*30.00 FS
68	1		*SET REAR FENDER COWLING CLIP RH	Not Necessary	50.00 FS	*- FS
69	1		*SET REAR FENDER LOWER GUARD CLIP RH	Necessary	60.00 FS	*10.00 FS
70	1		*REAR WHEEL RIM RH	Not Necessary	250.00 FS	*- FS
71	1		*REAR WHEEL TYRE RH	Not Necessary	480.00 FS	*- FS
72	1		*POWER STEERING OIL	Not Necessary	180.00 FS	*- FS
73	1		*BRAKE OIL		30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
74	1		*FRONT WHEEL HUP RH	Not Necessary Damaged	252.35 FL	*252.35 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (\$\$)	30,458.66	9,287.40
				- List Item Discount on L Items 25.00/25.00% (\$\$)	6,842.41	2,225.60
				Total Parts (\$\$)	23,616.25	7,061.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & REMOVING AN REPLACING PARTS	New	2,200.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	1,000.00
3	TUFF COAT	New	250.00	50.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
6	REMOVE & REFIX FRONT WINDSCREEN	New	120.00	0.00
7	TRANFER FRONT DOOR MECHANISM	New	80.00	80.00
8	REMOVE AND REFIX DASH BOARD AND INTERNAL WIRING	New	850.00	0.00
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	220.00
10	REMOVE AND REFIX POWER STEERING RACK AND PINION	New	350.00	0.00
11	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	0.00
12	FOUR WHEEL ALIGNMENT	New	120.00	80.00
13	TRANSFER REAR SLIDING DOOR MECHANISM	New	80.00	80.00
14	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
15	RESET ABS LIGHT	New	350.00	0.00
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	350.00	0.00
Gross Labour Cost (\$\$)			8,500.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >