



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2006945
INV Date 09/10/2020
Reference CC4/FCI20009821/R1da3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SMV 2288D
Insured Veh. SH 8296T
Claim No. D20003697MFSH
Policy No. D-20094922MFSH
Accident Date 11/09/2020
Inspection Date 14/09/2020

Description	Total
Survey Inspection	230.00
Digital Photographs	
Transportation	
Subtotal	230.00
GST (7%)	16.10
Grand Total	246.10

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20009821/R1da3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-10-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8296T	Veh. Inspected	SMV 2288D
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20003697MFSH	Excess (\$)	0.00
Assign From	CHRIS LIM	Assign Date	14/09/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 520I	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	WBAJR12080BR79829	Colour	WHITE
Odometer	00412	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R18	PIRELLI	6 mm
L/H Front Tyre	245/45 R18	PIRELLI	6 mm
R/H Rear Tyre	245/45 R18	PIRELLI	6 mm
L/H Rear Tyre	245/45 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/09/2020	Inspection Date	14/09/2020
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 2288D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SUNDRIES (SN)	* CHECK	80.00	-
14	C CLIP FOR PLASTIC NUT (SN)	* CHECK	15.40	-
1	COVER GRILLE RH (SN)	CRACKED	76.25	76.25
1	GRILLE AIR INLET MIDDLE (LINES)(SN)	* CHECK	99.80	-
1	RH GRILLE AIR INLET OPEN (LINES)(SN)	CRACKED	116.45	116.45
1	RH PROTECTIVE STRIP LINES (LUXURY) (SN)	* CHECK	68.80	-
1	FRT IMPACT ABSORBER BOTTOM (SN)	* CHECK	63.00	-
1	RH BUMPER GUIDE (SN)	* CHECK	16.95	-
1	RH BUMPER GUIDE (SN)	* CHECK	16.95	-
1	FRT BUMPER PANEL PRIMED (PMA) (SN)	DEFORMED	1,377.95	1,377.95
10	EXPANDING RIVET D=8MM (SN)	* CHECK	11.00	-
1	FRT RH WHEEL ARCH FRT SECTION COVER (SN)	CUT	132.70	132.70
1	ENGINE COMPARTMENT SHIELDING FRT (SN)	* CHECK	171.95	-
1	RH COVER BOTTOM (SN)	* CHECK	71.20	-
1	RH FOG LIGHT LED (BLENDE BLACK) (SN)	* CHECK	471.40	-
2	DECOUPING RING PDC TORQUE CONVERTER (SN)	NECESSARY	10.20	10.20
1	ULTRASONIC SENSOR MINERALWEISS (WA96) (SN)	MISSING	370.00	370.00
			3,170.00	2,083.55
<u>LABOUR</u>				
TO REPLACE INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT.			1,275.00	850.00
TO RESPRAY FRONT BUMPER .			1,038.00	934.00
TO REMOVE AND INSTALL FRONT RIGHT SIDE VIEW CAMERAS INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION .		* CHECK	266.00	-
TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER INCLUDING ADJUSTMENTS OF HEADLIGHTS.			177.00	150.00
			2,756.00	1,934.00
GRAND TOTAL			5,926.00	4,017.55



RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,312.45 NETT)			4,017.55
--	--	--	-----------------

Report Ref No. CC4/FCI20009821/R1da3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMV 2288D

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

