

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9231A

AAD2009-052

Not Authorised
Resurvey B4 point

Vehicle No.:
Chassis No.: **11 SEP 2020**
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHD 9231A
JTDKB3FU403083400
TOYOTA
PRIUS
10.9.2020
FCIL
30/08/2019

| | PART | | LIST | |
|---|---|----|--------------------|-----|
| | | \$ | <i>Ry</i> 1,300.70 | ✓ |
| 1 | PANEL SUB-ASSY, FRONT DOOR, RH | \$ | <i>R</i> 97.50 | } X |
| 1 | HINGE ASSY, FRONT DOOR, UPPER RH | \$ | <i>R</i> 110.60 | |
| 1 | HINGE ASSY, FRONT DOOR, LOWER RH | \$ | <i>SL</i> 183.80 | |
| 1 | CHECK ASSY, FRONT DOOR | \$ | <i>SL</i> 390.60 | |
| 1 | HANDLE ASSY, FRONT DOOR, OUTSIDE RH | \$ | <i>SL</i> 193.50 | |
| 1 | FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH | \$ | <i>SL</i> 926.00 | |
| 1 | MOTOR ASSY, POWER WINDOW REGULATOR, FRONT RH | \$ | <i>SL</i> 238.30 | |
| 1 | REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH | \$ | <i>Me</i> 13.30 | ✓ |
| 1 | TAPE, BLACK OUT, NO.1 FRT RH | \$ | <i>Me</i> 43.50 | ✓ |
| 1 | TAPE, BLACK OUT, NO.2 FRT RH | \$ | <i>Me</i> 26.30 | ✓ |
| 1 | TAPE, BLACK OUT, NO.3 FRT RH | \$ | <i>R</i> 603.20 | X |
| 1 | LOCK ASSY, FRONT DOOR W/MOTOR, RH | \$ | <i>Ry</i> 1,294.90 | ✓ |
| 1 | PANEL SUB-ASSY, REAR DOOR, RH | \$ | <i>Me</i> 21.90 | ✓ |
| 1 | TAPE, BLACK OUT, NO.1 REAR RH | \$ | <i>Me</i> 34.90 | ✓ |
| 1 | TAPE, BLACK OUT, NO.2 REAR RH | \$ | <i>Me</i> 15.40 | ✓ |
| 1 | TAPE, BLACK OUT, NO.3 REAR RH | \$ | <i>R</i> 87.10 | X |
| 1 | HINGE ASSY, REAR DOOR, LOWER RH | \$ | <i>SL</i> 926.00 | X |
| 1 | MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH | \$ | <i>SL</i> 206.70 | X |
| 1 | REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH | \$ | <i>SL</i> 594.80 | X |
| 1 | MOULDING ASSY, BODY ROCKER PANEL, RH | \$ | <i>Ry</i> 977.80 | ✓ |
| 1 | FENDER SUB-ASSY, FRONT RH | \$ | <i>SL</i> 206.70 | X |
| 1 | LINER, FRONT FENDER, RH | \$ | <i>Me</i> 54.60 | ✓ |
| 1 | EMBLEM, SIDE PANEL | \$ | <i>SL</i> 93.90 | X |
| 1 | PROTECTOR, FRONT FENDER SIDE PANEL, RH | \$ | <i>SL</i> 100.40 | X |
| 1 | COVER SUB-ASSY, FRONT PILLAR, UPR RH | \$ | <i>SL</i> 516.00 | X |
| 1 | COVER, FRONT BUMPER | \$ | <i>R</i> 871.50 | X |
| 1 | PANEL SUB-ASSY, QUARTER, RH | \$ | <i>SL</i> 139.80 | X |
| 1 | LINER, REAR WHEEL HOUSE, RH | \$ | | |

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9231A

| | | |
|--------------|----|------------------|
| TOTAL | \$ | 10,269.70 |
| 25% | \$ | 2,567.43 |
| | \$ | 7,702.28 |

| Special Nett | |
|---------------------|--------------------------------|
| 1 | FRONT DOOR STICKER 'TRANS-CAB' |
| 1 | REAR DOOR STICKER "6555-3333" |
| 1 | FRONT WHEEL RIM COVER |
| 1 | REAR WHEEL RIM COVER |
| 2 | WINDSCREEN SEALANT |
| 1 | WINDSCREEN MOULDING |
| 1 | WINDSCREEN INNER SPONGE SEAL |
| 1SET | FRONT FENDER LINER CLIP |
| 1SET | ROCKER PANEL MOULDING CLIP |
| 1 | FRONT BUMPER CLIP |
| 1SET | BUMPER RETAINER CLIP |
| 1 | REAR FENDER LINER CLIP |
| 1 | REAR BUMPER CLIP |

| | | | |
|--------------|-----------|-----------------|-------------|
| \$ | <i>nn</i> | 100.00 | <i>60sn</i> |
| \$ | <i>nn</i> | 100.00 | <i>60sn</i> |
| \$ | <i>sn</i> | 211.50 | } |
| \$ | <i>sn</i> | 211.50 | |
| \$ | <i>nn</i> | 150.00 | |
| \$ | <i>nn</i> | 200.00 | |
| \$ | <i>nn</i> | 130.00 | |
| \$ | <i>nn</i> | 70.00 | |
| \$ | <i>nn</i> | 60.00 | |
| \$ | <i>nn</i> | 80.00 | |
| \$ | <i>nn</i> | 70.00 | |
| \$ | <i>nn</i> | 80.00 | |
| TOTAL | \$ | 1,533.00 | |

| | | |
|--------------------|----|-----------------|
| TOTAL PARTS | \$ | 9,235.28 |
|--------------------|----|-----------------|

LABOUR

To transfer of front door fittings, attachment and perform water seepage test.

| | | |
|----|--------|------------|
| \$ | 170.00 | <i>60l</i> |
|----|--------|------------|

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

| | | |
|----|----------|-------------|
| \$ | 1,600.00 | <i>500l</i> |
|----|----------|-------------|

To transfer of rear door fittings, attachment and perform water seepage test.

| | | |
|----|--------|------------|
| \$ | 170.00 | <i>60l</i> |
|----|--------|------------|

To Rust-Proofing and apply undercoat Of The Affected Areas.

| | | |
|----|--------|------------|
| \$ | 250.00 | <i>90l</i> |
|----|--------|------------|

To check steering geometry and computer wheel alignment

| | | |
|----|------------------|----------|
| \$ | <i>nn</i> 220.00 | <i>X</i> |
|----|------------------|----------|

AAD2009-052

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9231A

| | | | |
|---|-----------|------------------|-------------|
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$ | <i>nn</i> 380.00 | X |
| Putty And Spray Painting Of The Affected Portion. | \$ | 1,600.00 | <i>8801</i> |
| To transfer of tire, rim and on wheel balancing. | \$ | <i>nn</i> 170.00 | X |
| To Check Electrical Lighting Concerned. | \$ | 170.00 | <i>201</i> |
| To transfer of windscreen glass to facilitate bodywork repair. | \$ | 170.00 | X |
| To remove and refit fender fittings, attachment to facilitate bodywork repair. | \$ | <i>nn</i> 350.00 | X |
| TOTAL | \$ | 5,250.00 | |
| Over All Total | \$ | 14,485.28 | |

(PART-BY-PART) Repair Days

20 days

3 days

For Official Use

| | |
|--|--|
| Prepared By : _____ (Accident Dept) | <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> |
| Verify By : _____ (Accident Workshop) | |
| Checked By : _____ (Finance Dept) | |