

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20009835/ARS3Q2

Date: 12/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100495970
Claimant Vehicle No :	SMK5097B	Insured Vehicle No :	SDN3328P
Date of Loss:	10/09/2020	Nature of Claim:	TP
		Claim No:	5322763866SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK5097B	Engine No:	27195031247684
Make & Model:	MERCEDES-BENZ C200, 1.8 (A)	Chassis No:	WDD2040412A303476
Reg. Date:	17/08/2009 (Man. Year: 2009)	Odometer:	181121 km
Colour:	Black		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,817.49	8,512.43	8,305.06	49.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,760.00	1,940.00	2,820.00	59.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,577.49	10,452.43	11,125.06	51.56
Approved Total (Overridden) (S\$)		8,300.00		
(S\$)	21,577.49	8,300.00	13,277.49	61.53
+ GST 7.00/7.00% (S\$)	1,510.42	581.00	929.42	61.53
Nett Amount (S\$)	23,087.91	8,881.00	14,206.91	61.53
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		9,750.00		

INSPECTION

Date of Assignment:	15/09/2020		
Date Inspected:	15/09/2020	Inspected At:	Cas Garage Pte Ltd (HQ) No.1, Kaki Bukit Ave 6, #02-22 Autobay Singapore 417883
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,922.30 FL	*1,850.00 FL
2	1		*BOOTLID LOGO	Necessary	98.60 FL	*98.60 FL
3	1		*BOOTLID INNER TRIM	Not Necessary	385.90 FL	*- FL
4	1		*BOOTLID C200 EMBLEM	Necessary	95.20 FL	*95.20 FL
5	1		*BOOTLID KOMPRESSOR EMBLEM	Necessary	95.20 FL	*95.20 FL
6	1		*BOOTLID CYCLE & CARRIAGE EMBLEM	Necessary	85.20 FL	*85.20 FL
7	1		*BOOTLID INNER LOCK	Damaged	235.60 FL	*235.60 FL
8	1		*BOOTLID LOCK CATCH	Not Necessary	45.20 FL	*- FL
9	1		*BOOTLID OUTER CHROEM GARNISH	Not Necessary	356.30 FL	*- FL
10	1		*BOOTLID WEATHERSTRIP	Not Necessary	197.50 FL	*- FL
11	2		*REAR BUMPER SIDE RETAINERS	Necessary	157.00 FL	*157.00 FL
12	2		*REAR BUMPER ATTACHMENT RETAINERS	Not Necessary	171.20 FL	*- FL
13	1		*REAR BUMPER CENTRE RETAINER	Cracked	158.60 FL	*158.60 FL
14	1		*REAR BUMPER REINFORCEMENT	Not Necessary	599.30 FL	*- FL
15	1		*REAR REINFORCEMENT BOTTOM GARNISH	Not Necessary	285.60 FL	*- FL
16	1		*REAR REVERSE SENSORS (6 PCS)	Damaged (2 PCS ONLY)	1,518.60 FL	*506.20 FL
17	6		*REAR REVERSE SENSORS HOLDER	Necessary	233.40 FL	*233.40 FL
18	1		*TAILAMPS	N/S Cracked	1,388.40 FL	*694.20 FL
19	2		*TAILAMPS INNER SEALER	Necessary	76.00 FL	*20.00 FL
20	1		*END PANEL	Dented	1,308.60 FL	*923.00 FL
21	1		*END PANEL TOP GARNISH	Cracked	198.50 FL	*198.50 FL
22	2		*REAR SILENCER HEAT SHIELD	Not Necessary	334.40 FL	*- FL
23	1		*REAR EXHAUST GASKET	Necessary	52.00 FL	*52.00 FL
24	1		*SPARE TYRE FLOOR PANEL	Not Necessary	987.50 FL	*- FL
25	1		*SET REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
26	1		*REAR BUMPER (AMG)	Deformed	1,850.00 FS	*1,600.00 FS
27	1		*REAR LOWER DIFFUSER (AMG)	Deformed	1,050.00 FS	*600.00 FS
28	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
29	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
30	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
31	2		*SET TAILLAMPS CLIPS	Necessary	60.00 FS	*10.00 FS
32	1		*SET BOOTLID OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
33	1		*REAR NAPEXX 158 TWIN EXHAUST	Bent	3,800.00 FS	*1,400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,916.10	9,052.70
- List Item Discount on L Items 10.00/10.00% (\$)	1,098.61	540.27
Total Parts (\$)	16,817.49	8,512.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS ,REPLACE ,BEAT ,WELD ,REALIGN AND ALIGNE ALL PARTS	New	1,800.00	800.00
2	TO RESPRAY AFFECTED AREAS	New	1,800.00	800.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	60.00
4	TO REMOVE/REPLACE REVERSE SENSOR AND DISTANCE SETTLING	New	150.00	50.00
5	LABOUR TO UNDERCOATING TO AFFECTED AREA	New	180.00	0.00
6	LABOUR TO REMOVE INTERIOR UPHOLSTERY TO FACILITATE REPAIR JOB	New	150.00	60.00
7	LABOUR TO REMOVE REAR SILENCER BOX	New	180.00	80.00
8	TO CONDUCT WIRING CHECK ON REAR TAILLAMPS	New	150.00	30.00
9	TO REMOVE/REFIT REPLACE BOOTLID MECHANISM	New	150.00	60.00
Gross Labour Cost (S\$)			4,760.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >