



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 841J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
10	BUMPER CLIPS @\$1.61	SERVICEABLE	16.10	-
1	BUMPER LIP COVER RR/LH	SERVICEABLE	72.20	-
1	BUMPER SEAL, RR LH	SERVICEABLE	88.90	-
1	BUMPER SIDE RETAINER RR/LH	SERVICEABLE	94.80	-
1	FENDER RR/LH	SERVICEABLE	766.80	-
1	SMRT LOGO	SERVICEABLE	7.80	-
1	STICKER DECAL 6555 8888	SERVICEABLE	21.60	-
1	FENDER LINER RR/LH	SERVICEABLE	141.30	-
1	BUMPER REAR	TO REPAIR SEE LABOUR	458.60	-
1	ADVERTISEMENT STICKER (SN)	NECESSARY	296.88	296.88
			2,084.98	416.88
LABOUR				
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF BUMPER REAR.		338.00	200.00
	SPRAY PAINT.		756.00	200.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			1,434.00	420.00
GRAND TOTAL			3,518.98	836.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				650.00

Report Ref No. NS/INC20009836/Qtf3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.