

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20009837/KBS3Q2

Date: 29/10/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLR2280H	Insured Vehicle No :	SH6083D
Date of Loss: 14/09/2020	Nature of Claim: TP	Claim No: MCT20090194

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR2280H	Engine No:	2ZRS061715
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU203563466
Reg. Date:	04/08/2017 (Man. Year: 2017)	Odometer:	182484 km
Colour:	Metallic Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,282.94	6,831.17	4,451.77	39.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,070.00	2,490.00	1,580.00	38.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,352.94	9,321.17	6,031.77	39.29
Approved Total (Overridden) (\$\$)		7,450.00		
(\$\$)	15,352.94	7,450.00	7,902.94	51.48
+ GST 7.00/7.00% (\$\$)	1,074.71	521.50	553.21	51.48
Nett Amount (\$\$)	16,427.65	7,971.50	8,456.15	51.48
+ Car Rental (11.0 x S\$71.95/day) (\$\$)		791.45		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		8,770.40		
Global Sum Settlement (\$\$)		8,750.00		

INSPECTION

Date of Assignment:	14/09/2020	
Date Inspected:	15/09/2020 Inspected At:	385 SIN MING DRIVE Repairer: Esteem Performance Pte Ltd (HQ)
Estimated Period of Repair:	9.0 days	

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2020)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR2280H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Cracked	2,561.60 FL	*2,561.60 FL
2	1		*FRONT SUPPORT PANEL CENTRE	Repair	338.50 FL	*- FL
3	1		*FRONT SUPPORT PANEL RH	Repair	213.50 FL	*- FL
4	1		*HEADLAMP PANEL RH	Repair	89.20 FL	*- FL
5	1		*FRONT WINDSCREEN SIDE GARNISH	Cracked	105.50 FL	*105.50 FL
6	1		*FRONT BUMPER	Serviceable	450.80 FL	*- FL
7	10		*FRONT BUMPER CLIP	Not Necessary	40.00 FL	*- FL
8	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	77.00 FL	*- FL
9	1		*RH WING MIRROR (SIGNAL LAMP) }	Broken	1,374.20 FL	*1,374.20 FL
10	1		*RH WING MIRROR (ARM) }		0.00 FL	*- FL
11	1		*RH WING MIRROR (GLASS) }		0.00 FL	*- FL
12	1		*RH WING MIRROR (COVER)	Missing	87.40 FL	*87.40 FL
13	1		*RH FRONT FENDER	Bent	868.70 FL	*868.70 FL
14	1		*RH FRONT FENDER UNDERSHIELD	Serviceable	176.50 FL	*- FL
15	10		*RH FRONT FENDER UNDERSHIELD CLIP	Not Necessary	25.00 FL	*- FL
16	1		*RHF FENDER WORDING HYBRID	Necessary	45.17 FL	*45.17 FL
17	1		*RH FRONT HUB CAB	Serviceable	195.62 FL	*- FL
18	1		*RH FRONT DOOR	Repair	1,226.70 FL	*- FL
19	1		*RH FRONT DOOR HINGE TOP	Repair	78.34 FL	*- FL
20	1		*RH FRONT DOOR HINGE BOTTOM	Repair	78.34 FL	*- FL
21	1		*RH FRONT DOOR LOCK	Repair	428.40 FL	*- FL
22	1		*RH FRONT DOOR CHECKER	Serviceable	156.79 FL	*- FL
23	1		*RH FRONT DOOR WEATHERSTRIP	Serviceable	198.49 FL	*- FL
24	1		*RHF DOOR GLASS	Cut	818.10 FL	*818.10 FL
25	1		*RHF DOOR GLASS OUTER MOULDING	Dented	122.95 FL	*122.95 FL
26	1		*RHF DOOR STAND GARNISH	Not Necessary	75.60 FL	*- FL
27	1		*RH REAR DOOR	Bent	1,181.75 FL	*1,181.75 FL
28	1		*RH REAR DOOR HINGE TOP	Repair	78.34 FL	*- FL
29	1		*RH REAR DOOR HINGE BOTTOM	Repair	78.34 FL	*- FL
30	1		*RH REAR DOOR LOCK	Repair	411.70 FL	*- FL
31	1		*RH REAR DOOR CHECKER	Serviceable	156.79 FL	*- FL
32	1		*RH REAR DOOR WEATHERSTRIP	Serviceable	178.40 FL	*- FL
33	1		*RH REAR DOOR GLASS	Cut	450.90 FL	*450.90 FL
34	1		*RHR DOOR GLASS OUTER MOULDING	Dented	111.61 FL	*111.61 FL
35	1		*RH REAR DOOR OUTER HANDLE	Repair	107.40 FL	*- FL
36	1		*RH REAR FENDER	Bent	881.60 FL	*881.60 FL
37	1		*REAR BUMPER	Repair	411.64 FL	*- FL
38	10		*REAR BUMPER CLIP	Not Necessary	40.00 FL	*- FL
39	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	112.70 FL	*- FL
40	1		*TAIL LAMP RH -UPPER	Cracked	498.75 FL	*498.75 FL
41	1		*TAIL LAMP RH -LOWER	Not Necessary	511.60 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) 15,043.92 **9,108.23**
- List Item Discount on L Items 25.00/25.00% (\$\$) 3,760.98 2,277.06

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	11,282.94
						6,831.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (FRONT BUMPER ,RHF FENDER ,BONNET ,RH WINDSCREEN PILLAR ,RHF DOOR ,RHR DOOR ,RHR FENDER ,REAR BUMPER)	New	1,400.00	1,000.00
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (FRONT BUMPER ,RHF FENDER ,BONNET ,RH WINDSCREEN PILLAR ,RHF DOOR ,RHR DOOR ,RHR FENDER ,REAR BUMPER)	New	1,800.00	1,200.00
3	TO CHECK WIRING & FOCUS HEADLAMP	New	50.00	40.00
4	TO REMOVE & REFIT DOOR TRIM ,DOOR GLASS ,WINDOW REGULATOR ,DOOR LOCK TO ASSIST WORK LOAD	New	300.00	60.00
5	TO TUFF COAT	New	150.00	90.00
6	TO REMOVE & REFIT INNER SEAT & UPHOLSTERY TO ASSIST WORK LOAD	New	250.00	100.00
7	TO DO WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			4,070.00	2,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >