

REF: CS/SMO20009857/USF3

ASSIGNMENT

Veh No: SLX186EX Tr Page: 3/18
 Type: MCa / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Hyundai Elantra cc 1591
 Colour: Grey A/C: Insured / Std / Nil / NA
 Sp Reading: 52256 T/Radio: Insured / Std / Nil / NA
 Eng No: _____
 Ch No: KMHD841CMJU 645318
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Free / Jammed / Leaked / Burnt or
 Brakes: Free / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: _____ R: 215/50R17
 (S) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SOMI /
TOYO / YOKO or
 Front R/Bal: 6 mm Rear R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: 31/8/20 D.O.I: 15/9/20
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Rear
 The UIC / Chassis frame / Body Structure affected due to collision.

FRONT: _____
 DATE: _____
 ESTIMATED COST: _____
 TO INSPECT VEHICLE NO: SLX186EX
 AT WORKSHOP N/S OF: 200M
 INSURED: ABC3411
 POLICY NO: _____
 CLAIMS NO: _____
 SUM INSURED: _____ EXCESS: _____
 (Client's Record)
 MAKE OF VEH: _____
 (Policy Condition)
 REMARK: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 458
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 3 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS 218B
 Vehicle: IN / OUT
 Date: _____ Person Contacted: LIA 4026

28/9/20 1/5 @ 2000 confirmed with E.I. (\$ 12,248.56 Red - 86%)

Sompo officer - Agnes


Date/Time, File Pass to? : Prell. Report
 1) 29/09/20 : Final Report
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: 3
 Resurvey No. of Trip: 1 Survey Fee: _____
 Transportation: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Report Format :
 Lump Sum / I.B.I. (\$ 2,000/- 45)

TOTAL



REP. _____
Date: _____

EVA / INV / 3
M/C
24.
240

ZOOM AUTOWERKS

ZOOM AUTOWERKS PTE LTD
120 Bedok Reservoir Road, Eunos Spring
#08-1329 Singapore 470130
Tel: 9450 7920
zoomautowerks@gmail.com

Car Number: SLX1865X
Model: HYUNDAI ELANTRA AD 1.6 GLS
Damaged Area: (Rear Portion)
Repairer Estimation Cost of Repair :
Supplementary may be included during the cost of repair :

*not Authorized
N/A
15/9/20
2/5# 2000
3days.*

Parts / Material :				
1	Rear Bumper	DD/OC	429.40	\$ 907.40
2	Rear Bumper Side Retainer @ 65.00	^^		\$ 130.00 X
3	Rear Bumper Bracket @ 78.00	^^		\$ 156.00 X
4	Rear Bumper Reflector @ 97.80	^^		\$ 195.60 X
5	Rear Bumper Reinforcement Bracket @ 118.40	NS		\$ 236.80 ✓
6	Rear Bumper Reinforcement	DD		\$ 386.50
7	Rear Bumper Top Bracket @ 130.00	^^		\$ 260.00 X
8	Rear Bumper Lower Skirting	de/abepuh	850.00	\$ 924.80
9	Rear Bumper Lower Bracket (SET)	^^		\$ 224.40 X
10	Rear Bumper Clips	^^		\$ 60.00 ✓
11	Rear Bootlid Panel	^^		\$ 958.40 X
12	Rear Bootlid Centre Moulding	^^		\$ 198.70 X
13	Rear Bootlid Inner Lock	^^		\$ 195.80 X
14	Rear Bootlid Catch	^^		\$ 38.70 X
15	Rear Bootlid Logo	^^		\$ 68.20 X
16	Rear Bootlid Name Plate (Elantra)	^^		\$ 58.70 X
17	Rear Bootlid Weather Strip	^^		\$ 194.20 X
18	Rear Bootlid Lamp @ 513.60	^^		\$ 1,027.20 X
19	Rear Taillamps @ 750.80	^^		\$ 1,501.60 X
20	Rear Taillamp Panel @ 185.70	^^		\$ 371.40 X
21	Rear End Panel	^^		\$ 485.20 X
22	Rear End Panel Top Garnish	^^		\$ 165.80 X
23	Rear End Panel Top Garnish Clips	^^		\$ 60.00 X
24	Rear Fenders	^^		Repair X
25	Rear Fender Inner Trim Garnish @ 385.70	^^		\$ 771.40 X
26	Rear Fender Inner Trim Garnish Clips	^^		\$ 80.00 X
27	Rear Fender Inner Shield @ 176.00	^^		\$ 352.00 X
28	Rear Left Fender Inner Shield Clips	^^		\$ 80.00 X
29	Rear Spare Tyre Top Board	^^		\$ 265.40 X
30	Rear Spare Tyre Panel	^^		\$ 963.80 X
31	Rear Exhaust Pipe	^^		\$ 982.50 X
32	Rear Exhaust Chrome Muffler	^^		\$ 465.20 X
33	Rear Exhaust Mounting @ \$48.00	^^		\$ 144.00 X

Parts : \$ 12,309.70
Less Parts 20% : \$ 2,461.94
Total Parts : \$ 9,847.76

*10,218.56
P-1754-9
20%
1404.72*

REF: 2014-000000701

Date:
 RES: EVAL/INV/MD
 SMC
 LH
 4/24/14

Special Net Items :
 Rear Taillamp Panel Sealant
 Rear End Panel Sealant
 Rear Spare Tyre Panel Sealant
 Rear Number Plate W/Base Garnish
 Reverse Sensor

AM	\$	60.00	X
17	\$	80.00	X
17	\$	80.00	X
17	\$	80.00	X
17	\$	80.00	X
Subtotal	\$	280.00	00
Total S/N Parts :	\$	580.00	

Labour :
 To Remove, Repair & Renew Rear Affected Accident Areas
 To Putty, Spray Paint on Affected Accident Areas
 To Check & Re-Connect all electrical wiring
 To Remove & Install Rear Bootlid Components Trim & Garnish
 To Remove & Install Rear Fenders Trim, Garnish
 To Conduct Water Leakage Test
 To Remove, Install & Re-position Reverse Sensor
 To Rust Proof Affected Areas

	\$	1,400.00	300
	\$	1,200.00	SD0
	\$	50.00	20
17	\$	150.00	X
	\$	150.00	60
17	\$	150.00	X
	\$	150.00	50
AM	\$	200.00	X
Total Labour :	\$	3,450.00	

TOTAL PARTS :	\$	9,847.76
TOTAL SPECIAL NET ITEM :	\$	580.00
TOTAL LABOUR :	\$	3,450.00
TOTAL REPAIR COST :	\$	13,877.76

14,248.56

p. 1404-72
 S.N. 200.00
 1-930.00
 2534-72
 20
 2027

DATE OF SURVEY / INSPECTED :
 RECOMMENDED PART BY PART / LUMP SUM :
 RECOMMENDED NUMBER OF DAYS :
 SURVEY BY / SURVEYOR FIRM :
 RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :
 FINALISED AMOUNT :

LKK Auto Consultants hence notify the Repairer of the following:

- To re-survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No major modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: